Quality Control Check Repot. Stage: After Brickwork (Villas)

Bungalow No.	160	Others		Sl. No.	32/5
Company	Nilligioni Estates	Project	Nilligion Estate	Phase	
Prepared by	T. Vinad Kumay Sign	Sign	T. Vin Pod Kurnos	Date	9 2/04/19
Project Manager	Modhu Sudhan	Sign		Date	23/04/19
Previous stage report no.	no.	048392	Report filed and signed by PM?	d by PM?	Yes No
Bungalow No		Other		Other	
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:	Society				
Stop further work.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck Stop further work. Proceed with work after submitting ATR on QC report to QC team.	port to QC team. Proper submitting ATR or	ceed only after recheck by QC report to QC team.	by QC.	
Proceed with furth	Proceed with further work only after making corrections pointed out in the QC report.	ing corrections pointe	ed out in the QC report.	ATR not required.	
T TOCCCO WITH INTELL W	i iocceu with intuier work. A i K not required	red.			
TO CONTRACT OF THE PARTY OF THE					

Inspection should be done after:

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed.
- electrical conducting work is completed (except bathrooms).

Brickwork Check.

Notes:

- Mark v for correct or minor mistake which does not require correction
- Mark × for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- . Chicken mesh should be used in each and every joint between RCC & Brickwork.
- . Joint between brickwork & beam on external side must be filled.
- . Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- . Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 2. Check room height with specified height. (Tolerance: 1")
- . Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.
- 16. Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.
- Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws.

Ren	19	18	17	16	15	14	13			10	9	∞	7	6	Ŋ	4	w	2	1	S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony-2	Terrace/ balcony-1-	Lobby-2-	-Lobby 1	Dining	Drawing	Toilet-4	Bedroom-4	Toilet-3	To	Toilet 2 P.T	Bedroom 2 C.Bed	Toilet 1 M.T	n	Room
			Ņ	١	<		A	١,	j	1	1	4	1	1	سسي	7	7	1	Ś	Wall thickness (✓ or ×)
			<	1	ζ	1	1		1	′	(١	1	t	١	ζ	7	5	1	Beds in walls (✓ or 🗙)
			关×	1	××	1	9	١	1	٢	(1	Ī	1	1	7	ς.	1	1	Chicken mesh (✓ or 🗙)
			ς,	-	7	1	1	١	١	<	ς	١	1	1	1	1	1	1	1	External brickwork & beam joint (or x)
			ς.	1	(١	į	١	1	7	ζ	1	1	1	1	1	(7	(Room Dimensions (• or ×)
			5	1	<	١)	1	1	7	٢	1	1	1	Ţ	?	1	7	(Room Dimensions Difference in inches
			<	١	ς)	1	}	<	ς.	1	1]	Ţ	1		(7	Diagonal (✓ or 🗙)
	-11		ζ	١	<	1	1	ı	1	5	١	1	1	1	١	ζ	7	7	1	Diagonal Difference in inches
			1	1	1	,	4	1	١	1	١	1	1	1	1	١	1	ſ	}	Balcony sill level (v or x)
		17	ς	1	7	1		1	1	ζ	7	1)	1	ţ	ζ	(1	1	Room Height (v or x)
		d	Ava	1	AVA	1	1	Ţ	1	1,1	Dur	1	1		١	=	ď	7	AVA	Plumb of walls (Good/Avg./Bad)
			ζ	1	(7	1	١	1	7	ζ	!	1	1	•	<	7	7	>	Alignment of beams and walls - Nos.

Quality Control Check Repot.

Stage: After Brickwork (Villas)

Quality Control Check Repot. Stage: After Brickwork (Villas)

	Specify rooms that need correction:	Quality of edges and corners in all rooms?
		☐ Good ☑ Avg. ☐ Bad

Challas Quality Check

Notes: Width of chajja should be 6"more than the width or the door or window.

Remarks	90	Total Nos. of Chajjas
		Total Nos. of Chajjas Slopes incorrect – nos. Thickness incorrect – nos Width incorrect - nos.
		Thickness incorrect -nos
	100 miles	Width incorrect - nos.
	•	Height in correct - nos

Door Frames & Windows check

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark **XX** for major mistake that requires correction by replacement or re-fixing. Mark **XXX** for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 32"or 33" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

0		Re	19	18	17	16	15	14	13	12		10	9	∞	7	6	S	4	ω	12	à	S No
At staircase	frame at Head	Remarks: O Dasteac	Other	Other	Kitchen	Portico	Head room	Terrace/baleony-2	Terrace/-balcony-1	20.00	Lobby-1		Drawing	Teilet-4	Bedroom 4	Toilet-3-	Bedroom-3-	Toilet 2 C.T	Bedroom 2 C. Bed	Toilet 1 M.T	Bedroom I M. Bed	Room
drea		0			4.70		×	1	}	I	}	١	ζ,	١	1	١	1	<	1	5		Door size, face and position (vor X)
Chea window z-angle	XOOM.	6			i	-	<	ĺ	1	ſ	1	1	ζ	}	1	١	i	<	\	<		Brick at bottom of door frame10 (vor X)
2 7 Q	,	0'-6")			١	1	1	1	-	1	1	}	1	1	١	١	Ţ	?	7	ζ.	<	Door lentil level ⁶ (v or X)
		You			j		ζ.	1	١	1	}	}	<	1	١	1	1	1	7	1	(Door diagonal check ⁶ (* or *X)
name not		£xc			1		(XXX)	1	١	1	١	1	5	١	١	1	١	7	7	1		Door Plumb - two sides (vor x)
not		Some			•	١	\	1	1	١	1	1	×	١	t	1	١	5	7	7	-1	Door frame black Japan/ wood primer/Peelambar check (vor X)
provided	E	they			<			1	١	l	Ţ	<	<	1	ſ	1	١	7	7	7	<	Windows lentil & sill level(✓ or 🗙)
led.	_	9			7	1	<	1	1	1	1	<	ς.	1	1	1		7	7	ζ	<	Windows size (✓ or 🗙)
		populad		80.0		1	(1	1	١	1	7	5	1	١	١	1	7	7	7		Windows - template depth & diagnal ⁵ (✓ or X)
					<	1	ς,	1	1	١	1	<	ς	1	٩	ſ	١	<	7	7		Windows - template powder coated ⁵ (✓ or ズ)
		3'-0")		25	Yes		1	1	1	1	1		1	1	1	1	1	Į		١		Loft & Kitchen platform required ? (Yes or No)
		raab			<	1	١	1	1	1	١		•	1	1	*	١	ſ		•		Loft & Kitchen platform provided ⁸ (v or x or NA)
					\	1	1)	1	1	1	1	3	1	1	١	1	١	1	Ì		Loft & Kitchen platform slope (✓ or X)

Quality Control Check Repot.

Stage: After Brickwork (Villas)

Quality Control Check Repot. Stage: After Brickwork (Villas)

		Remarks:
5	xide painting (v or x)	Parapet and compound wall railing design quality, fitting & redoxide painting (v or x)
\		Parapet wall thickness, height and design (or x)
7		Chicken mesh provided on external joints of villa (v or x)
Actual distance provided: q -11"	10'-0"	Specified distance between gate columns:
	5-011	Specified height of gate columns:
Yes No		Is level marked on villa & compound wall with 2 screws, 2 ft above FFL?
Yes No		Is leveling in the setbacks of the villa 6" below FFL?
鱼		Quality and level of PCC for portico?
Good Avg. Bad	10000 10000	Quality and level of PCC on ground floor?
Actual level above FFL: 41-611	4-6"	Specified compound wall height above FFL:
Actual level below FFL:	Ŷ	CRS + bed - specified level below FFL:
		Compound wall check
		Remarks:
	Yes No	Drum (200 lts) provided for curing in each flat?
	☐ Good ☑ Avg. ☐ Bad	Storage of building material like bricks sand and cement.
	☐ High ☑ Medium ☐ Low	Wastage?
	☐Yes ☐No	Is the Bungalow cleaned for plastering?
ly .	Yes No Cant' say	Was the Bungalow cleaned before starting brick work?
	☐ Good ☑ Avg. ☐ Bad	Condition of proportion box?
	√Yes □No	Was 3.75 CFT proportion box provided?
		Mico (hecks