	Allign
	Quality Control Check Report.
Section 1	Stage: After
WYDAMATYCE	Rrickwork
Capai michica)	Stage: After Rrickwork (Anortments)

))			
riat ivo.	101-101	Others	ì	S1. No.	18666
Company	VISTA HOMES	Project	VISTA HOMES	Phase	1
Prepared by		Sign		Date	1. 1. 1.
Project Manager		Sign	1	Data	11/4/11/8
y voleon manuser	Machu	ngic	7 RULEY	Date	8/14/m
Previous stage report no.	no.	29813	Report filed and signed by PM?	d by PM?	NYes No
Apartment No		Other		Other	
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation:					
Stop further work. Stop further work. Proceed with furth	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Proce er submitting ATR on ing corrections pointed	ed only after recheck location out in the QC report.	by QC. ATR not required.	
Inspection should be done after:	after:				

rispection should be done after

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork ('heck,

Notes:

- . Mark ✓ for correct or minor mistake which does not require correction
- 2. Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XXX for major mistake that cannot be corrected.
- 5. Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- 7. Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- 9. Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 1. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- 13. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than 1"in a room.
- 15. Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

		7 124 17	Remarks () Change	15 Other	14 Other	t	12 Hility / balcony 3			+-	<u> </u>		_ _	-Tailet 3	رد اد	4 Toilet 2 (Cr)	3 Bedroom 2 (kg)	-	1_	Room	
		OVEY	261			<	- - -	<	<	1	<	<	1	<	,	<	<	?	<	Wall thickness	Qua
£		707	P .			<	1	<	<	1	<	く		<	Y		<	<	<	Beds in walls	lity Cont
		1101	7		<		}	<	<	1	<	<		4			١.	<	<	Chicken mesh	Quality Control Check Repot.
		worlded	2		<		1			1	<	5	1	۷	<	<		<	<	External brickwork & beam joint (• or ×)	Repot.
		ica.	-		<				5	,		<	ſ 	<	K	<			<	Room Dimensions	Stag
						! 1		1]		\	١		(1	1			1	Room Dimensions Difference in inches	Stage: After Bri
					<		<		1	<	,	۲	1	<u>ر</u>	<	<	K	<		Diagonal (✓ or X)	Brickwor
					1			{	1	\	1	1		1	1	1	1	ſ		Diagonal Difference in inches	ckwork (Apartments)
	<u> </u>				}	1	1)	9	1)	1		\	}	١	}	5		Balcony sill level	ments)
					<	1	<	<	4	<	<		*	<	<	〈	<	<		Room Height	
					449	1	-7	129	>1	-	449	> 1		1,	=	-	4	Ava	. I	Plumb of walls Good/Avg./Bad)	
					<)	(5)	<	5		<		<	<	<	<	a	Alignment of beams and walls - Nos.	

Quality Control Check Report.	Stage: After Brickwork (Anortments)
Quality of edges and corners in all rooms?	Good NAvg. Bad
Specify rooms that need correction:	
Misc. Checks.	
Was 3.75 CFT proportion box provided?	\ \forall Yes \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
What he had a second to be a second	Good Avg. Bad
Is the Anartment cleaned for the Anartment cleaned for the Anartment cleaned for the cleaned f	☐ Yes ☐ No ☐ Cant' say
Wastage?	¬Yes □No
Storage of building material like bricks sand and coment	High Medium Low
Orum (200 lts) provided for curing in each flat?	Ves No
Remarks:	
Joor Frames & Windows check	

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark $\mathbf{X} \mathbf{X}$ for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 35" or 36" from SFL.
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

	Rem	15	14	53	 ::)		5	· · ·	~		0	V	4	ن د	u l	2	- S No
	Remarks:	Other	Other	Kitchen	titility / balcony 3	Utility / baleony 2	Hality / balcony 1	-Lobby-1-	Dining	Drawing	Lollet-3	Bedroom 3 (45)		7 n	- X-	>	Room Bedroom 1 (Mg)
					1		1	1	1	<		<	<	<	<		Door size, face and position (or X)
]	1	1	1	1	<	١	<	1	<	Brick at bottom of door frame (or X)
				1	1			1	/	<	١	\ \	<	<	<	<	Door lentil level
				(<]	1	1	<	1	<	<	<	<	<	Door diagonal check
				1	1		1	1	1	1	1	<	<	<	<	, <	Door Plumb - two sides
				(<		1	1	1	1	1	<	<	<	<	<	Door frame black Japan/ wood primer/Peelambar check (or X)
			<					1	1	1	1	۷,		<	<	<	Windows lentil & sill level (✓ or ×)
			\ 	\ \ \		1		1	١	}	\		<		<	<	Windows size (✓ or ×)
			<	1			Ì		()		\		,	<	<	<	Windows - template depth & diagonal (✓ or 🗙)
			<				9,00		()		4	<	\	<	<	<	Windows - template powder coated (✓ or X)
			NO	1		1	1)	1		\	1		}	1	Loft & Kitchen platform required ? (Yes or No)
				-)	1	j]	}		1		1	1	1	Loft & Kitchen platform provided (✓ or × or NA)
			1]	1		1	1	1	1			1	1	Loft & Kitchen platform slope (v or X)