	Quality Contro	Quality Control Check Report.	Stage: After Brickwork (Apartments)	(Apartments)	
Flat No.	E-008	Others	9	SI. No.	34247
Company	Vista Homes Project	Project	VISTA HOME	Phase	ph septim
Prepared by	T. VIVOY Klumay Sign	Sign	Tall Rumal Date	Date	23/08/19
Project Manager	T. Madhis	Sign	7 46 16-1	Date	23/08/19
Previous stage report no.	no.	33428	Report filed and signed by PM?	d by PM?	Yes No
Apartment No		Other		Other	
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work.	Submit ATR on QC re . Proceed with work aft	port to QC team. Proter submitting ATR (	scommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.	by QC.	
Proceed with furth	ner work only after mak	ing corrections poin	Proceed with further work only after making corrections pointed out in the QC report. ATR not required	ATR not required.	

Proceed with further work. ATR not required. Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

## Brickwork Check.

## Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- 2. Mark X for minor mistake that requires minor correction.
- 3. Mark XX for major mistake that requires correction by replacement or re-fixing
- 4. Mark XXX for major mistake that cannot be corrected.
- 5. Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- . Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- 9. Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 1. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 12. Check room height with specified height. (Tolerance: 1")
- 13. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than 1"in a room.
- 15. Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Rer	15	14	13	12	1	10	9	∞	7	6	5	4	3	2	-	S No
Remarks	Other	Other	Kitchen	Utility/balcony 3	Utility / balcony 2-	Utility / balcony 1	Lobby-1	Dining	Drawing	Toilet-3	Bedroom 3 C Bear	Toilet 2	Bedroom 2 C. Best	Toilet 1 19.7	Bedroom 1 内・Be	Room
			<.			\.	A. Visado	< ,	ς,	-	\ \ \ \	Υ.		-	2_	Wall thickness ( • or ×)
			4	i		۲,	M. Comm	<,	ς,	P.	<.	<	<	<	<	Beds in walls (✓ or X)
			4	f	8.	<.		٢,	<		Κ.	<,	ζ,	ς.	ς,	Chicken mesh (✓ or X)
			7	-	i e	ζ,	į	<,	<	,	ς,	ζ.	<	<	<	External brickwork & beam joint ( • or ×)
			<	200	1	5	Press	<.	<	1	ζ,	<,	<	5	<	Room Dimensions ( • or ×)
			<			ς,	,	5	ς,	Ą	4.	<	<	<	<,	Room Dimensions Difference in inches
			Se.	9		<,		ζ,	<,		<.	<2	<	<	<	Diagonal (✓ or X)
			<	No. of Contract of	5	<		<,	<		ς.	<	۲.	<	<	Diagonal Difference in inches
			Edo.	d Division	1	9	7	t i	}		Diag.	Come	P.	# (C) (C)	فتاروا	Balcony sill level (✓ or 🗙)
			<			<,	-	<_	<	7) same	<	<	<	4	<	Room Height (v or x)
			AVS	7.27		A.U.a	1	Good	Aug	1	5	5	-	7	Good	Plumb of walls (Good/Avg./Bad)
			<	-	ī	<	ì	۲.	7	3	ζ.	٤′	1	. <	1	Alignment of beams and walls - Nos.

Quality Control Check Report.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	Good Ave Bad
Specify rooms that need correction:	g [ Care
Misc. Checks.	
Was 3.75 CFT proportion box provided?	Yes No
Condition of proportion box?	Good Avg. Bad
Was the Apartment cleaned before starting brick work?	Yes No Cant' say
is the Apartment cleaned for plastering?	Yes No
Vasiage:	☐ High ☐ Medium ☑ Low
Orum (200 lts) provided for our in the bricks sand and cement.	☐ Good ☑ Avg. ☐ Bad
Remarks:	Yes No .
Joor Frames & Windows check	

- Mark ✓ for correct or minor mistake which does not require correction
- Mark  $\times$  for minor mistake that requires minor correction.
- Mark **XX** for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 1/2" after plastering.
- Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 35" or 36" from SFL.
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

 $\infty$