Block No Company Project Prepared by Project Manager Project Manager Previous stage report no. Checked By MD on Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work only after making corrections pointed out in the QC report. ATR not required. Stop Froceed with further work. ATR not required.	2	Quality Control Check Repot.		Stage: Before Casting Plinth Beam (Villas)	nth Beam (Villas)	
Project Sign Sign Ort no. MD Sign MD Sign Report filed and signed by PM? Phase Date Project MVR COLLING Phase Date Project MVR COLLING Phase Date Project ATR on QC report filed and signed by PM? Phase Phase Cort no. Report filed and signed by PM? For filling Where the project of the	Block No	64	1	P.B	SI. No.	34227
ort no. Sign Sign Date Ort no. MD Sign Report filed and signed by PM? Report filed and signed by PM? Proceed with work after submitting ATR on QC report to QC team. Ork. Proceed with work after submitting ATR on QC report to QC team. Ork. ATR not required.	Company	ACOUNT	Project	DIE COLLEGE	Phase	3
ort no. Sign Report filed and signed by PM? In	Prepared by	J. S. S. A. Lines	Sign		Date	97 0 10
ort no. Report filed and signed by PM? MD Sign MD Sign For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Project Manager	NOX FINDS	Sign	Javes		0 0 0 0
MD Sign For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Previous stage report no.		1	Report filed and signed		Yes No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	MD S	gn		ling	☐ Yes ☐ No
	Recommendation: Stop further work. Subm Stop further work. Proceed with further wo Proceed with further wo	nit ATR on QC report to eed with work after subr rk only after making cor rk. ATR not required.	QC team. Pro nitting ATR o rections pointe	ceed only after recheck b n QC report to QC team. ed out in the QC report. A	y QC. TR not required.	

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam. Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam Dimensions Check Plan as follows:

- Show outer dimensions. (Tolerance 2")
 Show length and width of plinth beams (Tolerance 1")
 Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.
- Plinth Beam Dimensions Check Plan enclosed? \\\\Yes

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

	as pen mo sign trabactions.	Remarks: O Mud should be powerly leveled inside and on testes ab-villa	Pedestal/column0 – self check report attached?	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Level marking at 2° above FFL is made?	Drackets for elevation features provided?	Augument of beams on outer side?	Aliment of practing Provided?	One it of Decision of the Provided?	Chaire of Contenting, lod bending and concreting?	Quality of centering, rod bending and concreting.
	stograted in pile	e et villa.	Yes No	Correct Needs correction	Yes No	☐ Yes ☐ No ☐ÑA	☐Good Avg. Bad	☐Good ☐ Avg. ☐ Bad	Yes No	Good Avg. Bad	

Plinth Beam Steel check.

Notes:

- Mark of for correct or minor mistake which does not require correction
 Mark for minor mistake that requires minor correction.
 Mark or major mistake that requires correction by replacement or re-fixing.
 Mark or major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

	Remarks:		7	6.		5	4.	į	اد	2.		1-1	O NO
		Depth and width of beams	J	Covering blocks for beams	Sieel Check - Beams Bearing	Stool Class of the stool Class o	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Stool Charles and a second	Steel Check - Beam size of hars	See Cuser - Death 110 Of 1008	Steel Check - Room no of wall	Item
			5			5	1		(3		(or X)	Quantitative Check
	[Com R ANY &. [Dad	Good Java Dad	Good Avg. Bad	L Noon E AVg. L Bad	Good	☐ Good ☐ Avg. ☐ Bad	L 2000 L 11V &. Dau	Chook Ava Bad	Good Avg. Bad	Dau Cave. Dau	Good Ave Day	(Good / Avo / Bad)	Qualitative Check