# Quality Control Check Repot. Stage: After Brickwork (Villas)

Bungalow No.	109	Others		SI. No.	30867
Company	Nilawi Estab	Project	rilgici estate	Phase	77
Prepared by		Sign	1-1-20-KB	Date	810c/ta/61
Project Manager	Sign Sharp Sign	Sign	M. What	Date	8102/2018
Previous stage report no.	no.	29853	Report filed and signed by PM?	d by PM?	Yes No
Bungalow No		Other		Other	
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation:	ecommendation: Stop further work. Submit ATR on OC report to OC team. Proceed only after recheck	port to OC team. Proc	eed only after recheck b	by QC.	
Stop further work.	Stop further work. Proceed with work after submitting ATR on QC report to QC team	ter submitting ATR on	QC report to QC team.		***
Proceed with furth	Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	ing corrections pointed	d out in the QC report.	ATR not required.	
Proceed with furth	Proceed with further work. ATR not required.	ired.			

Inspection should be done after:

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed.
- electrical conducting work is completed (except bathrooms).

#### Brickwork Check,

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.
- Sctbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL
- 17. Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws.

Ken	1	10	18	17	16	15	14	13	12	=		9	∞	7	6	S	4	· ω	2		S No
Remarks	Otter	Other	Utility	Kitchen	Portico	Head room	Lerrace / balcony 2-	Ferrace/ balcony 1	Lobby 2	Lobby 1	Dining	Drawing	Toilet 4	Bedroom 4 св	Toilet 3 GT	n 3		n 2	Toilet 1 m.T	n  -	
				(	1	(	1			۲.	•	1	(	7	1	{	<	Ć.	1	1	Wall thickness
				'	1	1	-			<	ì	7	(	<	7	<	( 	ς		ζ	Beds in walls (v or x)
				۲.	7	<	!		,	Ĭ.,		<	<	۲	ς.	,	7	<	ζ	1	Chicken mesh
						(	-			\	1	l		7	7	7	7	7	7	7	External brickwork & beam joint ( or x)
	•		_		9	7	ļ	5	1	7	7	<	7	7	(		7	ς	1		Room Dimensions ( • or ×)
	-			1	(	1	1	1	Line	1	1	1	1	)	1	1	1	1	1	1	Room Dimensions Difference in inches
			- -	,	i.		1	1	1 5			`		, ,			1	,	\	,	Diagonal ( • or x)
					)	,	ſ	1	1	1	1	1	(	1			1	1			Diagonal Difference in inches
						!	,				F	1	1		1		1	1			Balcony sill level
			,	4	k	< !	,		1 5		,	.  ,	, (	, ,	, ,	,		, (	(		Room Height
		•	2	1	<b> </b>	,		9	1 700	2	,		1-2			25	\	, ,	LAN	>	Plumb of walls (Good/Avg./Bad)
			<	5	-	. 1		(	(	,	, (	,	(	,	, ,	, ,	,	, ,	' /	١	Alignment of beams and walls - Nos.

	Specify rooms that need correction:	Quality of edges and corners in all rooms?	Quality Control Check Report.
		Good Avg. Bad	Stage: After Brickwork (Villas)

### Chajjas Quality Check

Notes: Width of chajja should be 6"more than the width or the door or window.

	Remarks		Total Nos. of Chajjas
	3	<	Slopes incorrect – nos.
		(	Slopes incorrect – nos. Thickness incorrect – nos Width i
		7	Width incorrect - nos.
		7	Height in correct - nos

## Door Frames & Windows check

Notes:

- Mark  $\bullet$  for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.

- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Window template depth should be between 2 to 2 ½"after plastering.

  Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")

  Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 32"or 33" from SFL. (Tolerance 1")
- Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

# Quality Control Check Repot. Stage: After Brickwork (Villas)

∏Good □ Avg. □ Bad	
Yes No Cant' say	
□No	The state of the s
]High Medium Low	
Good Avg. Bad	
Yes ZNo	er veget - seguina se
, to 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	
J	Actual level below FFL:
1	Actual level above FFL:
	☐ Good ☐ Avg. ☐ Bad
	] Good√ Avg. [] Bad
	Yes No
	☐Yes ☐No
	Actual height provided: 5'.0"
	Actual distance provided: 8 ! 9 !
	<
	<
Parapet and compound wall railing design quality, fitting & redoxide painting (v or x)	
	Avg. Bad  Avg. Bad  No  Medium Low  Avg. Bad  No  Or x)