Bungalow No.	=	Others		SI. No.	30732
Company	SOV(LLP)	Project	SOV	Phase	Ϋ́
Prepared by	S.Kuldeep	Sign	Dustro	Date	8105/10 120
Project Manager	Pulshottan	Sign		Date	05/07/2018
Previous stage report no.	no.	29637	Report filed and signed by PM?	ed by PM?	√Yes □No
Bungalow No		Other		Other	
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work.	Submit ATR on QC r	scommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck	eed only after recheck	k by QC.	
Stop further work.	Proceed with work af	Stop further work. Proceed with work after submitting ATR on QC report to QC team Proceed with further work only after making corrections notified out in the QC report.	QC report to QC team). ATR not required	
Proceed with further work. ATR not required	er work. ATR not requ	limed ,			
N TIOCCCA MINI INITIA	er work. ATM not redu	шeu.			

Inspection should be done after:

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed.
- electrical conducting work is completed (except bathrooms).

rickwork Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- . Mark **XXX** for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC
- . Chicken mesh should be used in each and every joint between RCC & Brickwork.
- . Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- 0. Diagonals of each room shall be equal. (Tolerance: 2")
- Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- 3. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 4. Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar -- at cost of painter.
- 16. Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.
- Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws.

Ren	19	18	17	16	15	14	13	0.000	11	10	9	8	7	6	2	4	w	2	L	S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony-2		Lobby 2 Puja Room	Lobby 1 Family Lounge	Dining	Drawing	Toilet-4-	4		n 3		n 2		Bedroom 1 100.8)	Room
	and the con-		1	1	<	!	~	<	1	1.			ſ	(7	۲	<	1	<	Wall thickness (✓ or ×)
			(1	<	1	<	ζ.	ζ	ţ	<	Ì	!	1	(<	4	<u> </u>	7	Beds in walls (v or x)
			(ı	<	ı	〈	(<	1	/	[1	(,	<	ς .	((Chicken mesh
			1	ı	<	İ	<	(<	-]	(1	((<	1	1	<	External brickwork & beam joint (or x)
3 7 3			(ţ	ζ	1	1	ζ	(}	1	1	1	(<	(ζ	(ς	Room Dimensions (• or ×)
			8	Ţ	l	1	ı		1	Ţ	1	1	I	Ţ	1	١	1	(1	Room Dimensions Difference in inches
		,		i	<	1	1	1	<	1	1	{	1	(((1	/	1	Diagonal (v or x)
			4	1	1	1	•	1	-	[1	•	Ţ	-	Ţ	ľ	Ţ	-	1	Diagonal Difference in inches
			<	1	Ţ	1	<u> </u>	1	1	1		1	1	Ţ	1	1	1	1	1	Balcony sill level (• or ×)
			ب	1	ζ	1	1	1	<	1	1	-	1	()	((\	Room Height (v or X)
			Away	<	ζ,	1	1	(/	1	<	!	1	(-	4wq	<u>/-</u>	Aug	(1	Plumb of walls (Good/Avg./Bad)
			Ç	1	<	1	\	1	(1	1	1	1	1	1	(ζ.	\	\	Alignment of beams and walls - Nos.

Quality Control Check Repot. Stage: After Brickwork (Villas)

 	7	1	
		Specify rooms that need correction:	Quality of edges and corners in all rooms?
			Good Avg. Bad

Chajjas Quality Check
Notes: Width of chajja should be 6"more than the width or the door or window.

Remarks	<u>-</u>	Total Nos. of Chajjas
and the second s	(Slopes incorrect – nos.
	(Thickness incorrect –nos Width incorrect - nos.
	(Width incorrect - nos.
	•	Height in correct - nos

Door Frames & Windows check

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 1/2" after plastering.
- Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 32"or 33" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

Ren	19	18	17	16	15	14	13	12	=	0	9	8	7	6	S	4	w	2	1	S No
Remarks:	Other	Other	Kitchen	Portico	Head room	Ferrace / balcony 2	Ferrace/ balcony 1	Lobby 2 Pooja Room	1.0bby 1 tomily Lound	Dining	Drawing	Foilet 4 ·	Bedroom-4		n 3	ļ	n 2		Bedroom 1 (ක.ප)	Room
			<		<	1	((,		(1	7	<		5	ς ,	((Door size, face and position (✓ or ×)
			(1	<	1	<	ζ	•	÷ ,	1	****	J	(((1	ζ		Brick at bottom of door frame10 (✓ or 🗙)
			<	1	<	t	<	<	1		1	٢.	ļ	ζ.	(7	1	ζ.	1	Door lentil level ⁶ (• or X)
			(ı	\checkmark	1	<	<	1	į	(Ţ	J	((1	7	((Door diagonal check ⁶ (✓ or 🗙)
			1		<	١	(~	1	1	((I	(′	′	7	<	ζ	Door Plumb - two sides (or X)
			~	-	<		<	1	ţ	1	((1	Ç	ς	ĺ	(1		Door frame black Japan/ wood primer/Peelambar check (vor X)
			<	1	<	1	1	1	ĺ	ŀ	1	(1	7	7	7	(ζ.	Windows lentil & sill level(✓ or 🗙)
-			<	1	<u> </u>	1	1	((1	/	1	1	′	ζ	1	(7	(Windows size (✓ or 🗙)
			(!	ζ		1	(1	1	((1	(<	ζ	7	7		Windows - template deptl & diagnal ⁵ (✓ or X)
			1	1	(1	1	1	1	1	7	Ţ	I	<	<	<	/	′	ζ	Windows - template powder coated ⁵ (✓ or X)
			à	1	1	1	l	ſ	١	1	1	١	1	1	I	1	1			Loft & Kitchen platform required? (Yes or No)
ŀ			<	t	!	1	1	1	1		Ī	1	1	1	ľ	•	ſ	ľ	-	Loft & Kitchen platform provided ⁸ (v or × or NA)
			<	1	ļ	Ī	!	ľ	1		1	1	1	1	ı	,	1	1		Loft & Kitchen platform slope (✓ or 🗙)

Quality Control Check Repot. Stage: After Brickwork (Villas)

Quality Control Check Repot. Stage: After Brickwork (Villas)

1	
☐ Good ☐ Avg. ☐ Bad	
□Yes □No ☑ Cant' sa	У
✓Yes □No	and the second second
☐ High ☐ Medium ☑ Low	
☐ Good ☑ Avg. ☐ Bad	
☐Yes ☐No	

	Detail level octor in the
4.6	Actual level above FFE. 4:6'
	☐ Good [Avg. ☐ Bad
	☑ Good ☐ Avg. ☐ Bad
The state of the s	∏Yes ∏N₀
Is level marked on villa & compound wall with 2 screws, 2 ft above FFL?	☐Yes ☐No
5	Actual height provided: 51
9.31	Actual distance provided: q '. z'
	τ,
	•
Parapet and compound wall railing design quality, fitting & redoxide painting (v or x)	<
	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Good ☐ Avg. ☐ Bad ☐ Yes ☐ No # '- 6" # '- 6" # '- 6" # '- 3

,