Recommendation: Checked By MD on Previous stage report no. Project Manager Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. T. Vinos Kumas AGIH Quality Control Check Repot. MD Sign Sign Other 32408 Sign Others Project Report filed and signed by PM? という Stage: After Brickwork (Villas) rama Phase Sl. No. For filling Other Date Date ∠ Yes Yes

00

L Zo

Z

Bungalow No

Prepared by Company Bungalow No.

	7	
	Ishection should i	
	Œ	
	C	
	Ξ	
,	2	
,	Ξ	
	V	
	Ξ	
	9	
	Ξ	
	0	
	_	
	×	
	be done after:	
	H	
1	7	
!	7	
	5	
	ਜ	
	œ	
	.:	

Proceed with further work. ATR not required.

Proceed with further work only after making corrections pointed out in the QC report. ATR not required.

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed.
- electrical conducting work is completed (except bathrooms)

Brickwork Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4" and 6" blocks must be checked
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room. Door frames must have black Japan coating and wood primer / pellambar – at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL
- Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws.

1

1

1

19 Other

18

Kitchen Utility

5 3

1

>

Groca

15

Grood

16

Head room Portico

Terrace/-balcony-1-

13

Lobby 2

10

Feilet 4-Drawing

1

1 | 1

112

F

1

1

1

1

1

1

Ī

Вефюнт-4-

Bedroom 3-Toilet 3

1 0

Dining Lobby-1 2

Bedroom 1 M. Bed

Bedroom 2 Gr. Bed

S No

Room

Wall thickness

Beds in walls

Chicken mesh

(**v** or **x**)

(✓ or X)

Diagonal

(**∨** or **×**)

Diagonal

(**v** or **X**)

(**v** or **x**)

Room Height

Plumb of walls

(Good/Avg./Bad)

and walls - Nos.

Alignment of beams

Difference in inches

Balcony sill level

OTTO DITO	
115.17	`
Kepol.	
Stage: After Brickwork	2
Aiter Bri	
ckwork (
(Villas)	

Quality Control Check Repot. Stage: After Brickwork (Villas)

				Remarks
	~	JV	<	9
Height in correct - nos	Width incorrect - nos.	Slopes incorrect – nos. Thickness incorrect – nos. Width incorrect – nos.	Slopes incorrect – nos.	Total Nos. of Chajjas
		door or window.	Chajjas Quality Check Notes: Width of chajja should be 6"more than the width or the door or window.	Chajjas Quality Check Notes: Width of chajja should
		e e e e e e e e e e e e e e e e e e e		
			correction:	Specify rooms that need correction:
	Avg. 🗌 Bad	☐ Good ☑ Avg. ☐ Bad	ers in all rooms?	Quality of edges and corners in all rooms?

Door Frames & Windows check Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 32" or 33" from SFL. (Tolerance I")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

Ren	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	သ	2	1	S No
Remarks:	Other	Other	Kitchen	Portico	Head room	Ferrace/balcony2	Terrace/balcony L.	±obby 2	Lobby-1	Dining	Drawing	Foilet4	Bedroom-4	Toilet3	Bedroom-3	3	Bedroom 2 Gr. Bed	Toilet I M. T	Bedroom 1 M. Bed	Room
			1	٩	5	ì	}	ed-		١	5	١	١	معجمون	1	<	<	<		Door size, face and position (vor X)
			8	ì	<	ſ	j	j	ı	1	<	Ŋ		١	ſ	<	<	<	<	Brick at bottom of door frame10 (vor X)
			1	ţ	<	1	1	1	-	1	<	1	b***	F	i	<	<	<	<	Door lentil level ^c
			i	¥.	ζ,	1	-	1	١	1	<	1	Ţ	-	4	<	(<	<	Deor diagonal check ⁵ (* or *X)
			1	Ī	<	1	ì	١	i	1	<	Î		1	1	<	<	ζ,		Door Plumb - two sides
			9	١	<	1	1	-	١	•	\	٩	age-tim	-		<	V	<	`	Door frame black Japan/ wood primer/Peelambar check (vor X)
1			V	Í	1	1	*	p. 1	1	<	<	¥.		1	ĺ	<	<	7	Ę	Windows lentil & sill level(✓ or ×)
			V	1	(1	1	1	1	′	<	-	î,	Page 1	į	~	′	<	<	Windows size (✓ or 🗙)
			<u> </u>	T	١	-	î	١	J	/	~	4:0	-	7.	-	7	7	1	<	Windows - template depth & diagnal⁵ (∨ or X)
			<	5	5 ,	-				ζ,	<			١		<	V	~		Windows - template powder coated ⁵ (✓ or ×)
		¢	Xes.	1	1	-	1	1	1	١	ĵ	1	١	Į	-	4	5	9		Loft & Kitchen platform required? (Yes or No)
-			K SS	٩	9	ı	1	ī	1		1	i	ì	D-mark	-	l	ı	1		Loft & Kitchen platform provided ⁸ (• or × or NA)
			7		Ĭ	1	1		E. E.		ĵ	Į		i i	1	1	Ţ	ſ		Loft & Kitchen platform slope (vor X)

Quality Control Check Repot. Stage: After Brickwork (Villas)

Misc. Checks.	1	
Condition of proportion box?	Good V Ave Rad	
Was the Bungalow cleaned before starting brick work?	☐Yes ☐No ☑ Cant' say	ау
Is the Bungalow cleaned for plastering?	✓ Yes □No	
Wastage?	☐ High ☑ Medium ☐ Low	
Storage of building material like bricks sand and cement.	☐ Good ☑ Avg. ☐ Bad	
Drum (200 lts) provided for curing in each flat?	☐ Yes ☐ No —	
Remarks:		
Compound wall check		
CRS + bed - specified level below FFL:	9	Actual level below FFL:
Specified compound wall height above FFL:	4-6"	Actual level above FFL:
Quality and level of PCC on ground floor?		☑Good ☐Avg. ☐Bad
Quality and level of PCC for portico?		☐ Good ☑ Avg. ☐ Bad
Is leveling in the setbacks of the villa 6" below FFL?		✓ Yes □ No
Is level marked on villa & compound wall with 2 screws, 2 ft above FFL?	ove FFL?	Yes No
Specified height of gate columns:	4-6"	Actual height provided: 4'-6"
Specified distance between gate columns:	10-0"	Actual distance provided: 10'-0"
Chicken mesh provided on external joints of villa (✓ or 🗙)		
Parapet wall thickness, height and design (v or x)		<
Parapet and compound wall railing design quality, fitting & redoxide painting (v or x)	xide painting (vor x)	
Remarks:		