Checked By MD on Recommendation: Company Bungalow No. Bungalow No Previous stage report no. Project Manager Prepared by Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Proceed with lighter work only after making corrections pointed out in the QC report. ATR not required Stop litther work. Proceed with work after submitting ATR on QC report to QC team Proceed with further work. ATR not required. P. Sa. Zilgis. shiriyas States. Quality Control Check Repot. Car Sign Sign Project MD Sign Others Other 32341 Report filed and signed by PM? Stage: After Brickwork (Villas) Milas estate Date Phase Sl. No. Other Date For filling 23/3/19 Wes | 23/3/19 Yes Z No

Inspection should be done after-

- Brickwork, CR\$ for compound wall, compound wall and gate pillars are completed
- chicken mesh flagal
- uther cleaning the hungaling
- Cyturnal a affolding tied
- external Intekwork & beam points filling completed
- electrical conducting work is completed (except bathrooms)

Brickwork Check

- Mark V for correct or numer mistake which does not require correction
- Mark X for minor mustake that requires minor concetion.
- Nank XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC
- Chicken mesh should be used in each and every joint between RCC & Brickwork
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- ('heck room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than I "in a room. Door frames must have black Japan coating and wood printer / pellumbar - at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plustering is 6" below FFL
- Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws

Quality Control Check Repot. Stage: After Brickwon	Stage: After Brickwork (Villas)
Quality of edges and corners in all rooms?	☐ Good ☐Avg. ☐ Bad
Specify rooms that need correction:	

Chujjas Quality Check

Remarks		lutal Nov. of Chajjas Slopes incorrect – nos. Thickness incorrect – nos Width incorrect - nos.
	<	s Width incorrect - nos.
	<	Height in correct - nos

Door France & Windows check

Zolow:

- Mark I has control on mineral mistake which does not require correction
- Mark X for major mistake that requires correction by replacement or re-fixing.
- Nank X X X for major mistake that cannot be corrected.

- Window template depth should be between 2 to 2 ½"after plastering.

 Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")

 Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33" from SFL. (Tolerance 1")

 Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.

 Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

	Ren	19	-8	17	=	_	_		;3	_	10	9	00	7	0	را ر		سوا ،	. 1		5 No
	Remarks:	Other	Other	Kitchen	Portico	Head room	lemme / halcony 2	Terment Indumy 1	I white I	Yuldu. [Aminic	Bulwind	Tailer 4	Bedrugm 4	Toilet 1	Bedroom 1		Hedman ? Jes	Trille 73	n l	Room
Monte	7,			<	j	ς	!	April 10 mm				س.			}	,	<	5	2	7	Door size, face and position (✓ or ×)
9	Haster			5	١	<	1	}	J	1		-		٠	1		<	<	5	<	Brick at bottom of door frame10 (or X)
de	العاله			<.	j	<	***************************************	1	J	1	•	-		•	J	J	Ċ.	7	<	2	Door lentil level ⁵ (✓ or 🗙)
from				<	ſ	7	١	Į	1)	•	ř	5	•	1	1	<	<	<	<	Door diagonal check ⁶ (vor x)
مۇ ھ	Vartilator			<	1	AND)	Ţ	3	1	•			Ţ	J	J	く	<	<.	Dr	Door Plumb - two sides (vor X)
7	12,			<	ſ	<	1	1	}	5	•	•]	1	}	<_	<	<		Door frame black Japan/ wood primer/Peelambar check (vor X)
anden.	~			<	<u> </u>	<	1	(1]	1		24	ļ	Ţ	J	7	<	<	7	Windows lentil & sill level(✓ or 🗙)
D. A. every	र '			ζ	1	ς .	1	4	J)	}	٢	•	}]	1	<	<	<	7	Windows size (✓ or 🗙)
,	-)			<	[<	1	1	1)	Ι,	<u></u>		j))	<	ς_	Ž,		Windows - template depth & diagnal ⁵ (✓ or ズ)
	Halinade			<		<	1	١))	[۲.		1		}	7	<		1	Windows - template powder coated ⁵ (✓ or ×)
	4			SOK	1	1)	1	1)	1	·		}]	J	ļ)	•		Loft & Kitchen platform required? (Yes or No)
				<	1	1	1	1	}	•	1	1	•	1	1	1	1))	1	Loft & Kitchen platform provided ⁸ (✓ or ズ or NA)
:				<	1	1	1	1	1	}	1	1	ĺ		j)	l]	1		Loft & Kitchen platform slope (✓ or 🗙)

Quality Control Cheek Repot. Stage: After Brickwork (Villas)

Quality Control Check Repot. Stage: After Brickwork (Villas)

Parapet wall thickness, height and design (v or X)	(v or x)	solumns: $\mathcal{U}_{\bullet}^{[\cdot, \bullet]}$	In level marked on villa & compound wall with 2 screws, 2 ft above FFL? LY Yes \(\text{No} \) Sugariting the first columns:	 	Quality and level at lear portico?	Quality and level of PCC on ground floor?	Specified compound wall height above 111 (2.6)	CRS + bed specified level below FFL: Actual level below FFL:	Kennank's	Dunn (200 lts) provided for curing in each flat?	J P	Wastage?	Is the Bungalow cleaned for plastering? [Yes No	Was the Bungalow cleaned before sturting brick work?	Condition of proportion box?	Misc, Checks. Was 3.75 CFT proportion box provided? □Yes □No
---	-----------	---	--	------	------------------------------------	---	--	--	-----------	--	-----	----------	--	--	------------------------------	--