Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck because the stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. A Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager		Company	Block No
it ATR on QC report to Ceed with work after submits only after making correlations. ATR not required.	MD Sign		Madhu Sudan,	Sisting Kulmer	Nilger Exter	139
C team. Procitting ATR on scrions pointed	'n	29707	Sign	Sign	Project	
eed only after recheck be QC report to QC team. I out in the QC report.		Report filed and signed by PM?	- Mr. W.	3	Nilger Estates	
by QC. ATR not required.	For filling	d by PM?	Date	Date	Phase	Sl. No.
	☐Yes ☐No	Yes No	16/8/18	16/8/18		31174

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam Yellow enamel paint to be used for marking FFL of flooring. Mark 2° above FFL on column steel. Plinth beam top must be 2°3° (in case of pavers) or 2°4° (in case of RCC slab) below the mark. Prepare plinth beam. Dimensions Check Plan as follows.

- Show outer dimensions (Tolerance 2")
 Show length and width of plinth beams (Tolerance 1")
 Print an A3 size plan

クルト

- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Plinth Beam Dimensions Check Plan enclosed?	
Yes No	The state of the s
	en are same to mis report

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	Good Avg. Bad
Have rods for staircase slab been provided?	□Yes □No
Quality of Bracing Provided?	Good Avg. Bad
Alignment of beams on outer side?	Good Avg. Bad
Brackets for elevation features provided?	☐Yes ☐No ☐NA
Level marking at 2° above FFL is made?	Yes No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	☐ Correct ☐ Needs correction
Pedestal/column() - self check report attached?	Yes No
Remarks: nucl Property not levelled.	
	The state of the s
Company and management of the second	

Plinth Beam Steel check.

Votes:

- Mark for correct or minor mistake which does not require correction
 Mark × for minor mistake that requires minor correction.
 Mark × tor major mistake that requires correction by replacement or re-fixing.
 Mark × × for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	/.	6.	J.	t. 1	ů.	2 1) -	N Z
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steet Check - Beams Overlapping & Cranking	Sicel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	5	5	5	5	5	۲		Quantitative Check
	Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)