	Quality Control Check Repot.		Stage: Before Casting Plinth Beam (Villas)	nth Beam (Villas)	
Block No	163 .	ł	1	SI. No.	29079
Company	Milami estatos	Project	Milan estato	Phase	F)
Prepared by	7	Sign	THE W	Date	82/01/18
Project Manager	Modbwindon	Sign	M. wat	Date	23/01/18
Previous stage report no.		28435	Report filed and signed	d by PM?	Nes □ No
Checked By MD on	MD Sign	ign		For filling	☐ Yes ☐ No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. AT Proceed with further work. ATR not required.	commendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. AT Proceed with further work. ATR not required.	QC team. Proc nitting ATR or rections pointe	eed only after recheck lack QC report to QC team	by QC. ATR not required.	

## Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.

  Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam. Dimensions Check Plan as follows:

  a. Show outer dimensions. (Tolerance 2")

  b. Show length and width of plinth beams (Tolerance 1")

  c. Print an A3 size plan.

- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

  Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Yes No	

## Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting.	\
Quality of centering, rod bending and concreting?	Good NAvg. Bad
Have rods for staircase slab been provided?	Nyes No
Quality of Bracing Provided?	☐ Good ☑ Avg. ☐ Bad
Alignment of beams on outer side?	☐ Góod ☐ Avg. ☐ Bad
Brackets for elevation features provided?	□Yes □No NA
Level marking at 2' above FFL is made?	No □No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	YCorrect ☐ Needs correction
Pedestal/column0 – self check report attached?	☐Yes ☑No
Remarks: 1) Afready Reducted Columns are Casted	

## Plinth Beam Steel check.

Notes:

- Mark  $\checkmark$  for correct or minor mistake which does not require correction Mark  $\times$  for minor mistake that requires minor correction.

  Mark  $\times$  for major mistake that requires correction by replacement or re-fixing. Mark  $\times$  for major mistake that cannot be corrected.

  Columns overlapping length should be 45 to 50 D.

Ouality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

S.No	Item	Quantitative Check	Qualitative Check
)		( v or X )	(Good / Avg. / Bad)
1.	Steel Check - Beam no of rods	>	Good Avg. Bad
2.	Steel Check - Beam size of bars	>	Good Mays. Bad
3.	Steel Check - Beams Extra Bars	7	☐ Good ☑ Avg. ☐ Bad
4.	Steel Check - Beams Overlapping & Cranking	>	Good MAvg. Bad
5.	Steel Check - Beams Bearing	>	Good NAvg. Bad
6.	Covering blocks for beams	<i>&gt;</i>	Good WAvg. Bad
7.	Depth and width of beams	<i>/</i>	☐ Good ☑ Avg. ☐ Bad
Remarks:			
	A MARIE MARI		