2	Quality Control Check Repot.	3	Stage: Before Casting Plinth Beam (Villas)	nth Beam (Villas)	
Block No	14	-		SI. No.	くしたのと
Company	nilajai Estatu	Project	wilgin Estate	Phase	=
Prepared by		Sign	SERVERT	Date	810= (40 / 90
Project Manager	radhu sudhan Sign	Sign	ろういかん	Date	8105/100/90
Previous stage report no.		30322	Report filed and signed by PM?	d by PM?	☑Yes □No
Checked By MD on	MD Sign	gn		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	it ATR on QC report to eed with work after subr rk only after making cor rk. ATR not required.	QC team. Proc nitting ATR or rections pointe	eed only after recheck loger only after recheck loger to QC team.	by QC. ATR not required.	

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.
 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.
 Prepare plinth beam Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")
- Show length and width of plinth beams (Tolerance I") Print an A3 size plan.

- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Plinth Beam Dimensions Check Plan enclosed?	∠Yes □ No

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting.	THE RESIDENCE AND ADDRESS OF THE SECOND SECO
Quality of centering, rod bending and concreting?	☐ Good [☐ Avg. ☐ Bad
Have rods for staircase slab been provided?	∏Yes □Nο
Quality of Bracing Provided?	☐ Good ☑ Avg. ☐ Bad
Alignment of beams on outer side?	☐ Good ☑ Avg. ☐ Bad
Brackets for elevation features provided?	□Yes □No ☑NA
Level marking at 2' above FFL is made?	☐Yes ☐No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Pedestal/column0 – self check report attached?	∏Yes □Nο
Remarks: i) Mud peoperly not levelled inside and outsid	outside the willa.

Plinth Beam Steel check. Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.

 Mark X X for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	. ω	2.		S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
		<		<	~	_	1	Quantitative Check (• or x)
	☐ Good [Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐Good ☐ Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)