Quality Control Check Repot. Stage: After Plastering (Villas)

		16 (See Succession			
Villa No.	213	Stage		Sl. No.	33 053
Company	(dr)) ran	Project	70v	Phase	1
Prepared by	S. Kuldeep	Sign	Bulders-	Date	01/03/19
Project Manager	A Susush.	Sign	(f	Date	01/03/19
Previous stage report no.	no.	7 2018	Report filed and signed by PM?	d by PM?	☐Yes ☐No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furth	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck Stop further work. Proceed with work after submitting ATR on QC report to QC team Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	eport to QC team. Proc fter submitting ATR or king corrections pointe	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	k by QC. m. t. ATR not required.	
Proceed with furth	Proceed with further work. ATR not required.	iired.			

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.

 Mark X X for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Kei	7 17	10	18	17	16	15	14	13	12	11	10	9	∞	7	9	S	4	ယ	2	_	S No
Kemarks	Onici	Othor	Utility	Kitchen	Portico	Head room	Terrace/ balcony 2	Terrace / balcony 1	Lobby 2	Lobby 1 Pools	Dining	Drawing	Toitet 4	n 4		n 3		n 2	Toilet 1 つって	Bedroom 1 ~ &	Room
			1	1.	1	1.	Ţ	T.	1	(ζ	Α,	!	!	<	1	ζ	ス	ς	٢	Skirting Provision (v or x)
			Ţ	Ţ	1	1	1	1	ļ	([ζ	-	ı	۲,	5	ζ	٢	۲	۲	Finishing around door frame (v or x)
			(([1	1	1		ζ	ζ	ζ	1	-	(ς	5	٢	7	۲	Beams & columns finishing (v or x)
			į	1	1	١	1	Ĭ	1		١	1	1	ļ		١	1		ľ	1	Finishing of lofts (• or ×)
			(1	ı	1	1	l		ς.	×	7	I	!	1	V	V	~	٢	٢	Electrical junctions finishing (• or ×)
			(1	1	1	1	1	ı	1	1	7	ſ	1	ζ	1	4	7	٢	٢	Window check (✓ or 🗙)
			<	1	-	5	1	J	Ī	1	1	1	1	ı	(J	V	1	7	{	Tiles provision (✓ or 🗙)
			į	-	1		١	1	-	Ţ	1	Ţ	!	İ	١	1	-	ţ	-	1	Sink provision & size (✓ or 🗙)
			,	1	[<	1	1	-	1		1	!	1		Α.	7	٢	7	٢	Grooves for door frames (v or x)
			Ţ	1	1	1	-	1	ζ.	1	1	1	ı	1	(1	1	1	1		Balcony & terrace sill top finishing ¹⁰ (v or x)
			1	ſ	-	1	1	1	•	1	1	}	1	ļ)	,	1	1	1	1	Screeding in bathroom & utility (• or ×)
			([1		1	Į	1	(Ţ	Ŧ)	!	1	l	(1	ļ	1	Screeding in 6" above FFL? (v or x)

Quality Control Check Repot.

Stage: After Plastering (Villas)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check		
Overall quality of plastering?		☐ Good ☐ Avg. ☐ Bad
Plastering of compound wall & gate pillars (v or x)	or X)	(
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	rnal walls 6" below FFL of setbacks?	Yes No
Plastering quality of parapet walls (\checkmark or \times)		7
Plastering and finishing of chajjas (✓ or 🗙)		port
Remarks:		θ