Canala Const of Charles Inches	Creme Axica bilengoine
--------------------------------	------------------------

Bungalow No.	262	Others		S No	22120
Company	100 (11P)	Project	790	Phase	
Prepared by	S.Kulderp	Sign	Andre	Date	102/19
Project Manager	Assurab	Sign	E	Date	12 03/15
Previous stage report no.	10.	32076	Report filed and signed by PM?	ed by PM?	Yes No
Bungalow No		Other		Other	
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Stop further work. Proceed with further	Submit ATR on QC r Proceed with work at	eport to QC team. Profer submitting ATR o	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report.	k by QC. m. ATR not required	
Proceed with furth	Proceed with further work. ATR not required	nired.		1	5 5

Inspection should be done after:

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed
- electrical conducting work is completed (except bathrooms).

Brickwork Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: I")
- Diagonals of each room shall be equal. (Tolerance: 2")
- Balcony sill level should be 3'3" from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar -- at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.
- Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws.

Ren	19	18	17	16	15	14	13	12			c	∞	7	6	2	4	ယ	2		S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace / bal	Terrace/balcony 1	Lebby 2	Lebby I	Dining	Drawing	Toilet 4	Bedroom 4	Toilet 3	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom 1	Room
						balcony-2	ony 1		-	P				1.5	8.5	トゴ	1.00 E	3	প্র	
			۲	1	7		٢	1	!		٢]	1	(7	5	ς	7	1	Wall thickness (✓ or ×)
			<	1	7	ı	7	1	ı	-	7	ı	Ţ	<	1	1	1	۲	۲	Beds in walls (v or x)
-	11		7	1	ζ	•	ζ	1	1	 c	٢	ļ	1	(ς.	'	ς .	ς	ς	Chicken mesh (v or x)
1			X	l	*		7	Ţ	1	ζ	7	1]	X	ζ	۲	7	X	7	External brickwork & beam joint (or x)
			٢	-	1		7	1		ζ.	7	Ţ	}	(ζ	7	7	ζ	ς	Room Dimensions (v or x)
			ı	l	1	ļ	Ţ	1	1	Ţ	1	1		1	1	ı	1	1	!	Room Dimensions Difference in inches
			(1	7	1	ς	ţ	I	7	7	1		(7	7	ζ	٢	(Diagonal (v or x)
			1	1	1	1	ţ	Ţ	ļ	Ī	1	-	1	(1	1	1	1	l	Diagonal Difference in inches
	-		1	1	1	!	<	L		!		1	!	1	1	1	1	ı	1	Balcony sill level
			7	1	(7	Ţ	1	?	7	ſ	1	(ς	?	?	7	?	Room Height (• or ×)
		c	Aug	0	400	1	Gos d	1	I	Ewas	Good	!	1-	Aud	bro	Cach	ore o	409	appo	Plumb of walls (Good/Avg./Bad)
			7	6	are	1	7	1	1	ζ.	ς	!	1	Ċ	7	5	0	And	\	Alignment of beams and walls - Nos.

Quality Control Check Repot.	Stage: After Brickwork (Villas)
corners in all rooms?	Cood TAME Dad
ped correction.	

	Specify rooms that need correction:	Quality of edges and corners in all rooms?
	ction:	in all rooms? Good Avg. Bad

Chajjas Quality Check

Notes: Width of chajja should be 6"more than the width or the door or window.

			Nelliaiks
		(Damasir
	ζ,		2
TIVISHI III COLLECT - MOS			0.0
Total Nos. of Chajias Slopes incorrect - nos Width incorrect - nos Height in correct - nos Height in correct - nos	Thickness incorrect _nos Width	Slopes incorrect - nos	Total Nos. of Chajias

Door Frames & Windows check

- Mark v for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected. Window template depth should be between 2 to 2 ½"after plastering.
- Lentil level should be 7'3" from SFL & 7' from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 32" or 33" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

Quality Control Check Repot. Stage: After Brickwork (Villas)

☐ Yes ☐ No	
☐ Good ☑ Avg. ☐ Bad	
☐Yes ☐No ☐ Cant' sa	У
Lyres No	
☐ High ☐ Medium ☐ Low	
☐Good ☐ Avg. ☐ Bad	
□Yes □No	
	Actual level below FFL:
1	Actual level above FFL:
	☐ Good Avg. ☐ Bad
	☐ Good ☐ Avg. ☐ Bad
	Yes □No
Is level marked on villa & compound wall with 2 screws, 2 ft above FFL?	☐Yes ☐No
21-611	Actual height provided: 26
10-101	Actual distance provided: 10
	1
	7
Parapet and compound wall railing design quality, fitting & redoxide painting (v or x)	<
	ss