	Quanty Colly of Check Report Stage: Al	
	ant	-
	~	;
	ווטע	2
	III	-
	.11E	,
i	CK	֚֚֚֚֚֡֝֝֝֜֜֝֜֝֜֝֟֝֜֝֜֜֝֜֜֜֜֜֝֓֓֓֜֜֜֝֓֜֜֜֜֝֡֓֜֜֜֝֡֓֜֜֜֡֡֡֡֡֡֡֡֡֡
	Ne	J
	pu	
	•	_
	213	2
2	19e	
200	H	•
200000000000000000000000000000000000000	TILE	
200	L	•
	STI	
	Š	<u>_</u>
	Š	
	Stage: After Brickwork (VIII	
	~	4 7
Į	=	

				- A	The masting also also also also also also also also
			iired.	Proceed with further work. ATR not required	Proceed with furth
	ort. ATR not required.	d out in the QC repo	✓ Proceed with further work only after making corrections pointed out in the QC report.	er work only after mak	Proceed with furth
	am.	1 QC report to QC te	Stop further work. Proceed with work after submitting ATR on QC report to QC team.	Proceed with work at	Stop further work.
	ck by QC.	seed only after reche-	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck	Submit ATR on QC r	Stop further work.
			30 300000		Recommendation:
□Yes □No	For filling		MD Sign		Checked By MD on
	Other		Other		Bungalow No
√Yes □No	gned by PM?	Report filed and signed by PM?	30615	no.	Previous stage report no.
02/01/19	Date	T.	Sign	A · Supresh	Project Manager
02 01 119	Date	1.5. K.M.	Sign	V. Sambell	Prepared by
	Phase ,	Voc	Project	Vec (LLP)	Company
32527	SI. No.		Others	36	Bungalow No.

inspection should be done after:

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed.
- electrical conducting work is completed (except bathrooms).

Brickwork Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.
- Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws.

Quality Control Check Repot. Stage: After Brickwork (Villas)

	Specify rooms that need correction:	Quality of edges and corners in all rooms?
	÷	☐ Good ☑ Avg. ☐ Bad
	÷	

Chajjas Quality Check

Notes: Width of chajja should be 6"more than the width or the door or window.

Total Nos. of Chajjas	Total Nos. of Chajjas Slopes incorrect - nos. Thic	Thickness incorrect –nos Width incorrect - nos.	Width incorrect - nos.	Height in correct - nos
+	<.	<	<	~
Remarks	-			

Door Frames & Windows check

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.

- Window template depth should be between 2 to 2 ½"after plastering.

 Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")

 Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 32"or 33" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

	Ren	19	8	17	16	15	4	3	12	=	=	<u>د</u> 	∞	7	6	S	4	3	2	1	S No
	Remarks: XX. Instead	Other	Other	Kitchen	Portico	Head room	Terrace/-balcony 2	Terrace/ balcony 1		Lobby 1 Lowrage	Dining	Drawing	Toilet 4	Bedroom 4	Toilet 3	Bedroom 3 G. V3		12	Toilet 1 Notal	Bedroom 1 M.设	Room
Head som.	tead			<	1	べる。	ţ	V	í	1	1	<	1	ļ	<	<	X	<	K.		Door size, face and position (✓ or X)
800.	9			<	1	乀	١	<u> </u>	•	١	1	V	•		<	<	X	K,	<		Brick at bottom of door frame10 (✓ or 🗙)
	5-6" X			<	1	<		<u> </u>		1	1	<	Î	1	<.	<	ζ.	<	<	<	Door lentil level ⁶ (v or X)
	(19だ)			<	4	<	1	<	1	I	٦	٠.	*		<	K	K	<	<	<	Door diagonal check ⁶ (✓ or ★)
	ther.			4	1	۷	1	~	1	1	ì	<	1	١	<	<	<u> </u>	Ç	<	<	Door Plumb - two sides (✓ or 🗙)
	Pari ded			<	1	<	1	<	1		1	<	1.	1	<	<	2	<	~	<u> </u>	Door frame black Japan/ wood primer/Peelambar check (or X)
	Last Control		35 35 45 55 55	<	1	1	1	ľ	1	4	۷	<	١	١	X.	7	Ċ.	V	<	Į,	Windows lentil & sill level(v or x)
	3-0"×			<	1	f	1	1	1	<	<	<	٩	١	<	<	<	ζ	Ç	<	Windows size (✓ or 🗙)
	(in Orth X			K	ľ	٩	1	١	1	<	. <	<	1		<	K	<	<	<	<	Windows - template depth & diagnal ⁵ (✓ or X)
	(Can't			<	1	1	1	1	ì	<	<	C	1	1	<	<	<	<	c	<	Windows - template powder coated ⁵ (✓ or ×)
	Jeanne			•	1	1	1	١	1		1	1	1	•		1	1	١	١	f	Loft & Kitchen platform required ? (Yes or No)
	e of			1	•	1	1	1	I	١	1	ļ	1	1	9)	1	1	1	****	Loft & Kitchen platform provided ⁸ (✓ or X or NA)
				1	90000	•	1		1	9	1	egecanc	è	1	1) 1	()		١	Loft & Kitchen platform slope (✓ or X)

Quality Control Check Repot. Stage: After Brickwork (Villas)

IVIISC, CHECKS.		
Was 3.75 CFT proportion box provided?	✓ Yes UNo	÷
Condition of proportion box?	☐ Good ☑ Avg. ☐ Bad	
Was the Bungalow cleaned before starting brick work?	☐ Yes ☐ No ☑ Cant' say	ay
Is the Bungalow cleaned for plastering?	Yes No	
Wastage?	☐ High ☑ Medium ☐ Low	
Storage of building material like bricks sand and cement.	Good Avg. Bad	
Drum (200 lts) provided for curing in each flat?	✓ Yes ☐ No	
Remarks:		
Compound wall check		
CRS + bed – specified level below FFL:		Actual level below FFL:
Specified compound wall height above FFL:	2-6"	Actual level above FFL: 2:7
Quality and level of PCC on ground floor?		Good Avg. Bad
Quality and level of PCC for portico?		Good Avg. Bad
Is leveling in the setbacks of the villa 6" below FFL?		Yes No
Is level marked on villa & compound wall with 2 screws, 2 ft above FFL?	ove FFL?	☐ Yes ☑No
Specified height of gate columns:	2-6	
Specified distance between gate columns:		Actual distance provided: 📈
Chicken mesh provided on external joints of villa (✓ or ×)		<
Parapet wall thickness, height and design (v or x)		<
Parapet and compound wall railing design quality, fitting & redoxide painting (v or x)	xide painting (vor x)	*
Remarks: (1 one of the Crate Columns	not asted.	
(2. SCOreus not fixed.		