## Quality Control Check Repot. Stage: After Brickwork (Villas)

Bungalow No.	4)	Others		Sl. No.	31443
Company	K N M	Project	Bloomdale	Phase	4
Prepared by	V. Sanketh	Sign	J. Sweeth	Date	11-09-18
Project Manager	Bala Numal: Vaishora	Sign		Date	81-60-11
Previous stage report no.	no.	30467	Report filed and signed by PM?	ed by PM?	√Yes □No
Bungalow No		Other		Other	
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation:	ecommendation:	port to OC team Proc	eed only after recheck l	hv OC	÷
Stop further work	Stop further work. Proceed with work after submitting ATR on QC report to QC team.	ter submitting ATR on	QC report to QC team.	,	
Proceed with furth	Proceed with further work only after making corrections pointed out in the QC report.	ing corrections pointed	out in the QC report.	ATR not required.	
Proceed with furth	Proceed with further work. ATR not required.	ired.			

Inspection should be done after:

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed.
- electrical conducting work is completed (except bathrooms)

### Brickwork Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 12. Check room height with specified height. (Tolerance: I")
- Specify the No. of beams which are not aligned by more than 1"in a room. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.
- Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws.

Ren	19	18	17	16	15	14	13	12	1	10	9	∞	7	6	S	4	3	2		S No
Remarks A	Other	Utility	Kitchen	Portico	Head room	Terrace / balcony 2.	Terrace/ balcony 1	Lobby 2 Pooja	Lobby 12 L	Dining	Drawing	Toilet 4	Bedroom 4 Standy		n 3	Toilet 2 G.T	n 2		Bedroom 1 MR	Room
			7	F	4		4	۷	۲,	4	۷,	1	۲,	۷,	۲.	کی	<b>~</b>	۷.	7	Wall thickness
			4	1	4	١	7	5	۷.	۷.	4	-	4	Y	4	کر	۷.	<b>&lt;</b>	4	Beds in walls (v or x)
,			4	1	X O		4	4	7	~	۷	1	<u>ــ</u>	J	~	1	_	4	4	Chicken mesh (✓ or 🗙)
			4	1	۷.	C.	4	۷	۷,	۷	۷	1	_	7	7	~	<u>ح</u>	* \	<	External brickwork & beam joint ( > 0
			۲	١	7	١	۷.	۲,	۲	ረ	٤	1	~	۷	۲,	۷	4	7	ح	Room Dimensions
			4	1	_	۱.	4	~	۲	۷,	4	١	۷,	۷	_	۷.	ζ,	۷	4	Room Dimensions Difference in inches
-	_		۷	1	۷	١	4	4	_	4	5	1	<b>ا</b>	_	۷	۷	۷,	۷	_	Diagonal (v or x)
			۲	1	4	3	۲,	4	<u> </u>	<u>``</u>	4	l	4	_	۲,	٢,	<b>ح</b>	۷	۷	Diagonal Difference in inche
			1	15.7	1	1	1	1	1	A	ă.	1	1	A.,	١	١	٩	1	1	Balcony sill level ( • or x)
			4	i	4	1	4	۷.	4	4	'\	1	5	۷,	4	4	7	4	۷	Room Height ( v or x)
			٢.	4	_	1	4	D S	٢,	4	47		۷,	ز	4	4	۷,	4	۷,	Plumb of walls (Good/Avg./Bad)
			4	Ţ	<	10 mm	۲	4	4	<	4		۷	4	4	4	4	人,		Alignment of beam and walls - Nos.

	)u
	ality
	Control
	uality Control Check Repot.
	pot.
-	Stage:
1	After ]
The state of the s	Brickw
	Stage: After Brickwork (Villas)
	Has)

Quality of edges and corners in all rooms?	☐ Good ☐ Avg. ☐ Bad
Specify rooms that need correction:	

Chajjas Quality Check
Notes: Width of chajja should be 6"more than the width or the door or window.

Remarks	81	Total Nos. of Chajjas S
٥	~	lopes incorrect – nos.
	~	Slopes incorrect – nos. Thickness incorrect – nos Width i
	7	Width incorrect - nos.
	~	Height in correct - nos

## Door Frames & Windows check

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 1/2" after plastering.
- Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 32" or 33" from SFL. (Tolerance 1") Slopes of lofts and kitchen platforms to be checked by using 12" spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

# Quality Control Check Repot. Stage: After Brickwork (Villas)

∠ Yes No	
Good Avg. Bad	
	ıy
Yes No	
☐ High ☐ Medium ☑ Low	
☐ Good ☐ Avg. ☐ Bad	
✓Yes □No	
	The second secon
	Actual level below FFL:
	Actual level above FFL:
	A Cood Try 8. Trum
	Good Avg. Bad
	Yes No
Is level marked on villa & compound wall with 2 screws, 2 ft above FFL?	Yes □No
	Actual height provided:
	Actual distance provided:
	<b>L</b>
Parapet and compound wall railing design quality, fitting & redoxide painting ( v or x)	×
on Bakany.	
	☐ Good ☐ Avg. ☐ Bad ☐ Yes ☐ No ☐ Cant' say ☐ Yes ☐ No ☐ High ☐ Medium ☐ Low ☐ Good ☐ Avg. ☐ Bad ☐ Yes ☐ No ☐ FFL?  FFL?  Falcong.