	Quality Cor	Quality Control Check Repot.	Stage: After Brickwork (ork (Villas)	
Bungalow No.	4	Others		SI. No.	20100
Company	Severe Complianting Project	Project	Steven form	Phase	8 1 1 8
Prepared by	M. leja. Smdhu	Sign	١ ,	Date	* O. a.
Project Manager		Cian	, F		81/20/50
Pravious stocs	Balamire Kirolma Sign	Sign	J. J. J.	Date	81/80/50
r revious stage report no.	no.	28422	Report filed and signed by PM?	d by PM?	√Yes No
Bungalow No		Other		Other	
Checked By MD on		MD Sign		For filling	TVes TNo
Recommendation:				O	
Stop further work. Stop further work. Proceed with furth	Submit ATR on QC re Proceed with work after maker	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections.	ed only after recheck because of the propert to QC team.	y QC.	
Proceed with furth Proceed with furth	Proceed with further work only after making Proceed with further work. ATR not required	Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	out in the QC report.	VTR not required.	
nspection should be done after:	after:				

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed.
- electrical conducting work is completed (except bathrooms).

Notes: Brickwork Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark × for minor mistake that requires minor correction.
- Mark $\times \times$ for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 12. Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.

			Remarks	19	1-	┿	-	-	5	14	13	12		: 5) ×	0 -	7	6	2	4	, u	, ,	١.	S No
Note The	1000		くごう	Other	Utility	Kitchen	r-eretico	Double Treatment	Hand room	Terrace/halcony?	Terrace/ balcony 1	Lebby-2	tobby I-	Dining	Drawing	I other 4	THOOTHOUT	Badroom /	Toilet-3	-Bedroom-3	Toilet 2 (CT)	Bedroom 2 (KB)		1 1	Room
fixung	Athur	0	- 1			<	1	1		. ,	,	1	1	I	<	•	1]	1	4	ς.	3	<	Wall thickness (~ or ×)
2	i	Coilet	1			メイド		1	1)	,	1	1	<	1	(1		1		ζ	ζ	<	Beds in walls (v or x) Chicken mesh (v or x) External brickwork & beam joint (v or x)
aules	35	Chulce	,		/	*	\ 	(1 1	- -		(メ	*	1	<u></u>)			人人	×	×	×	Chicken mesh
mesh	CC			-			-	1)	ſ]	3	<	۲	1	ţ	1	. 1	•		<	ζ	<	External brickwork & beam joint (or
was	C bed	muh			•		1	1	[-	\				\	1	1	1	}	(1		<	5	Room Dimensions
a Roor	S.	was n	_			\	1)	<i>j</i>	}		}		\	1	1	{	1	1	1			J	}	Room Dimensions Difference in inches
5.	wall	not fixe			<	\	1	1	1	1	1	1	-	<	; j		,	}	1	<		,	`	5	Room Dimensions Difference in inches Diagonal (v or x)
九	was	ed,			1		\		1	}	1	1	1			1	1	[ļ	,	1			١	Diagonal Difference in inches Balcony sill level
51	782				{		1	{	1			1	1	1	1]	,	1]	Balcony sill level (* or *)
inter	tand				< -	1	<u> </u> }))]]	,	<	\	1			1	1	<	<	K	, ,		Room Height
Villa.	Ž.			ر	170	1		1	1	1	\ _		7	1	\ \ \	1	1		,	14	23	1/		*	Plumb of walls (Good/Avg./Bad)
<u> </u>			_		<])])	}	<	<	(1			1	<	3	5	<	١.	Alignment of beams and walls - Nos.

Door Frances & Windows check		Chajjas Quality Check Notes: Width of chajja should be 6"more than the width or the door or window. Total Nos. of Chajjas Slopes incorrect—nos. Thickness incorrect—nos.	Quality of edges and corners in all rooms? Specify rooms that need correction: Check Repot. Stage: After Brickwork (Villas) Good Navg. Bad
	rect - nos		

- Mark V for correct or minor mistake which does not require correction Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.

- Window template depth should be between 2 to 2 ½"after plastering.

 Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")

 Lofts should be at a height of 7' to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 32" or 33" from SFL. (Tolerance 1") Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

CO PC		marks:	19 Other	-	-		-	+		+-		1) Lining	4.		+	7 Dad	4		Toilet 2		$\overline{}$	1 S No Bedroom 1 (MB)
?	10	· -	+		1	(1		}	1	-	,	7	1	1])	<	1	, (Door size, face and position (or x)
Dedroom	fast	_	+		۱ 	1	1	1	1	(1	-	1	1	1	\ \ 	1	K	<	,	1	Brick at bottom of door frame10 (v or X)
	was	 	-	-		4	1	1	1	1	1	1	1	1]	1	j	2	5	<	, <	Door lentil level ⁶ (• or ×)
Juser	son ca		-	1		1		4	!	\	<u> </u>	1	5	1	1	ı	1	_	<	<	1	Door diagonal check ⁶
fame.				1	1		1 1			1 1		1	51		1		,	1	\	5	5	Door Plumb - two sides
	hrud				1	\ 	{		-			\	'\	1	1	1	1 1		<	<	,	Door frame black Japan/ wood primer/Peelambar check (vor X)
	B	-		<	{	1		1	1	1)	1	<	, //	1	1	1	•		<	۲	<	Windows lentil & sill level(• or ×)
	Man	-		<	 -	-	1	1			1	7	1				<		5	<	5	Windows size (✓ or 🗙)
			+	\ -		1)	}	1	5		}])	<			(5	Windows - template depth & diagnal ⁵ (✓ or 🗙)
1	Coox	+	-	\ -	1	1	1	1	1			5	1	1	1	1	K	7		5) [p	Windows - template powder coated 5 (v or X)
	frame		100			!))	1	(1	1))	h	/	1	1		, L	Loft & Kitchen platform equired ? (Yes or No)
	۶	<u> </u>	1	1	+	!			Į)	1	j	l.	Į.	l	1	l	1	1		pı	Loft & Kitchen platform rovided 8 (• or × or
			1	1)		1 /	,	V	(1))	\mathfrak{I}	l	 }	1	1	Lo	oft & Kitchen platform ope (v or X)

Quality Control Check Repot. Stage: After Brickwork (Villas)

Was the Bungalow cleaned before starting brick work? Is the Bungalow cleaned for plastering? Wastage? Storage of building material like bricks sand and cement. Drum (200 Its) provided for curing in each flat? Compound wall check CRS + bed - specified level below FFL: Specified compound wall height above FFL: Quality and level of PCC on ground floor? Quality and level of PCC for portico? Is leveling in the setbacks of the villa 6" below FFL? Specified distance between gate columns: Chicken mesh provided on external joints of villa (• or x) Parapet and compound wall railing design quality, fitting & redoxide painting (• or x) Remarks: (1) The distance between the factor of the fitting & redoxide painting (• or x) Remarks: (1) The distance between the factor of the fitting & redoxide painting (• or x)	Good Avg. Bad Yes No Cant' say Yes No Cant' say High Medium Low Good Avg. Bad Yes No Actual level below FFL: — Actual level above FFL: — Good Avg. Bad Good Avg. Bad Good Avg. Bad Actual height provided: 6 : 0 !! Actual distance provided: 12 9 !!
Condition of proportion box provided?	XYes UNo
Canada.	Γ
Condition of proportion box?	
VI/n~ 4h~ D	AVg.
was the bungatow cleaned before starting brick work?	No Ricant
Is the Bungalow cleaned for nlastering?	C to Call
Strivenson Landson Francisco	Γ
Wastage?	Nedium 1
Storage of building material like bricks sand and cement	, L
Jrnm (200 kg) 2000 1 1 5	
Provided for curing in each flat?	Nes No
Remarks:	
Compound wall check	
CRS + bed - specified level below FFL:	A
Specified compound wall height above FFL:	Trechat Toket Gelow LLF.
Quality and level of PCC on ground floor?	Actual level above FFL:
() mality and level of DCC for and those	☐ Good ☑ Avg. ☐ Bad
Kenney min react of the following	
Is leveling in the setbacks of the villa 6" below FFI?	u ∐ Avg. ∐ Bad ·
	Actual height provided: 6.01
12.0	Actual distance provided: 19
nicken mesh provided on external joints of villa (or X)	157 - TAINTA TAINTE
arapet wall thickness, height and design (or x)	
arapet and compound wall railing design and the feet	
emerican wan failing design quality, fitting & redoxide	
hate distance between hate	painting (v or x)
	painting (v or x)