Block No. Style Column No. C3 St. No. 33655 Company Syle Project Sign Phase TX Prepared by J. Carr. Heath Sign Phase TX Project Manager Report Manager Report Manager Report Fled and signed by PM? Phase Phase TX Previous stage report no. Sign Phase Date 25 25 16 Previous stage report no. 33 494 Report filed and signed by PM? Proceed by PM? Proceed with further work Submit ATR on QC report to QC team. Proceed only after recheck by QC. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.			
Project Sign Sign Sign Project Sign Phase Phase Date Tho. Sign MD Sign MD Sign MD Sign Report filed and signed by PM? Submit ATR on QC report to QC team. Proceed only after recheck by QC. Report filed and signed by PM? For filling For filling Ther work only after making corrections pointed out in the QC report. ATR not required.	54		
Sign K. F. Carr. Left Sign Sign Date Tho. Tho. Sign Report filed and signed by PM? Submit ATR on QC report to QC team. Proceed only after recheck by QC. Report for QC report to QC report to QC report to QC report to QC report. ATR not required.	Sov (11P)		
Sign Tho. Sign Report filed and signed by PM? MD Sign MD Sign Report filed and signed by PM? Submit ATR on QC report to QC team. Proceed only after rechcck by QC. Report filed and signed by PM? For filling For filling Therefore work only after submitting ATR on QC report to QC team. Therefore work only after making corrections pointed out in the QC report. ATR not required.	V.Com.Keth		
Tho. 3.3 4.44 MD Sign Report filed and signed by PM? For filling For filling ND Sign For filling For filling ND Sign For filling	下ではかける		î
MD Sign For filling Roubmit ATR on QC report to QC team. Proceed only after rechcck by QC. K. Proceed with work after submitting ATR on QC report to QC team. ther work only after making corrections pointed out in the QC report. ATR not required.			by PM?
ork. Submit ATR on QC report to QC team. Proceed only after recheck by ork. Proceed with work after submitting ATR on QC report to QC team. further work only after making corrections pointed out in the QC report. A further work. ATR not required.	М) Sign	
	Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after su Proceed with further work only after making c Proceed with further work. ATR not required.	to QC team. Proceed only after recheck bubmitting ATR on QC report to QC team. corrections pointed out in the QC report. 1	

Notes:

- Inspection should be done after easting of columns at each stage and before starting centering works for each slab.
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolcrance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

2121 7	Columns	5. Circle
imensions Check	Columns Position Check Plan enclosed?	ach correct dimension with green color
	✓ Yes No	Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

DILLETISIONS CHECK.

Notes:

- 1. Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconics (Tolerance 1")
- Show inner dimensions of ducts and lift well. (Tolcrance 1") Show location of sunken slab.
- Print an A3 size plan.

Specified thickness of slab?	Siab Dimensions Check Plan enclosed?	2	2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and me
5" Actual thickness of slab?	Yes No		orrect dimension with red color
ss of slab?	o`	THE STATE STREET, STATE STATE OF THE STATE O	ir and mention actual dimension next to it
	0.00.00000 - 20.000		

Quality Control Check Repot. Stage: After Column Casting (villas)

Quality of centering, rod bending and concreting?		Good Avg. Bad
Quality of starters?		√Good Avg. Bad
Number and size of honey combs?		☐ High ☐ Medium. ☑ Low
Are the honey combs is slab and columns packed?		√Good ☐ Avg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	han 1"	
Have 6 cubes each for columns and slab casted and numbered for testing?		√Yes □ No
Remarks:		
Curing.		
Bunds for curing made on slab?	√Yes □No	
Bund size is less than 100 sft?	√Yes □No	
Drum (200 lts) provided for curing?	☐Yes ☐No _	
Gunny bags used for column curing?	Yes No	
Distance of tap from furthest distance that requires curing. (max permitted 100')	30-0"	
Frequency of curing in number of times a day (enquire from labourers)	2times	
Is the pressure in the curing pipe more than 15' head?	Yes No	:
Quality of infrastructure for curing.	√Good Avg.	Bad
Remarks:		

Columns height, plumb, steel & level marking check. Notes:

- Mark for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.

 Tolerance: Plumb 0.25".

, , , , , , , , , , , , , , , , , , ,	10	Ξ	×	17.	16.	15.	14.	13.	12.	11.	10.	9.	œ	7.	0.	Ö.	1.	\ \ \ \	, i.) :-	•	ONTO	o No
_																	econ.	1	Ç	62		Col No. Col type Height in ft Steel (v or x)	- D. I XI
<u></u>																	<u>C</u> 3	3	Cs	5		Col type	
<u> </u>																	: 4-8	16-3	1,6-8	14-8	bjec.	Heigh	TOACT GITTOS
																	= \\ \'\\ \'\\\ \\ \'\\\\\\\\\\\\\\\\\\	9 .00	8,8"	8.6.	Actual	t in st	moin specific
		-														4	<u></u>		<		rods	Steel (d height by m
																<		< <	. <		Size of	or X)	ore than 1".
																<		, c	\ <			Honeycombs	
																<	~ <	<	<		Side 1		
																<	K.	\ \	<		Side 1 Side 2	(v or x)	
Yes [☐ Yes ☐	Yes	☐ Yes ☐	☐ Yes [☐Yes [☐ Yes ☐	☐ Yes [∐Yes [∐Yes [Yes	T cs L	Yes	Yes	Yes	Yes	✓ Yes	100	N is	Z res	COLUMN;	marked on	Reference level	
	No	No	No	No	No	No	No	No	No	No	No	NO NO	No	No	No	No	INO	NO	No		ž	e level	