Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report.	Checked By MD on	Previous stage report no.	Project Manager		Company AG+	Block No
on QC report to work after subnufter making connot required.	MD Sign	Quint's	20Kign)+168gin.	S-Sunil Xumas		3 F
QC team. Procenitting ATR on rections pointed	gn		Sign	Sign	Project	-
		Report filed and signed by PM?	aby.	A COLUMN	AVR GWLMOND	
by QC. n. ATR not required.	For filling	ed by PM?	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	☐ Yes ☐ No _	6110	クサーク	\	33926

Quality Control Check Repot.

Stage: Before Casting Plinth Beam (Villas)

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.
 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.
- Prepare plinth beam Dimensions Check Plan as follows:
- Show outer dimensions. (Tolerance 2")
- Show length and width of plinth beams (Tolerance 1")
- Print an A3 size plan
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Plinth Beam Dimensions Check Plan enclosed?
☐Yes ☐No

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

 Г	 1.	T	1					,	r			-
	o eils, as ones M.D. sign Trestanchiones.	ac checking was not done for tookings because i	Remarks: Mud was not properly hadred inside of aut side of ville		Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Level marking at 2' above FFL is made?	Brackets for elevation features provided?	Alignment of beams on outer side?	Quality of Bracing Provided?	Have rods for staircase slab been provided?	Quality of centering, rod bending and concreting?	Quality of centering, rod bending and concreting.
		Cause water was strain	of villa.	Yes No	☐ Correct ☐ Needs correction	∠Yes □No	□Yes □No ⊡NA	☐Good ☐ Avg. ☐ Bad	☐Good ☐Avg. ☐Bad	☐Yes ☐No	☐ Good ☐ Avg. ☐ Bad	

Plinth Beam Steel check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XXX for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	. ω	2.		S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	<		<	ζ,	ς.	<	ζ.	Quantitative Check
	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Good ∏ Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)