1	
	Quality C
2	Control Check Repot.
CI No	Stage: After Brickwork (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on MD Sign	Bungalow No Other	Previous stage report no. 27785 Report fil	Sign	Prepared by M. Tija Sudh Sign	Company Wilsin wtate Project Mile	Bungalow No. 84 Others
recheck by QC. QC team. C report. ATR not required.	For filling	Other	Report filed and signed by PM?	Date	Date	Milgin what Phase	Sl. No.
-	∐Yes ∐No		VYes ∐ No	8 1/10/80	8/10/18	7	9 4 68%

Inspection should be done after:

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed
- electrical conducting work is completed (except bathrooms).

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.

Ren	1 4	10	18	17	16	15	14	13	12	=	=	; =	∞	7	6	, v	1		۱۹	2	_	S	No
Remarks	Omer	Other	Utility	Kitchen	Pertico	Head-room	Terrace / balcony_2	Lenace/ balcony 1	Labby 2	+ wbby 1	Humb	Drawing	Toilet 4	Bedrostn-4	Louiera	Bedroom->	١,		Redroom 2 (KB)	Toilet 1 (MT)	Bedroom I (MS)	,	Coom
				<	1	(1	3	1	1		∵ ≺	//	1	1	}		<	<	<	<		Wall thickness
	}			<	1	1		1	, 1	. 1			1	5		1 3		<	<	<	,<		Beds in walls (or x) Chicken mesh (or x) External brickwork & beam joint (or x)
		- 12.		<	1	}	j	1	1	1	}	<u>.</u> د إد	1				1	\ \	<	<	1		Chicken mesh
				\ \	1	1		((1	ř	ر ز	\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\			1	 }	4	<	<	,		External brickwork & beam joint (• or X)
				\ <		1			1)	1	ζ,	<				1	<	<	, (\ I	Room Dimensions (• or ×)
			-		1	()		1	1	<u> </u>	•	, , , j				1	1	1	ſ			1	Room Dimensions Difference in inches
				- -	1		1)	i i	ŗ.	<	- 1	î)	1	}	<	<	1	< '	<	Diagonal (• or ×)
		-			1		1	1	Lower C.	1	ŧ			I	1	ļ	}	1		1	1	J	Diagonal Difference in inches
		-			1	1			}	:	ë	i		1	1	1		1	\]	1	1	Balcony sill level
					۲	1	1	-	1	Ì	† 	<	<	1	1	1		<		<	र	<	Room Height
				ے	top		1	1)			1.1	*		-	1		1 2	-	۲.	Ę	Ave	Plumb of walls (Good/Avg./Bad)
					<	1			1		1	<	Z	1	1	il-		1	<	<	<	K	Alignment of beams and walls - Nos.

Specify rooms that need correction: Quality of edges and corners in all rooms? Quality Control Check Repot. Good Avg. Bad Stage: After Brickwork (Villas)

Chajjas Quality Check

Remarks		ncorrect -nos Width incorrect - nos.	Notes: Width of chaila should be 6"more than the width or the door or Window.
	<	Height in correct - nos	
	emarks	emarks	of Chajjas Slopes incorrect - nos. Thickness incorrect - nos Width incorrect - nos.

Door Frames & Windows check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark \times for minor mistake that requires minor correction. Mark \times for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 1/2" after plastering.
- Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 32" or 33" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

Rer	19	18	17	16	15	14	13	12	=	=	င	8	7	9	5	4	Ċ.	, ,	۱ د	_	S No
Remarks:	Other	Other	Kitchen	Pertico	Head room,	Terrace-balcony 2	Terrace/balcony_1	Lobby-2	Lobby J	Uning	Drawing	Toiler-4	Bedroom 4	Toilet3	Bedroom?	Toilet 2 (公)	Bedroom 2 (165)	ر ج	1	Redroom 1/MR)	Room
			١	1	1	1	١) '	•		- ! !	1	1)	1	2	\ \	,	<		Door size, face and position (v or X)
			1	1	1	1	,	1		3		1	1	1		\	~	`	١	\ .	Brick at bottom of door frame10 (✓ or 🗙)
			1	t	1	1		j	ļ		<u>\</u>	I)		}	<	k	, ,	<	ς	Door lentil level ⁶ (✓ or X)
			1	1	1	1	1	1			<	1	١	1	1	ł	1	ς.	<	<	Door diagonal check ⁶ (✓ or X)
			1	1		1	}	}			₹	•	1	١	ì	<	1	<	<		Door Plumb - two sides
			1	1	1	1	1	1			· K	1	1		1/1	<	1.	<	<u>ر</u>	5	Door frame black Japan/ wood primer/Peelambar check (or X)
			<)	570.0	i,		<		19.	1	J	4		〈	<	<	Windows lentil & sill level(✓ or X)
			~	(1	١	١	i	1	:	₹,	,			1 1	•		5	<	<	Windows size (✓ or 🗙)
			~		1		1		•			, ,		The state of the s				<u>ر</u>	<	<	Windows - template depth & diagnal⁵ (✓ or 🗙)
i			K		1		1	,		1	<		1		1		4	<u>ر</u>	<	<	Windows - template powder coated ⁵ (✓ or ×)
				3)		1		: } :]		1	-	1	j	Loft & Kitchen platform required? (Yes or No)
				1	1	1	-			1	i	į	.]		})	١	١	1	1	Loft & Kitchen platform provided ⁸ (• or × or NA)
					1	1)		-	, ,	,				•	}	No.)	Loft & Kitchen platform slope (✓ or X)

Quality Control Check Repot. Stage: After Brickwork (Villas)

	- La Aller Andrews	
		Remarks: > Kailing not fixed
χ	doxide painting (✓ or 🗙)	Parapet and compound wall railing design quality, fitting & redoxide painting (or x)
2		Parapet wall thickness, height and design (✓ or ×)
<	STATE OF THE PARTY	Chicken mesh provided on external joints of villa (v or x)
Actual distance provided: 8'.5'/	81.54	Specified distance between gate columns:
Actual height provided: 5'0"	\$1.011	Specified height of gate columns:
☐ Yes ☐No		Is leveling in the setbacks of the villa 6" below FFL?
Good Avg. Bad		Quality and level of PCC for portico?
Good Navg. Bad		Quality and level of PCC on ground floor?
Actual level above FFL: 4.6"	4:611	Specified compound wall height above FFL:
Actual level below FFL:	1	CRS + bed - specified level below FFL:
		Compound wall check
The state of the s		Remarks:
	\\\\\Yes \ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Drum (200 lts) provided for curing in each flat?
ad	☐ Good NAvg. ☐ Bad	Storage of building material like bricks sand and cement.
Low	High Medium	Wastage?
	No No	Is the Bungalow cleaned for plastering?
Cant' say	□Yes □No ₩	Was the Bungalow cleaned before starting brick work?
ad	Good YAvg. Bad	Condition of proportion box?
	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	Was 3.75 CFT proportion box provided?
		Misc. Checks.