	Quality Cor	Quality Control Check Repot.	Stage: After Brickwork (Villas)	vork (Villas)	
Bungalow No.	74	Others		CI NI	
Company	(411)100	Project		Dhan.	33248
Prepared by		7.10,000	Sov	Phase	মি
r repared by	S. Kuldeep	Sign	Filder	Date	377
Project Manager	K. Pushotham	Sign	P	Data	25/03/19
Previous stage report no.	S. 201 17 (1 12.11)	2001		Date	25/03/19
Bungalow No		Sec. 0	report fried and signed by FM?	d by FM?	Yes No
		Oniei		Other	
Checked By MD on		MD Sign		For Allina] (7
Recommendation:		(Smill for	L Yes L No
Stop further work.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by	port to QC team. Proce	ed only after recheck b	OC OC	
Proceed with furth	Proceed with further work only offer maline submitting ATR on QC report to QC team.	ter submitting ATR on	QC report to QC team.	, A	
Proceed with furth	Proceed with further work. ATR not required	ired.	out in the QC report.	ATR not required.	
Inspection should be done after	after:				

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed
- electrical conducting work is completed (except bathrooms).

Brickwork Check, Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked.
- Chicken mesh should be used in each and every joint between RCC & Brickwork. All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- Balcony sill level should be 3'3" from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- Specify the No. of beams which are not aligned by more than 1"in a room. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.
- Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 screws.

Ren	19	18	17	16	15	14	13	12		10	9	0 00	7	6	U	4	ب ر	2		S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace / balcony 2	Terrace/ balo	Lobby 2	Lobby-1	Dining	Drawing	Toilet-4	Bedroom 4	Toilet 3	Венгоот 3	Toilet 2	Bedroom 2	Toilet I	Bedroom 1	
8						cony 2	balcony I									ナ	4.8	3,4	Sin	
			(1	ζ.	1	!	1	1	j .	ζ	1	1	1	1	(<	ζ	ζ	Wall thickness
			<	1	<	,	1	1	i	1	((1	1	1	(5	7	١	Beds in walls (✓ or 🗙)
			<	1	7	1	1	1	1	1	([J	1	,	(7	ζ	7	Chicken mesh (• or ×)
			7	1:	<	!	1	1	(1	7	1	1	1	1	<	(5	7	External brickwork & beam joint (or x)
-			<	1		Ţ	!	1	i	,	7	1	(1	, ,	,	(ر ا	٢	Room Dimensions
		1	1	[1	1	!	1		·		1	; j			1	, <u> </u>		1	Room Dimensions Difference in inches
		7		1		1 1		1 1		1		()	1		, ,			((Diagonal (v or x)
		 			! !	1				1 1		\		1 1		(1	1 1		Diagonal Difference in inches
					1 1			[ĺ	1	١		1	1	1	, 1		1		Balcony sill level
		/	<u> </u>	+	1	!				K	1	\	1	į	(1	,	(Room Height
		Gwod		AVG	! !!	!	 -	!	1	avod	1	1	1	1	AUG	Gwod	-	Av9		Plumb of walls (Good/Avg./Bad)
		7	1	Ava)	1				7	١		1]	1	200	(200	a	Alignment of beams and walls - Nos.

Quality Control Check Repot. Stage: After Brickwork (Villas)

Specify rooms that need correction:	Quality of edges and corners in all rooms?
	☐ Good ☐ Avg. ☐ Bad

Chajjas Quality Check

Notes: Width of chajja should be 6"more than the width or the door or window

Door Frames & Windows check

- 1. Mark for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.

 Mark XX for major mistake that cannot be corrected.

 Window template depth should be between 2 to 2 ½ after plastering.
- Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 32" or 33" from SFL. (Tolerance 1") Slopes of lofts and kitchen platforms to be checked by using 12" spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

-	T_									ī —	Τ		Γ.	I _			Ι.			
Rem	19	18	-			14	13	12	1 1	10	9	8	7	6	2	4	S	2		S No
Remarks:	Other	Other	Kitchen	Portico	Head room	Terrace / balcony 2	Terrace/ balcony 1	Lobby 2	Lobby 1	Dining	Drawing	Toilet-4	Bedroom 4	Toilet 3	Bedroom 3		Bedroom 2 以完	Toilet 1 on.T	Bedroom 1 m.B	Room
			1	4	<	1	1	•	1	1	ζ	1	[ı	1	ζ	ζ	(Door size, face and
																				position (✓ or 🗙)
			(1	7	Ţ	1	İ	1	1	7	\	Ţ	1	1	(ς	ς		Brick at bottom of door frame10 (vor X)
		500	1	. [(1	ı			ļ	7	1	l	1	•	(1	٢	1	Door lentil level ⁶ (v or X)
		10	1	1	(•	Ţ	-	i		7		()	ļ	ς	1	ſ	۲	Door diagonal check ⁶ (v or X)
			-	1	(1	1	1	!	1	×	ı	(1	1	ζ.	,	ζ		Door Plumb - two sides (vor x)
			1	!	(ſ	1	ı	ļ	1	,	ı	{	1	1	(1	,)	Door frame black Japan/ wood primer/Peelambar check (vor X)
			(1	ĺ	1	1	1	•	-	(*	ſ	7	1		`	5		Windows lentil & sill level(✓ or 🗙)
			(1	1	1	1]	1]	(1	(1	1	ζ,	7	ζ.	,	Windows size (✓ or 🗙)
		(1		1	ı	1	!	1	(1	ţ	1	1	(ς	(,	Windows - template depth & diagnal ⁵ (✓ or X)
			`,	1	1	1	!	!	1	1	(1	1	1	<	۲	ς.	, 1	Windows - template powder coated ⁵ (v or
			Los	!		1	l	ı	1	1	١	1	1)	1	1	1	١	1	Loft & Kitchen platform required ? (Yes or No)
			(1	1	1	1	1	1		1	1	1	1	,	١	1	(1	Loft & Kitchen platform provided ⁸ (• or × or NA)
		,		ı	1	١	1	1	1	1	1	1	1	1	ţ	ı	١	1		Loft & Kitchen platform slope (✓ or 🗙)

Quality Control Check Repot. Stage: After Brickwork (Villas)

Quality Control Check Repot. Stage: After Brickwork (Villas)

Misc, Checks.		
Was 3.75 CFT proportion box provided?	Yes No	
Condition of proportion box?	☐ Good ☑ Avg. ☐ Bad	
Was the Bungalow cleaned before starting brick work?	☐ Yes ☐ No ☑ Cant' say	ay
Is the Bungalow cleaned for plastering?	Yes No	
Wastage?	☐ High ☐ Medium ☐ Low	
Storage of building material like bricks sand and cement.	☐ Good ☐ Avg. ☐ Bad	
Drum (200 lts) provided for curing in each flat?	☐Yes ☐No	
Remarks:		
Compound wall check		
CRS + bed - specified level below FFL:		Actual level below FFL:
Specified compound wall height above FFL:	41611	Actual level above FFL: u'-6
Quality and level of PCC on ground floor?		☐ Good ☐ Avg. ☐ Bad
Quality and level of PCC for portico?	And the second s	☐ Good ☑ Avg. ☐ Bad
Is leveling in the setbacks of the villa 6" below FFL?		☑·Yes □No
Is level marked on villa & compound wall with 2 screws, 2 ft above FFL?	ove FFL?	□Yes □No
Specified height of gate columns:	51-011	Actual height provided: 5'-0'
Specified distance between gate columns:	9-111	Actual distance provided: 91
Chicken mesh provided on external joints of villa (✓ or 🗙)		<
Parapet wall thickness, height and design (v or x)		<
Parapet and compound wall railing design quality, fitting & redoxide painting (✓ or ×)	oxide painting (vor x)	×
Remarks:		State of the state