Quality Control Check Repot. Stage: After Brickwork (Villas)	
	<b>uality</b>
	 Control
	Check
	Repot.
After	Stage:
	After
	k (Villas

Company Setche Construct Project Setche Foxing Phase
Posto Date
5557 Rep
Bungalow No Other Other
Checked By MD on MD Sign For filling Yes No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.

- Brickwork, CRS for compound wall, compound wall and gate pillars are completed
- chicken mesh fixed
- after cleaning the bungalow.
- external scaffolding tied.
- external brickwork & beam joints filling completed.
- electrical conducting work is completed (except bathrooms).

## Brickwork Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark X X for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4" and 6" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- 0. Diagonals of each room shall be equal. (Tolerance: 2")
- Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 13. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2") Check room height with specified height. (Tolerance: 1")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.
- Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.

Rei	19	2	5 5	17	6	15	14	13	12	11	10	9	∞	7	6	U		4	ω	2	_	S	No
Remarks	Other	Utility	TY:1:	Kitchen	Portiee	Head-room>	Terrace/balcony-2	Terrace/balcony-l,	Lobby-2	Lobby 1	Dining-	Drawing	Toilet4	Bedroom-4	Forlet's	Bedroom	5	1	om 2 A	Toilet 1 M. Toi	Bedroom 1 M. Bloo		Loom
				7	1	1	1	1	1	5	1	5	1	1	!	]		(	1	7	1		Vall thickness  ✓ or ×)
				ς.	١	)	)	1	)	5	1	ς	1	]			J	(	×.	×	×	300	Beds in walls or x)
				7	١	1	١	1	1	ς	1	5	1	1	1	1	,	×	(	1	5		Chicken mesh
				<	1	)	)	)	1	<	1	5	1	j	!		)	(	<	(	5		External brickwork & beam joint (  or
				3	1	1	1	1	1	<	1	3	1	1	1		1	5	5	<	(	]	Room Dimensions ( • or ×)
				1	1	1	1	)	1	1	1	-	1				)	1	1	1	1		Room Dimensions Difference in inches
				<	1	1	١	1	1	13	, 1	<	, 1		,		1	<	(	<			Diagonal (• or ×)
				1	1	J	)	1	)	1	1	1	1		)	1	)	1	î	١	1		Diagonal Difference in inches
				<	1	1	1	1	1	1	-	1	1		1	1	1	1	1	1			Balcony sill level
				)	1	1		)	)	1 (	< 1	(		1	)	1	J	<	<	<	,	<	Room Height ( • or ×)
				MVB	- 1	1	1	1			-	1	=	1	1	1	1	11	11	-		41/9	Plumb of walls (Good/Avg./Bad)
				L			-	1	)	1	1	1	-	1	)	J	1	1	1		1	1	Alignment of beams and walls - Nos.

Ouality Control Check Repot. Stage: After Brickwork (Villas)

	Specify rooms that need correction:	Quality of edges and corners in all rooms?	Chamity Country of Circ
	1	Good Avg. Bad	CN INC DOM

Chajjas Quality Check
Notes: Width of chajia should be 6"more than the width or the door or window.

				Remarks
				1 -
1	1		1	10
Height in correct - mos	Width incorrect - nos.	Thickness incorrect –nos Width incorrect - nos.	Slopes incorrect – nos.	Total Nos. of Chajjas Slopes incorrect – nos.
TT: 1.1 in commont mon		TOOL OF THE PARTY	Notes: Width of challa should be of mole man the width of the cool of mines.	Notes: width of chaffa should

## Door Frames & Windows check

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 1/2" after plastering.
- Lentil level should be 7'3" from SFL & 7' from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 32"or 33" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

Rer	19	18	17	16	15	14	13	12	=	10	9	∞	7	6	S	4	w	2	-	S No
Remarks:	Other	Other	Kitchen	Pertico-	Head-room>	Ferrace/balcony-2	Terrace/balcony-1	Lobby 2	Lobby Lobby	Dining	Drawing	Toilet 4	Bedroom 4	Toilet-3,	T	Toilet 2 C. Toi	Bedroom 2 G. Be	Toilet 1 M. Toi	Bedroom 1 M. Bcd	Room
			A	١	1	(	1	1	1	1	5	١	J	}	1	٢	٢	۲		Door size, face and position ( • or ×)
			1	١	1	1	١	1	1	1	1	1	1	1	1	5	(	٢		Brick at bottom of door frame10 (✓ or X)
			1	1	١	1	1	1	1	-	<	١	)	)	1	(	<	٢	(	Door lentil level <sup>6</sup> ( • or ×)
			(	1	1	-	1	1	1	-	<	1	1	1	1	(	5	٢	7	Door diagonal check <sup>6</sup> ( • or ×)
			1	1	1	1	1	l	1	1	<	-	J	1	1	(	(	(		Door Plumb - two sides (✓ or 🗙)
			1	Ţ		1	1	1	-	1	X	١		١	١	(	1	1	1	Door frame black Japan/ wood primer/Peelambar check ( or x)
			7	1	-	1	1	1	<	1	1	1	1	1	)	١	7	(	1	Windows lentil & sill level( ✓ or 🗙)
			<	1	1	1	)	)	<	1	(	_	1	1	١	<	(	(	1	Windows size (✓ or 🗙)
			7	1		(	(	1	ζ	1	××	10	1	1	1	7	(	<	(	Windows - template depth & diagnal⁵ (✓ or 🗙)
			×	1	)	J	1	)	×	1	(	1	1	1	1	X	×	×	X	Windows - template powder coated <sup>5</sup> (✓ or 🗙)
			Zo	1	1	1	١	1	1	1	1	ſ	)	ı	]	1	1	1		Loft & Kitchen platform required ? (Yes or No)
			ZP	1	1	1	1	1	,	1	(	1	1	1	1	1	(	1	1	Loft & Kitchen platform provided <sup>8</sup> ( ✓ or X or NA)
			١	1	1	)	١	1	١	1	1	١	)	)	1	1	1	1		Loft & Kitchen platform slope (✓ or X)

## Quality Control Check Repot. Stage: After Brickwork (Villas)

Misc. Checks.		
Was 3.75 CFT proportion box provided?	Yes No	
Condition of proportion box?	Good Avg. Bad	
Was the Bungalow cleaned before starting brick work?	☐Yes ☐No ☐ Cant' say	ау
Is the Bungalow cleaned for plastering?	☐Yes ☐ No	
Wastage?	☐ High ☐ Medium ☐ Low	
Storage of building material like bricks sand and cement.	Good Avg. Bad	
Drum (200 lts) provided for curing in each flat?	☐Yes ☐ No	
Remarks:		
Compound wall check		
CRS + bed - specified level below FFL:  Specified compound wall beight above FFI:	マガ	Actual level below FFL:
Specified compound wan neight above FFL.	27	Actual level above FFL.
Quality and level of PCC on ground floor?		Good Avg. Bad
Quality and level of PCC for portico?	not done	☐ Good ☐ Avg. ☐ Bad
Is leveling in the setbacks of the villa 6" below FFL?		Yes No
Specified height of gate columns:	رار . ت	Actual height provided: 6-c
Specified distance between gate columns:	W I I	Actual distance provided: 195
Chicken mesh provided on external joints of villa (✓ or 🗙)		5
Parapet wall thickness, height and design (✓ or 🗙)		5
Parapet and compound wall railing design quality, fitting & redoxide painting (	loxide painting ( • or ×)	1
Remarks:		

0