The state of the s	Quality Control Check Repot.	
	Stage: After Finishing Stage II (Apartments)	

Inspection should be done after:

- Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint. Completion of windows, grills, electrical wiring, switches must be done in next stage
- False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided.
- Provide granite soffit for main door and balconies in this stage.

## Miscellaneous check:

False ceiling to be provided?	Main door granite soffit workmanship Good Main door granite soffit edge polishing	Granite soffit for main door required ☐Yes ☐ No	Balcony granite soffit workmanship Good Avg Poor Balcony granite soffit edge polishing	Granite soffit for balcony required	Main door fixed with lock & stopper  Yes  No
Yes No	☐ Good ☑ Avg ☐ Poor	Yes No	Good Avg Poor	☐Yes ☐No	TYes No
False ceiling workmanship	Main door granite soffit edge polishing	Granite soffit for main door provided Yes No	Balcony granite soffit edge polishing	cony provided	Stoppen not fitted.
☐ Good ☐ Avg ☐ Poor	☐ Good ☐ Avg ☐ Poor	☑:Yes ☐ No	☐ Good ☑ Avg ☐ Poor	☐Yes ☐No	

	Rer	9	∞	7	6	S	4	ယ	2	Н	S No	
	Remarks	Other	Other	Utility	Kitchen	Wash basin dining area	Foffet 4	Foilet 3	Toilet 2	Toilet 1	Room	Tiling & granite work
	Provisi ex					in in	904	Marie Marie	Cital	Mitai		granite
10 0000 NORTH	,			۲	1	1	1	!	ζ	ς	Workmanship of tiling	
	for madulas xit				1	Ţ	1	1	a'	88	White cement filling around CPVC lines	
3	ladivila			234	1	Ţ	1	١	(	۲	Corners finishing	Rate the
	99 15			(	}	1	1	1	<	۲	Finishing near doors	Rate the quality of (Good ✓, Avg. X, Poor
				5	1	1	1	1	<	ς.	Finishing on top of tiles	of (Good
	7,000			1	1	1	1	١	/	/	Finishing near ventilators	l v, Av
				ς	1	1	1	(	۲	(	Step at bathroom entrance / utility	g. X, Po
				ζ		1	1	1	<	ς.	Step for shower / pot wash	oor – nec
				Х	1	1	-	ſ	e <sup>c</sup>	•	Tile joint grouting	- needs correction <b>XX</b> , NA)
	2.			1	1	1	1	1	5	ζ	Granite platform finishing and edge polishing	ction X
				1	1	1	ļ		<	ζ	Granite platform slope	X, NA)
					١	1	١	1	(	(	Granite platform height	
				)	)	)	,	١	k	×	Finishing under granite platform	

Page	
$\omega$	
of $3$	

	12	=	10	9	8	7	6	5	4	သ	2	<u> </u>	S No	
Remarks	Other	Other	Kitchen	Utility/balcony-3	Utility / balcony 2-	<del>Utility</del> / balcony 1	Lobby 1—	Dining	Drawing	Bedroom 3 Grae	Bedroom 2 K-Bed	Bedroom 1 M.Beo	Room	Flooring & painting
			7	J	<	1	Į	1	7	ς.	۲	7	Color variation of floor tiles	
			?	1	<	(	1	)	ς	(	٠.	ς	Flooring workman ship & grouting	
			ς	١	ς	(	1	1	ţ	ζ	ς.	ζ	Skirting size (3")	Rate
			<	1	ζ	ζ	-	1	(	(	(	(	Skirting workmanship	Rate the quality of (Good
			<	١	<	ζ	1	1	ς	(	ζ	<	Plastering above skirting	ty of (Go
	8		(	1	ς	ζ	1	1	ζ	<	(	7	Plastering & finishing of walls	od ∨, Avg.
			(	1	<	ζ,	-	1	<	ζ,	ς.	ς.	Crack filling	×
			1.	ļ		3	1		1	1	)	)	Loft Finishing	oor – nee
			ζ	1	ς	<	1		<	<	<	ς	General quality of painting & finishing	ds correct
		4040	I	General Control of the Control of th	ς			1	<	3	′	(	Door & frame painting quality	Poor – needs correction <b>XX</b> , NA)
			1	1	<	1	1	I	ζ	(	,	5	Door beading, luppam and painting quality.	, NA)
			ζ	)	У.		}	)	<	ί	(	ζ	Edge building	