## Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

Project  Phase  Phase  Sign  Nedworder  Sign  Nort no.  Nort nort no.  Nort not required.  Nort not required.	Flat No	υ <sup>1</sup>	Other	Sl. No.	31135
Sign  Notwork  Sign  Notwork  Sign  Notwork  Sign  Date  Ort no.  Sign  Notwork  Sign  Notwork  Sign  Notwork  Report filed and signed by PM  Report filed and signed by PM  MD Sign  MD Sign  MD Sign  Report filed and signed by PM  For filling  rk. Submit ATR on QC report to QC team. For filling  ork. Proceed with work after submitting ATR on QC report to QC team.  urther work only after making corrections pointed out in the QC report. ATR not required.  urther work. ATR not required.	Company	Milgin estantes	Project	+	=)
ort no.  Sign  ACV 5 3  Report filed and signed by PM  MD Sign  MD Sign  MD Sign  Report filed and signed by PM  For filling  For filling  ork. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  ork. Proceed with work after submitting ATR on QC report to QC team.  urther work only after making corrections pointed out in the QC report. ATR not required.  urther work. ATR not required.	Prepared by	P. In Kun	Sign	↓	21/8/11
ort no.  3C153 Report filed and signed by PM  MD Sign For filling  rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  ork. Proceed with work after submitting ATR on QC report to QC team.  urther work only after making corrections pointed out in the QC report. ATR not required.  urther work. ATR not required.	Project Manager	Madhimaker	Sign	Date	11/8/11
MD Sign  For filling  rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  ork. Proceed with work after submitting ATR on QC report to QC team.  urther work only after making corrections pointed out in the QC report. ATR not required.  urther work. ATR not required.	Previous stage report	no.	30153	Report filed and signed by PM	N Yes No
ork. Submit ATR on QC report to QC team. Proceed only after recheck by Qork. Proceed with work after submitting ATR on QC report to QC team. Further work only after making corrections pointed out in the QC report. ATF urther work. ATR not required.	Checked By MD on		MD Sign	For filling	□Yes □No
	Recommendation: Stop further work. Stop further work Proceed with furth Proceed with furth	Submit ATR on QC re. Proceed with work aff her work only after mak her work. ATR not requ	port to QC team. Proter submitting ATR of the corrections point ired.	oceed only after recheck by QC. on QC report to QC tcam. led out in the QC report. ATR not required.	,

- Completing stage II works.
- Complete works like windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:
   Window grills must be fitted at the depth of ¼" from the wall.
   Switchboards must be fitted to plum.
- Cover jurction boxes with cement covers and not PVC covers. Use pin head type sheet metal screws (not MS).

## Miscellaneous check:

Video door phone to be provided Yes		Modular kitchen workman ship	Modular kitchen to be provided Yes	
⊠Yes □No	1	od Avg Poor   ]	☐ Yes ☑No	)
Video door phone provided	workman ship & finishing	☐ Good ☐ Avg ☐ Poor   Modular kitchen granite & dado	Modular kitchen provided	
☐ Yes ☐ No	***	Good Avg Poor	□Yes □No -	

## Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

T				100	10,000	109	
	Remarks:	Quality and workmanship of lawn	Cleaning/painting of external cladding/texture	Painting of gates & railings	Quality and workmanship of railings	Quality and workmanship of gate	MISCELLATIEOUS CHECK — After thristling stage III
		Good Avg. Poor	Good Avg. Poor	☐ Good ☐ Avg. ☐ Poor	☐ Good ☑ Avg. ☐ Poor	Good Avg. Poor	