	P
	ЯШП
	Control Check Repo
	2
	nec
	Kepot.
	Sta
	itage: After Fil
3	Añ
	er]
	3
	ishin
	S
	tagg
	lg Stage III (
ł	?
	illas
ŀ	_

Project Sign Sign And Sign And Sign And Project Project And Project Project And Project Project Project And And And And And And And An	Flat No	1 7	Other		CI No	
Sign Sign Nilgin astrolic Phase Sign Nilgin astrolic Phase Sign Nilgin astrolic Phase Date All Mall Date All Mall Date The Mall Date All Mall Date MD Sign MD Sign MD Sign Report filed and signed by PM For filling Ceed with work after submitting ATR on QC report to QC team. ork only after making corrections pointed out in the QC report. ATR not required.		45	(DI. INO.	30+39
Sign Sign Nimbel Date Date Coed with work after submitting ATR on QC report to QC team. Proceed out in the QC report. ATR not required.	Company	Milgin estales	Project	Vilson of a	Phase	
Sign Carry 995 Report filed and signed by PM MD Sign MD Sign MD Sign For filling Ceed with work after submitting ATR on QC report to QC team. ork only after making corrections pointed out in the QC report. ATR not required.	Prepared by		Sign	TUG	Date	81(+17
MD Sign MD Sign Report filed and signed by PM For filling mit ATR on QC report to QC team. Proceed only after recheck by QC. ceed with work after submitting ATR on QC report to QC team. ork only after making corrections pointed out in the QC report. ATR not required.	Project Manager		Sign	Sharley -	Date	x=4\cdots
mit ATR on QC report to QC team. Proceed only after recheck by QC. ceed with work after submitting ATR on QC report to QC team. ork only after making corrections pointed out in the QC report. ATR not required.	Previous stage report	no.	508tz	Report filed and signe	d by PM	NYes No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Inspection should be done after:	Recommendation: Stop further work. Subjection Should be done after the specific should be done after the stop of	Submit ATR on QC rep Proceed with work after cr work only after making work. ATR not required	port to QC team. Proceer submitting ATR on ng corrections pointed red.	eed only after recheck b QC report to QC team. I out in the QC report.	y QC. ATR not required.	

- Completing stage II works.

 Complete works like doors, windows, grills, electrical wiring, switches, french door glass, etc.
- In case of modular kitchen provide platform, granite and dado and modular kitchen in this stage.
- Provide video door phone in this stage.
- Possession for wood work cannot be given until QC check for stage III is completed and all corrections mentioned in the report are made.

- Stage III check notes:

 1. Window grills must be fitted at the depth of 1/2" from the wall.
- Switchboards must be fitted to plum.

 Cover junction boxes with coment covers and not PVC covers. Use pin head type sheet metal screws (not MS).

Miscellaneous check:

video door phone to be provided	17:1	Modular kitchen workman ship	Modular kitchen to be provided
Yes	- Contraction of the contraction	Good Avg Poor	☐Yes WNo
Video door phone provided	workman ship & finishing	Good Avg Poor Modular kitchen granite & dado	Modular kitchen provided
\\\Yes \ \No		Good Avg Poor	□Yes □No

Quality Control Check Repot. Stage: After Finishing Stage III (Villas)

Remarks:	Quality and workmanship of gate Quality and workmanship of railings Painting of gates & railings Cleaning/painting of external cladding/texture Quality and workmanship of lawn
	Good Avg. Poor