Quality Control Check Repot. Stage: After Finishing Stage II (Apartments)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by S.	Company	Flat No
bmit ATR on QC recoceed with work aft work only after making work. ATR not require			T. Modhu	7	Vista Hames	0-301
port to QC team. Procer submitting ATR on ing corrections pointedired.	MD Sign	38677	Sign	Sign	Project	Other
		Report filed and signed by PM	Manden	- JE	Vista Homes	
by QC. n. ATR not required.	For filling	ed by PM	Date	Date	Phase	Sl. No.
	☐Yes ☐No	Yes No	8813/19	28/2/19		33281

- Inspection should be done after:
 Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint.
 Completion of windows, grills, electrical wiring, switches must be done in next stage
 False ceiling must be completed before flooring.
- Kitchen platform, granite and dado must be completed where modular kitchen is not provided. Provide granite soffit for main door and balconies in this stage.

Miscellaneous check:

☐ Good ☐ Avg ☐ Poor	False ceiling workmanship	☐Yes ☐No	False ceiling to be provided?
	polishing		
Good Avg Poor	Main door granite soffit edge	☐ Good ☐ Avg ☐ Poor	Main door granite soffit workmanship Good Avg Poor Main door granite soffit edge
Yes No	Granite soffit for main door provided ☐ Yes ☐ No		Granite soffit for main door required Yes No
☐ Good ☐ Avg ☐ Poor	Balcony granite soffit workmanship Good Avg Poor Balcony granite soffit edge polishing Good Avg Poor	☐ Good ☐ Avg ☐ Poor	Balcony granite soffit workmanship
Yes No	Granite soffit for balcony provided	☐Yes ☐No	Granite soffit for balcony required
		Yes No	Main door fixed with lock & stopper Yes No

	Remarks	9	∞	7	6	2	4	ယ	2		S No			
	Other	Other	Utility	Kitchen	Wash basin in dining area	Toilet4	Toilet-3-,	Toilet 2 (2, 70)	Toilet 1 M. Control	Room	Tiling & granite work			
	100 7	8 8		()	1	1	1	<	3	Workmanship of tiling			
	for modulier Kit			()	J	j	}	7	ς	White cement filling around CPVC lines			
	外天子			(1	1	i	1	×	ζ	Corners finishing	Rate th		
				(1		1	}	<	(Finishing near doors	e quality		
			5 1 1	1	١]	((Finishing on top of tiles	Rate the quality of (Good ✓, Avg. X, Po				
				1	١)	Ì)	(ζ	Finishing near ventilators	d √ , A₁		
				ζ	1	١	1	1	(~	Step at bathroom entrance / utility	/g. × , F		
				ζ	Í	1)	}	/		Step for shower / pot wash	oor – ne		
				×		1	1)	<	ζ	Tile joint grouting	eds corr		
)	Granite p and edge		Granite platform finishing and edge polishing	ection X					
				1	1)	1	1	1	Í	Granite platform slope	or – needs correction XX , NA)		
))	}	J	1	1	Granite platform height
				١	1,	J)	J	})	Finishing under granite platform			

Г			_			-	1	100.7		r —			1		T	
			12	11	10	9	∞	7	6	Ŋ	4	w	12	_	S No	
	7	Remarks	Other	Other	Kitchen	Utility-/-balcony-3	Utility / baleony-2-	Utility/balcony 1	Lobby-1-	Dining	Drawing	Bedroom 3 & Bear	Bedroom 2 Krbe	Bedroom 1 M. Bed	Room	Flooring & painting
	t	The state of the s		22	(1	<	5	f	1	ς	ς.	(5	Color variation of floor tiles	
					<	1	<	(1	((ς	5	Flooring workman ship & grouting	
					(١	<	ς	١	1	(ζ	<	(Skirting size (3")	Rate
a	2				<	4	ζ	ζ	1	-	((አ	(Skirting workmanship	Rate the quality of (Good
					ς	1	ζ	ζ		1	((ς	<	Plastering above skirting	ty of (Go
i					(1	ζ	<	1	I	ζ	((<	Plastering & finishing of walls	ζ.
					1	1	<	4)	1	ζ	<	ζ	<	Crack filling	Avg. X, P
					(•)	1	1	•	1	l	1	}	Loft Finishing	oor – need
	۵				ζ	1	ζ	5	7		〈	ζ	〈	ζ	General quality of painting & finishing	ls correcti
					1	1	<	1	-		ζ	ζ	ζ	<	Door & frame painting quality	Poor – needs correction XX, NA)
)]	く	1	1	9	<	ζ	<	ζ	Door beading, luppam and painting quality.	NA)
		X.			<)	×	<))	X	X	<	X	Edge building	