	ATR	ATR on Quality Control Check Repot.	heck Repot. Dungarows		
				SI. No.	2226
Bungalow No	35%	QC report stage	After Backwell	Dhase	
	A KOK	Project		I Habe	
Company	VOC 11.4			Date	m/02/12
Prepared by	so de la Francisco Francis	Sign	Que Ra		
Project Manager	0 0	Sign	ر کے	Date	10/08/19
Donaint har OC data	A Character	Sign		Other	210-11
Trecorde of Security		(
Receipt at HO date		Sign		Other	1
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation that was made by QC: Stop further work. Submit ATR on Q Stop further work. Proceed with wor	t was made by QC: Submit ATR on QC re Proceed with work af	eport to QC team. Proc ter submitting ATR on	Recommendation that was made by QC: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team.	y QC.	

- Attach a copy of the QC report to this sheet.

 Circle each correction with a red pen tick (*) each circle for work completed and cross (*) each circle where work has not been completed. Give remarks for each case where work has not completed on this sheet.

 Make 2 copied of the ATR send one to MD and other to QC.

- Enclose required photographs hard copy.

All woolk	Remarks:
All wolks are completed	

,		Ton -1- Danot	Stage: After Brickwork (Villas)	ork (Villas)	
	Quality Cor	Quality Control Cneck Nepot.		CI NO	23361
- INo	776	Others		1	
Bungalow No.	122	Designat	- Jn c	Phase	
Сотралу	mc (LLA)	Project	400	Data	08 104 19
Dancard by	o v. Idas	Sign	A STATE OF THE STA	Date	
Tichmonol	0.700	Cim		Date	1,1 40/80
Project Manager	A-susush	TRIC	77	d by DM9	Cyes No
Previous stage report no.	10.	32754	Report filed and signed by I ivi	St by Live:	
Part No.		Other		Other	
Bungalow Ivo				הביי מוויהה	☐ Yes ☐ No
Checked By MD on		MD Sign		For mung	
Recommendation:		į		}	
Stop further work.	Submit ATR on QC re	eport to QC team. Proc	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.	by QC.	
Stop further work.	Proceed with work af	ter submitting ATR or	Stop further work. Proceed with work after submitting ATR on QC report to QC team.	•	
Proceed with furthe	r work only after mak	ing corrections pointe	Proceed with further work only after making corrections pointed out in the QC report. ATR not required	ATR not required.	
Proceed with further	Proceed with further work. ATR not required.	ired.	1		

external brickwork & beam joints filling completed. external scaffolding tied. after cleaning the bungalow. chicken mesh fixed Inspection should be done after.

Brickwork, CRS for compound wall, compound wall and gate pillars are completed

Mark ν for correct or minor mistake which does not require correction

Notes:

Brickwork Check

electrical conducting work is completed (except bathrooms).

Mark XXX for major mistake that cannot be corrected.

- Mark X for minor mistake that requires minor correction. Mark XX for major mistake that requires correction by replacement of re-fixing.

- Wall thickness should be as per plan. Use of 4"and 6"blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC. Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Diagonals of each room shall be equal. (Tolerance: 2") Check room dimensions with working plan. (Tolerance: 1")

- 11. Balcony sill level should be 3'3" from SFL. (Tolerance: 2")

 12. Check room height with specified height. (Tolerance: 1")

 13. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")

 14. Specify the No. of beams which are not aligned by more than 1"in a room.

 15. Door frames must have black Japan coating and wood primer / pellambar at cost

 17. Mark a line 2ft above FFL. on the Line."
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

 Setbacks must be leveled atleast 6" below FFL of setbacks to ensure plastering is 6" below FFL.

 Mark a line 2ft above FFL on the building, compound wall and road face of compound wall. Affix 2 scrows.

Page 1 of 5

		Kemarks	D Other	+			16 Portico		-	13 Terrace/ balcomy	1.2 Labby 2	-	dumin 1		n Follet 4	' Bedroom	c toner o	Dedroom.	4 Toilet 2	_		1 Bedroom	S No Room
								₽,	Terrace / baleony 2 ·	rateony i		Haria.			******	4	6.7	١٠	1	n2 K.B	3	n l .m·8	
				<	1	1	,		۲	,		•		,	,	1	,	,	,	,	<	(Wall thickness
			ľ	(1	1	1	1	1	٢	٠,			*	*	1	,	<	•	1	K	,	Beds in walls
			1		•	1	1	4	•		•	,			1	1	(1	1	9	1	1	Beds in walls (or x) Chicken mesh (or x) External brickwork & beam joint (or x)
			1		1	1	(Ś	: ;	,	٠,	į	1		ļ	ī	Ç	1	(5	′		External brickwork & beam joint (v or
			<	1		1	<	1	8		٢		, ,	1	1	1	<	,	<	\	Κ	5	Room Dimensions
			1	1	1		1	i	!	!	.!			1	1	1	1	•	}	1	,	١	Room Dimensions Difference in inches
			<	5	1	<		Į.	ς.	1	۲.	,	1		1	ı	~	<					Diagonal (v or x)
			,	1	1				\$	•	į	1	1		1	1	1	1	,	1	,	1	Room Dimensions Difference in inches Diagonal (• or ×) Diagonal Difference in inches
		1		1	1	!	!		5	ı	1	1	1	1		1	1	ı	1	1	,	1	Balcony sill level
		<	1		!	1	!	1	٠	[]	ŗ	1	1	,		,	((((1	Room Height
	4	Aug	COOR	-	1	Good	428	2000		1	Ewo d	ے ا	Ava	1		,	0	AwQ	Ava	Gran	Aug	₹.	Plumb of walls (Good/Avg./Bad)
	-	Aid	47.0		\rightarrow	pup	,	1	1	1	۲	10	Ava				, ,	Ava	<	,	5	7	Alignment of beams and walls - Nos.

	Remarks	40	Chajjas Quality Check Notes: Width of chajja should be 6"more than the width or the door or window. Total Nos. of Chajjas Slopes incorrect – nos. Thickness i	Specify rooms that need correction:	Quality Co Quality Co Quality of edges and corners in all rooms?
•		<	Slopes incorrect – nos.	ection:	Quality Control Check Repot. in all rooms?
		(oor or window. Thickness incorrect -nos. Width incorrect - nos.		
		1	Width incorrect - nos.		Stage: After Brickwork (Villas) Good Avg. Bad
		,	Height in correct - nos		

Door Lannes & Windows check

- Mark > for correct or numer mestake which does not require correction.

 Mark X for numer mistake that requires entrection, by replacement or re-fixing.

- Ntark X X for major mistake that cannot be corrected.

 Window template depth should be between 2 to 2 ½"after plastering.

 Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")

 Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from SFL and 32"or 33" from SFL. (Tolerance 1")

 Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.

- 10. Provide single layer table brick at bottom of each door frame without threshold.

Do Roung N painined on Insact.	1 3	Parapet wall thickness, height and design (v or X)	(v or x)		Specified height of gate columns:	Is level marked on villa & compound wall with 2 screws, 2 $\%$ above FFL?	Is leveling in the sethacks of the villa 6" below FFE?	Charles and level of the bottler?	Specified companied Will neight access or a	CRS bed specified level relieve 1111	Compound wall check	Remarks:	[X 100	f building material like bricks sand and cement.	High Medium	- 1	Good No	Misc. Checks. Show provided? Yes No	Quality Control Check Report. Stages	ctore: After Brickwork (Villas)
	×	<	×	hol-D" Actual	2.16" Actual heigh	L Yes	k. Yes	1 1	Good	Actual level :	Actual				Low		Cant' say			(Villas)
				Actual distance provided: 11 5 11	neight provided: 2 L 5'1	LNo		1 Avg. Bud	Ik Avg. [] Bad	evel above FPL:	Actual level below FFL:									