ATR on Quality Control Check Repot. (Bungalows)

Bungalow No	107	QC report stage	<i>II</i>	Sl. No.	33338				
Company	Hilgiri Edatu	Project	Nilgiri Estatus	Phase	$\widehat{\mathcal{I}}$				
Prepared by	9kHEEL	Sign	701 01	Date	29/05/2019				
Project Manager	Madhusudhan	Sign	W. W.	Date	29/05/2019				
Receipt by QC date		Sign		Other					
Receipt at HO date		Sign		Other					
Checked By MD on		MD Sign		For filling	Yes No				
Recommendation that was made by QC:									
Stop further work.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.								
Stop further work. Proceed with work after submitting ATR on QC report to QC team.									

Notes:

- 1. Attach a copy of the QC report to this sheet.
 2. Circle each correction with a red pen tick () each circle for work completed and cross () each circle where work has not been completed.
 3. Give remarks for each case where work has not completed on this sheet.
 4. Make 2 copied of the ATR send one to MD and other to QC.

- 5. Enclose required photographs hard copy.

works	completed	which	cure	mentioned	a.	bendina
· ·	/					Paris A
	4					
	. 1					
	sdrow.	· ·	C.	C.	CC ,	C.

Page 1 of 1

Flat No				trette de la constitución de la					
	107	Other	1	Sl. No.	33338				
Company	Nilgini Est	Project	1 - 1 1	Phase	I				
Prepared by	V. Sanketh	Cian	Nilson Estatis	Date	04/04/19				
Project Manager	Carinina	Sign	V. Soukoth	Date	04/04/19				
Previous stage report	no.	32909	Report filed and sign	ed by PM	Yes No				
Checked By MD on		MD Sign		For filling	Yes No				
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required. Inspection should be done after: Completion of flooring, bathroom /utility tiles, doors & beading, first coat of paint. Completion of windows, grills, electrical wiring, switches must be done in next stage False ceiling must be completed before flooring. Kitchen platform, granite and dado must be completed where modular kitchen is not provided. Provide granite soffit for main door in this stage.									
Miscellancous check:	10.								
Main door fixed with l		Yes No							
Granite soffit for main		Yes No	Granite soffit for main	door provided	Yes No				
Main door granite soffi	it workmanship	Good Avg Poor	Main door granite sof	Good Avg Poor					

Stage: After Finishing Stage II (Villas)

Quality Control Check Repot.

Flat No

Page 1 of 4

Certified that all corrections mentioned in the QC report have been completed.

Work can proceed to next stage.

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

	Tiling & granite work		Rate the quality of (Good , Avg. X, Poor – needs correction X X, NA)											
S.No	Room	Workmanship of tiling	White cement filling around CPVC lines	Corners finishing	Finishing near doors	Finishing on top of tiles	Finishing near ventilators	Step at bathroom entrance / utility	Step for shower / pot wash	Tile joint grouting	Granite platform finishing and edge polishing	Granite platform slope	Granite platform height	Finishing under granite platform
1	Toilet 1 MT	1 1	1	X	Y.	/_	X	✓	1	X				<u></u>
2	Toilet 2 CT	√	X	~	<u> </u>		14.	~		√			<u> </u>	
3	Toilet 3			<u> </u>	*****	75	~_/							
4	Toilet 4		~	<u>.</u> .				,		-		j		-
5	Wash basin in dining area	~-	-		•1-		* ** **		-	,		i		•
6	Kitchen	V	✓	34.	,,,,	/	У.		in tree	~	.5	✓	1	1
7	Utility		~	X	X			7		-				
8	Portico													
9								63					1	
R	temarks												1	J
-			4				- 4							
-			•											

Page 2 of A

Quality Control Check Repot. Stage: After Finishing Stage II (Villas)

	Flooring & painting		Rate the quality of (Good \vee , Avg. \times , Poor – needs correction $\times \times$, NA)										
S No	Room	Color variation of floor tiles	Flooring workman ship & grouting	Skirting size (3")	Skirting workmanship	Plastering above skirting	Plastering & finishing of walls	Crack filling	Loft Finishing	General quality of painting & finishing	Door & frame painting quality	Door beading, luppam and painting quality.	Edge building
1.	Bedroom 1 MT3	~/			~	~ ·	7	1	7	√ 	\ \ \ \ \ \	O V	χ.
2.	Bedroom 2 KB	✓	~	√ ·	./		~	√ ✓	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	√ √	~_	- -	/.
3.	Bedroom 3				_		~~~		Ž		7		
4.	Bedroom 4				-		~			-	_		_
5.	Drawing	~	.≅√	./	~/	✓	J	/	سن	✓	1	~	.,
6.	Dining	~	-5	J	√	/	>/	~	4	~	~		X
7.	Lobby 1		-	-			~~		_				×
8.	Lobby 2	~.										·-·	
9.	Terrace/ balcony 1	₽ PROPE	~-										
10.	Terrace / balcony 2	~	^				_	_		_			
11.	Head room	✓.	~		XX	1	V	√	_	√			
12.	Portico	~	J	_		1	√	1		√ √	~~~		X.
13.	Kitchen	~	V		_ ✓	~	√	X					X
15.	Utility	- V		1	J	5	1	4		~			*
	Other							~		\checkmark	7	X	X
Rema	IKS A Skir	tion a	iece n	ot laid	Lat	11 1							
		- C Y	The state of the s	ac lan	1,00	ttead	Swm.						

Page 3 of 4

Quality Control Check Repot. Miscellaneous check – after finishing stage II Quality and workmanship of portico tiles Quality and workmanship of flooring & setbacks Quality and workmanship of external cladding/ texture Remarks:	Stage: After Finishing Stage II (Villas) Good Avg. Poor Good Avg. Poor Good Avg. Poor