## Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	200	no.	X. Noverblan Red Sign	M. Tegasvidher Sign	NET!	18
port to QC team. Procester submitting ATR on ing corrections pointedired.	MD Sign	25063	Sign	Sign	Project	Stage
eed only after recheck l QC report to QC team l out in the QC report.		Report fixed and signed by PM?	Copal-	Q1	NF-II	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐Yes ☐No	☐Yes ☐No	t(1+0/81	t1/40/81		26908

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.

  Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Rem	19	18	17	16	15	14	13	12	11	10	9	∞	7	6	S	4	ယ	2	1	S No
Remarks	Other	Utility	Kitchen	Portieo	Head-room	Terrace/balcony 2	Terrace/-baleony 1	Lobby 2	Lobby 1	Dining	Drawing	Teilet 4	Bedroom-4	T <del>oil</del> et 3	Bedroom-3	Toilet 2 (cr)	2	Toilet 1 (MT)	Bedroom 1 (MB)	Room
		ſ	<	\	ĺ	1	1	1	1	く	<		1	1	ſ	<	<	<	<	Skirting Provision ( • or ×)
		1	<	١	1	1	1	1	1	1	<	١	1	1	1	<	<	<	<	Finishing around door frame ( v or x)
		1	<	1	1	(		1	1	<	<	1	١	1	<b>S</b>	<	<	<	5	Beams & columns finishing ( v or x)
		,	<	1	ſ	•	-		}	ſ	ſ	(	1	-	J	\	く	1	<	Finishing of lofts ( • or ×)
		•	<	\	1	1	١	{	j	<	<	1	1	j	J	<	<	<	<	Electrical junctions finishing ( v or x)
		1	<	(	١		1	,	1	<	<	(	1	ş	1	<	<	<	<	Window check ( • or ×)
		Ţ	<	١	ſ	1	1	١	}	(	(	1	ı	١	j	く	1	<	j	Tiles provision ( • or ×)
		1	<	l	1	1	1	1	1	١	J	1	١	1	j	<	(	<	١	Sink provision & size ( v or x)
		ı	1	1	1	1	ļ	١	}	1	<	١	ŗ	)	1	<	<	<	<	Grooves for door frames ( v or x)
		1	١	ſ	1	1	)	١	1	1	ı	١	١	1	ţ	1	1	١	}	Balcony & terrace sill top finishing 10(v.gr x)
į		4	1	(	ſ	١	١	1	1	1	}	1	١	}	1	1	1	1	1	Screeding in bathroom & utility ( • or ×)
		1	1	ı	١	J	1	1	}	١	J	١	)	١	}	1	!	1	1	Screeding in 6" above FFL? (✓ or 🗙)

## Quality Control Check Repot. Stage: After Plastering (Villas)

Remarks:	Plastering and finishing of chajjas ( v or x)	Plastering quality of parapet walls ( or x)	Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Plastering of compound wall & gate pillars ( • or x)	Overall quality of plastering?	Miscellaneous check
	<	<	NYes □ No		Good Avg. Bad	