Ľ	
2	
uality Control Check Repot.	•
IZ)
ΙĔ	
ΙĘ	
2	
	1
15	
C	-
ck Kepot.	
lê.	•
12	
ŀ	
ı	
V.	2
2	•
6	
	•
Œ	
	٥
)
ΙĚ	•
巨	
⋾	
	2
3	
E	
ř	
Stage: After Column Casting (Apartmen	
5	
12	
E	
æ	
S	,

Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No.
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. AT Proceed with further work. ATR not required.		no.	T. Marke	S. Sunil Kings	Vista Homes.	A-(401 Jo405) Column No.
eport to QC team. Proc ter submitting ATR on ting corrections pointed tired.	MD Sign	87818	Sign	Sign	Project)Column No.
eed only after recheck QC report to QC team I out in the QC report.		Report filed and signed by PM?	Marling	SK,	Visita Homes	96
by QC. ATR not required.	For filling		Date	Date	Phase	SI. No.
	☐ Yes ☐ No	Yes No	27/05/17	27/05/17	, , ,	87884

Columns Position Check. Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab. Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each in

Columns Position Check Plan enclosed?	2. Since said sometiment with Electrocold. Office each montest appearance with an entering military colour, and including military colour, and including military colours.
	Hon next to it.

Notes: Slab Dimensions Check.

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show location of sunken slab. Show inner dimensions of ducts and lift well. (Tolerance I")
- Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

TO MAKE THE TAXABLE TO THE TAXABLE T	Specified thickness of slab?	Slab Dimensions Check Plan enclosed?	2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention
	44	,	rrect dime
	Actual thickness of slab?	Yes No	nsion with red colour and mention actual
	4/2	,	dimension next to it.

Quality Control Check Repot. Stage: After Column Casting (Apartments)

350 20	Remarks:
Good Avg. Bad	Quality of infrastructure for curing.
	Is the pressure in the curing pipe more than 15' head?
a times	Frequency of curing in number of times a day (enquire from labourers)
60.0	Distance of tap from furthest distance that requires curing. (max permitted 100')
es No	Gunny bags used for column curing?
es No	Drum (200 lts) provided for curing?
es No	Bund size is less than 100 sft?
es No	Bunds for curing made on slab?
	Curing.
	Remarks:
☐-Yes ☐ No	Have 6 cubes each for columns and slab casted and numbered for testing?
1"	Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"
☐ Good ☐ Avg. ☐ Bad	Are the honey combs is slab and columns packed?
☐ High ☐ Medium. ☐ Low	Number and size of honey combs?
☐Good ☐ Avg. ☐ Bad	Quality of starters?
Good Avg. Bad	Quality of centering, rod bending and concreting?
	Quality of centering, rod bending and concreting.

Columns height, plumb, steel & level marking check.

- Mark v for correct or minor mistake which does not require correction

 Mark x for minor mistake that requires minor correction.

 Mark x for major mistake that requires correction by replacement or re-fixing.

 Mark x x for major mistake that cannot be corrected.

 Tolerance: Plumb 0.25".

かとろ Circle actual height of columns if level differs from specified height by more than 1".

No | Col No. | Col type | Height in ft | Steel () or Y

		Т	\neg			-		_										1	
17.	16.		1 .	17	12.	13 1.	10.		9 9	0 :	7	۷ :	νi	٠, ٠	ı i	٦ <u>-</u>	_		ONIG
)	١	1	,	١)	1	1	١	١)	1)	}	1)	,		-	Col No.
	Ca	Ca	Ca	G	C3	ر وو	CS	દ	65	C3	Ch	CA	CS	C 4	64	CA			Col type
્રે. જે. જે.	\$ -1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	8-71	824	8-7/2	275-8	21/2-8	0,-230	8-412	8-4/2	3-7/2	8-112	8-47	12-A	8-A12	8-42	8-41	51,	Spec.	Heigi
or-	10 E-8	مم	874	12.27	A-A-	رهی	8-A10	8-4	8-4	P.	8-0	, Q-A,	, Q - A	,00,	0	9,5,	1	Actual	Height in ft
(<	<	<	((((ς	<	ς.	(7	<	(<	5	rods	No of	Steel (
(<	ζ	((<	((ς	((((((<	(rods	Size of	Steel (or x)
ς ,	((ς	ς	(<	· (ς .	۲	ζ	<	5	<	ζ	ς	ζ			Honeycombs
ς,		ς	((<	<	<		(ζ	<	(((<	(Side 1	Plumb
,	,	۲	(ζ	(((ς	((<	ζ	ς	ζ	۲	ς .		Side 2	Plumb (vor x)
Yes No	- 1	☐ Yes → No	☐Yes ☐No	☐Yes ☐No	☐ Yes ☐ No	☐ Yes ☐ No	Yes U.No	☐ Yes ☐ No	☐ Yes ☐ No	☐Yes ☐No	☐Yes ☑No	☐ Yes ☑ No	☐ Yes ☐ No	☐Yes ☐No	☐ Yes ☑ No	☐ Yes ☐ No	column?	marked on	Reference level
		_															-		

Quality Control Check Repot. Stage: After Column Casting (Apartments)

Г	-	7	Т-	т	T-	100	Ţ-	-	_		_	т—											
39.	38.	37.	36.	35.	34.	33	32.	31.	30.	29.	28.	27.	26.	25.	24.	23.	22.	21.	20.	19.	18.		S No
)	1	١)	١	١	1	١)))	١)	1))	1)	1))		Col No.
CA	Ç	(4	C5	C 9	C,	CA	G	C,	C	C 9	G	G	G	CA	CA	23	S	C4	CA	G	C3		Col type
100-17-190	8-770	3/4-2/16	8,472	0-7-K	8,73,	8-78°	8,77	8-7-T/2	37-17	2,72	8,	27.7	8-7/2	8-47	8-412	0,	8-A1	P. 137	8, C	A. 7/2	0-7-7-5	Spec.	Heig
\$ - 8.	14 J	0,00	χ, Α,	8-27/27	8-7/2	8-87	B-4/	8-8,	ر د -4,	0, -0,	09, 09,	3-0-0-15 1-0-0-15	0, 8,				8-3/	8-4	ر رون رون		. ور روی	Actual	Height in ft
ζ	ζ.	<	ζ	<	ς.	<	ζ ,	ζ.	ζ.	<	<	ζ	((<	(ζ.	۲	۲	ς.	ζ	No of rods	Steel (~
,	ζ.	(((C	(<	<	<	(<	ζ	C	((ζ	(((ς	`	Size of rods	(or X)
ς .	1	٢.	ع	۲	<	<	<	<	〈	ς	۲	ζ	ζ	<	(<	<	<	<	ς	ς		Honeycombs
(,)	((((<	(((((((((((,	,	(Side 1	Plumb
5	(((۲	ς	ς .	ς '	ς .	۱ ۲	۲ ا	۲	((۲	\	((; (, ,	,	ζ.	Side 2	Plumb (v or x)
☐ Yes ☑ No	☐ Yes ☑ No	Yes No	☐Yes ☐No	☐ Yes ► No	Yes No	- 1		1		Yes No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ► No	Yes No	☐Yes ☐No	☐ Yes ☑ No	☐ Yes ☑ No	- 1		☐ Yes ☑ No	☐ Yes ☑ No	marked on column?	Reference level

Quality Control Check Repot. Stage: After Column Casting (Apartments)

61.	60.	59.	58.	57.	56.	55.	54.	53.	52.	51.	50.	49.	48.	47.	46.	45.	44.	43.	42.	41.	· 40.		S No
)	1	3		Col No.
						Tanasa (dissilation	<u>C</u> 3		Ca Ca		Col type
																			D-1-100	R-41/2	A - 22 - 24 - 24 - 24 - 24 - 24 - 24 - 2	Spec.	Heigh
																						Actual	Height in ft
															2000				٢	ς	۲	No of rods	Steel (
																			((ς	Size of rods	Steel (v or x)
																			١	((.		Honeycombs
																			٢	ζ	(Side 1	Plumb
																			(<	(Side 2	Plumb (vor x)
☐ Yes ☐ No	□Yes ₽No	☐Yes ☐No	☐ Yes ☐ No	marked on column?	Reference level																		