Quality Control Check Repot. Stage: After Plastering (Villas)

Villa No.	60	Stage		Sl. No.	30268
Company MR	MRA (LLP)	Project	AGH	Phase	•
Prepared by P.	P. Sai Remar	Sign	Pray	Date	1515)18
Project Manager	Soman Kinner	Sign	Framont	Date	15/5/18
Previous stage report no.	-	2949)	Report filed and signed by PM?	d by PM?	WYes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	t ATR on QC re ed with work aff k only after mak k. ATR not requ	port to QC team. Proceed ter submitting ATR on ing corrections pointed ired.	eed only after recheck be QC report to QC team. I out in the QC report.	y QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	19	18	17	16	15	14	13	12	11		٠	×	. 7	0	U	1 n	٠ ر) V	- اد	S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terraec/ balcony 2	Terrace / baleony 1	Lobby-2	Lobby 1	Dining	Drawing	Toilet 4	Bedroom 4	Toilet 3	Bedroom 3	TOTTEL 7 CL	7 U	1-4	ı m	•
			<	}	1	1	١	1	<u> </u>	<	5		1		1			<	<	Skirting Provision (• or ×)
			<	1		J			1	ſ	<		1	TI T	ţ	<	K,	<	<	Finishing around door frame (• or ×)
			<	1	1	Ī	1	(\	<	<	}	}	!	-	<	<	3	5	Beams & columns finishing (• or ×)
				!	1	ſ	}	1	1	l	j	\			!	1	S	مسيا	-	Finishing of lofts (• or ×)
	_		<	\	I	1	١	(1	<	×))	(<	<	<	<	Electrical junctions finishing (• or ×)
		<u> </u>		}	1	1	}	1	1	1		1	,	[1	<	<	7	<	Window check (• or ×)
		j	4	}	1	1	1	1) .	1	١	-	\	1.	-	<	{	ς	†	Tiles provision (• or ×)
		_ k		1	[]	1	{	1	1	1	1	1	1	j	1	<	1	<	1	Sink provision & size (✓ or ×)
		<u> </u>		l	(1	1	l		1		[]	j	\	1		<u> </u>	<	`	Grooves for door frames (v or x)
	_		1	1	[((ţ	1	١	(1			}	\	1	1	1	Balcony & terrace sill top finishing 10(v or x)
 -				({ }	(l	({	}	(1	7	1	1	{	((Screeding in bathroom & utility (• or ×)
				\	1 1		1	1	[1	1	[(1	1	ſ	ſ	ſ	Screeding in 6" above FFL? (• or ×)

Page 2 of 3

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check Overall quality of plastering?	Good WAvg. Bad
Plustering of compound wall & gate pillars (or X)	AUS
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Plastering quality of parapet walls (✓ or 🗙)	DVa
Plastering and finishing of chajjas (or x)	dea
Remarks:	