Block No. 188 Column No. 188 Column No. Sign Column No. Column No. Sign Column No. Column No. Column No. Column No. Column No. Sign Column No. Column No.						
Project Vac (27 c) Project Vac Phase	Block No.	188	Column No.	(S)	SI. No.	30915
ager Sign Sign Date			Project	VOC	Phase) m
ort no. 30.750 MD Sign Report filed and signed by PM? MD Sign MD Sign Report filed and signed by PM? For filling For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.		CONUNT LINES	Sign		Date	22 11 18
ort no. 3c-750 MD Sign Report filed and signed by PM? MD Sign For filling For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.		' 	Sign	W		23/7/18
MD Sign For filling For filling For f	Previous stage report no.	30750		Report filed and signed		wes ⊠No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
	Recommendation: Stop further work. Subremark. Subremark. Proceed with further work. Proceed with further work. Proceed with further work.	nit ATR on QC receed with work aftork only after making. ATR not requi	port to QC team. Proce er submitting ATR on on ing corrections pointed red.	ed only after recheck b QC report to QC team. out in the QC report. A	y QC. \TR not required.	

Columns Position Check.

Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab. Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

The state of the s	Columns Position Check Plan enclosed?	3. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention i
	☐Yes ☐ No	actual dimension next

Slab Dimensions Check.

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
 a. Show outer dimensions of slab. (Tolerance 2")
 b. Show length and width of balconies (Tolerance 1")
 c. Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.

Sis

.

Specified thickness of slab? Actual thickness of slab?	Slab Dimensions Check Plan enclosed? NA Slab Dimensions Check Plan enclosed?	2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dim
6? 2P		ation actual dimension next to it.

Quality Control Check Repot. Stage: After Column Casting (villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good ☐ Avg. ☐ Bad
Quality of starters?	☐ Good ☐ Avg. ☐ Bad
Number and size of honey combs?	☐ High ☐ Medium. ☐ Low
Are the honey combs is slab and columns packed?	☐ Good ☐ Avg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	
Have 6 cubes each for columns and slab casted and numbered for testing?	□Yes □ No
Remarks:	en e
Curing.	
Bunds for curing made on slab?	
Bund size is less than 100 sft?	
Drum (200 lts) provided for curing?	
Gunny bags used for column curing?	
Distance of tap from furthest distance that requires curing. (max permitted 100')	
Frequency of curing in number of times a day (enquire from labourers)	2 Jims
Is the pressure in the curing pipe more than 15' head?	
Quality of infrastructure for curing.	Bad
Remarks:	

Quality Control Check Repot. Stage: After Column Casting (villas)

Columns height, plumb, steel & level marking check.

- Mark V for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Tolerance: Plumb 0.25".
 Circle actual height of columns if level differs from specified height by more than 1".

20.	19.	18.	17.	16.	15.	14,	13.	12.	11.	10.	9.		7.	6.	5.	4.	3.	10				S No
											63	53	200	C3	Ca.	13.2	60	1/3	3	_		Col No.
											C,	C3	Ca	C)	6.3	()	C	(2)	(2)			Col type
											9-31	9-31	0-3	9-3		7.07	9,3,	9.32	رور	1	Spec.	Heigh
											9-017	0,-1	9-0	9-01	9-1	9-1-	q'\	Q	9,-0		Actual	Height in ft
											ς	5	ζ	7	(٢	(ς .	7	rods	No of	Steel (
											ζ	((٢	(((5	(rods	Size of	Steel (or x)
											((((ς .	ſ	ζ	ζ	ζ			Honeycombs
	į										C	ς	(1	ζ	1	(1	(Side 1	Plumb
											((((((<	ζ	(Side 2	Plumb (✓ or ×)
☐ Yes ☐ No	☐Yes ☐No	Yes No	☐Yes ☐No	☐Yes ☐No	∐Yes ∐No	☐Yes ☐No	∠Yes □No	☐Yes ☐No	☑Yes ☐No	∠Yes □No	☐Yes ☐No	∠Yes □No	⊠Yes □No	⊠Yes □No	column?	marked on	Reference level					