## Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation:  Stop further work. Submit ATR on QC report Stop further work. Proceed with work after stop. Proceed with further work only after making of the proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
Submit ATR on QC re Proceed with work af er work only after mak er work. ATR not requ		10.	8	V Sankel	Joc (LLP) Project	228
eport to QC team. Proceed the submitting ATR or sing corrections pointe ired.	MD Sign	30856	Sign	Sign	Project	Stage
scommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.		Report filed and signed by PM?	-	7- (C)S-1-1	Voc	
by QC. a. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	□Yes □No	✓ Yes ☐ No	25/10/19	25/10/18	( many	31833

## Inspection should be done after:

- brickwork & 2 coats plastering is completed after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

### Plastering Check.

#### Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.

  Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	19	18	17	16	15	14	13					œ	7	6	5	4	3	2	1	S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony-2	Ferrace / balcony 1	- <del>L</del> obby 2 -	trobby t&	Dining	Drawing	Toilct 4	Bedroom 4	NEWS C	Bedroom 3 G.3	Toilet 2 \\.⊤	n 2	Toilet 1 M.T	Bedroom 1 M.8	Room
			<	<u> </u>	~		~	1	,	1			1	1	`~	1	<u>ر</u>	7	<b>\</b>	Skirting Provision ( • or ×)
				1	1	ì	7	1	Ţ	1	4		[	/	~	1	く	1	4	Finishing around door frame ( • or ×)
			4	Ì	7	****	イ	١	1	4	~	**	1	~	~	1	. 1	1	1	Beams & columns finishing ( • or ×)
			١	1	9	1	1	١	1	4		-	i	-	*	and the same of	1	7	1	Finishing of lofts ( v or x)
	8		1	۷,	~	ı	1	1	1	4	4			/	4	7	٠٠/	1	<u> </u>	Electrical junctions finishing ( • or ×)
			/	1	1	-	1	1	į	4	4	-		1	~	4	1	4	~	Window check ( v or x)
			ı_	/	١	١	•	١	}	•	1	******	-	/	١	7	<b>Q</b> 27 <b>—</b> ———	4	-	Tiles provision ( v or x)
			-		Ĵ	1		1	1	•		1	•		•	Marion .	-	****	-	Sink provision & size (✓ or 🗙)
				1	4	1	1	1	-	-	4	•	١	7	4	4	4	~	7	Grooves for door frames ( • or ×)
			1	8	-	1	1		BP1	4	1		٩		9	1	1	1	ę	Balcony & terrace sill top finishing 10( v or x)
	200		1	1	-		ga. In	1	1	1	1	1	١	1	9	۷.	•	1	١	Screeding in bathroom & utility ( • or ×)
			1	1		-	1	-	j	********	Section 1		any sales	-	***************************************	4	Ì	~	١	Screeding in 6" above FFL? ( • or ×)

# Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	☐ Good ☑ Avg. ☐ Bad
Plastering of compound wall & gate pillars ( v or x)	
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	✓ Yes ☐ No
Plastering quality of parapet walls ( v or x)	4
Plastering and finishing of chajjas ( v or x)	4
Remarks:	
	er de de martie de la principa de l