Recommendation: Checked By MD on Project Manager Company Previous stage report no. Prepared by Block No Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Bala mulaliteus has Skulder てるろ 72 Quality Control Check Repot. MD Sign Sign Sign Project Slab No. 30967 Report filed and signed by PM? Septe A Stage: Before Casting Slab (Villas) Bloomdale 02 grands For filling Date Phase SI. No. Date Yes No Yes 30/2 80/11 31156 No 12018 2018

Slab Check.

Proceed with further work. ATR not required.

- Inspection should be done before easting of slab at each stage i.e. when the slab is ready for easting.
- Prepare Slab Dimensions Check Plan as follows: Show outer dimensions of slab. (Tolerarce 2")
- Show inner dimensions of ducts. (Tolerance 1") Show length and width of balconies (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Wild landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour

Shari case slab dickness Specified:		Starrease - mid landing 2 Specified ht:	Staircase - mid landing! Specified ht:	Slab Dimensions Check Plan enclosed? Ves No
\A_=	d: 9:3"	, . 		egen meet
✓ (1 Actual:	Specified wd: 9.34 Actual wd: 9.34	Actual ht:	Actual ht:	Yes No
1	9.31	(2:6%"	No No
Within tolerance of 154"?	E	Within tolerance of 1500	2!6" Actual ht: 2:61/2" Within tolerance of 15"? Wes No	l mention actual dimension next to
Yes No	No No	□ Yes □ Vo	DYes □ No	0.11.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Remarks:		Remarks:
		ing length should be 45 to 50 D)

Slab Steel check. Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark X x for major mistake that requires correction by replacement or re-fixing.
 Mark X X for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Remarks:	16.	15.	14.	13.	12.	Ξ	10.	9.	8.	7.	6.	5.	4.	3.	2.	1.	S No
A	Steel check—slab extensions' joints	Steel check floating columns	Electrical Conducting	Steel Check - Column steel overlapping length and cranking	Covering blocks for slab	Steel Check - Slab Extra Bars	Steel Check - Slab cranking & chairs	Steel Check - Slab spacing of bars	Steel Check - Slab size of bars	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	•		•	ζ.						(C	((ς .	<	ς .	Quantitative Check
	☐ Good [☑] Avg. ☐ Bad	Good Avg. Bad	Good Avg. Bad	☐ Good [~] Avg. ☐ Bad	☐Good ☑Avg. ☐ Bad	Micood] Avg. [_] Bad	Good Avg. Bad	Good Navy. Bad	Good Avg. Bad	Good Avg. Bad	Good Avg. Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good [☐ Avg. ☐ Bad	L Good Avg. Bad	Good Avg. Bad	Qualitative Check (Good / Avg. / Bad)