dimension next to it.	ntion actual dimensi	Yes No Actual thickness of slab?	6 "	Plan enclosed? ab?	Slab Dimensions Check Plan enclosed? Specified thickness of slab?
		es: Prepare Slab (or plinth beams) Dimensions Check Plan as follows: a. Show outer dimensions of slab. (Tolerance 2") b. Show length and width of balconies (Tolerance 1") c. Show inner dimensions of ducts and lift well. (Tolerance 1") d. Show location of sunken slab. e. Print an A3 size plan. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and marting actions are all the properties.	Plan as follows: e 2") rance I") 'ell. (Tolerance I") ircle each incorrect dimen:	es: Prepare Slab (or plinth beams) Dimensions Check Plan as follows: a. Show outer dimensions of slab. (Tolerance 2") b. Show length and width of balconies (Tolerance 1") c. Show inner dimensions of ducts and lift well. (Tolerance 1") d. Show location of sunken slab. e. Print an A3 size plan. Circle each correct dimension with green colour. Circle each incorrect	Notes: 1. Prepare Slab (or plinth beams) Dimens a. Show outer dimensions of sla b. Show length and width of bal c. Show inner dimensions of du d. Show location of sunken slab e. Print an A3 size plan. 2. Circle each correct dimension with gree
dimension next to it.	ntion actual dimens	Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual umns Position Check Plan enclosed? Dimensions Check.	Sircle each incorrect dimer	ension with green colour. (k Plan enclosed?	3. Circle each correct dimension with green co Columns Position Check Plan enclosed? Slab Dimensions Check.
	each slab.	 es: Inspection should be done after casting of columns at each stage and before starting centering works for each slab. Prepare Columns Position Check Plan as follows: a. Divide blocks into smaller sub-blocks. b. Show size and orientation of columns. (Tolerance 0.5") c. Show inner – inner space between columns. (Tolerance 1") d. Show diagonals for 20% of bays. (Tolerance 1.5") e. Print an A3 size plan 	s at each stage and before olerance 0.5") ns. (Tolerance 1") nce 1.5")	es: Inspection should be done after casting of columns at each stage and Prepare Columns Position Check Plan as follows: a. Divide blocks into smaller sub-blocks. b. Show size and orientation of columns. (Tolerance 0.5") c. Show inner – inner space between columns. (Tolerance 1") d. Show diagonals for 20% of bays. (Tolerance 1.5") e. Print an A3 size plan	Notes: I. Inspection should be done after 2. Prepare Columns Position Che a. Divide blocks into sn b. Show size and orients c. Show inner – inner sp d. Show diagonals for 2 e. Print an A3 size plan
<u>i</u>	by QC. ATR not require	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. unns Position Check.	port to QC team. Proofer submitting ATR or ing corrections pointe ired.	Stop further work. Submit ATR on QC report Stop further work. Proceed with work after supproceed with further work only after making a Proceed with further work. ATR not required unnus Position Check.	Stop further work. Su Stop further work. Proceed with further Proceed with further Columns Position Check.
Yes	For filling		MD Sign		Recommendation:
QΥ _{es}	ed by PM?	Report filed and signed by PM?	34 8 08	10.	Previous stage report no.
400	Date Date	1000	Sign	Subha Roddy	Project Manager
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Phase	MPP	Project	MPL	Company Prepared by
-	SI No			A-00 02	Block No.
1	ing (Anartme	Stage: After Column Casting (Ana		Quality Control Check Repot.	

Quality Control Check Report. Stage: After Column Casting (Apartments)	ments)
Quality of centering, rod bending and concreting?	☐ Good ☐ Avg. ☐ Bad
Quality of starters?	Good VAvg. Bad
Number and size of honey combs?	High Wedium I ou
re the honey combe is slob and polymers and the	
sic the honey comios is side and columns packed?	Good WAvg. Bad
number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	1
lave 6 cubes each for columns and slab casted and numbered for testing?	Yes No
emarks:	

Curing.	
Bunds for curing made on slab?	LYes □ No
Bund size is less than 100 sft?	☐Yes ☐ No
Drum (200 lts) provided for curing?	Yes No
Gunny bags used for column curing?	Yes No
Distance of tap from furthest distance that requires curing. (max permitted 100')	4000
Frequency of curing in number of times a day (enquire from labourers)	2) times
Is the pressure in the curing pipe more than 15' head?	Yes No
Quality of infrastructure for curing.	Good WAvg. Bad
Remarks:	

Quality Control Check Repot. Stage: After Column Casting (Apartments)

Columns height, plumb, steel & level marking check.

Notes:

Mark • for correct or minor mistake which does not require correction
 Mark × for minor mistake that requires minor correction.
 Mark × for major mistake that requires correction by replacement or re-fixing.
 Mark × × for major mistake that cannot be corrected.
 Tolerance: Plumb 0.25"
 Circle actual height of columns if level differs from specified height by more than 1".

	T	\top	\top	Т	Т		T	T		Т	_	_	_	т.			_		
17.	10.	16.	. i	13.	12.	5 .	10.	9.	,œ) .	j	9.	4.	بايد	2.		-		S NO
68	49	66	Es	64	8	40	,05	Dy	C8	66	5)	Ch	A8	A6	AS	AW		6.8	Col No.
()	CI	C	CI	62	5	Ch	C5	63	0	63	Cy	Cy	()	Cr	Cı	13		2	Col type
11.712	11 4/2"	パイニ	1,44	はた。	11 7 1/2"	1/4 11	"れた」「1	1117%	111 91	1.9.	1000	1100	11/7 1/1	パイル	111 712	がた、こ		Spec.	Heigh
" + "	11.6%"	11.8%"	11.7/2"	11.8"	14.11	111.61/2"	11.8%	14七一二	111.10%	(1). 10"	11.9%	111.9/2	11/6 /2"	1116%	11, 81/1	11 8 "		Actual	Height in ft
<	. <	<	<	<	1	<	5	5	1	5	5	5	5	5	5	5	rods	No of	Steel (
•	<	<	5	<	7	<	~	<	1	7	<	<	5	<	,	<	rods	Size of	Steel (or x)
<	<	<	,	5	\	<	`	\	5	7	1	1	7	1	7	1			Honeycombs
<	<	<	<	<	<	1	<	(1	<	1	<	<	<.	<	1		Side 1	Plumb
<	1	<	<	<	\	/	1	1	<	1	1	1	1	1	<	1		Side 2	(or X)
Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	∠Yes □No	Yes No	√Yes □No	Yes No	✓Yes □No	column?	marked on	Reference level

Quality Control Check Repot. Stage: After Column Casting (Apartments)

39.	38.	37.	36.	33.	36	34	33 !	33	31.	30.	29.	28.	27.	27	36	25	24.	23.	22.	21.	20.	15	18.		ONI C
												H8	47	H 5	8 20	+ 2	2 0	27	2	C 8	93	53	2		Col No.
											C,	C9	Ca	CS	()	63		(4)	Cu	(2	C3	<u>F</u>	C3	2	Col type
											1119"	11/9"	11/9"	111 911	1119"	11.9"		11/0/	1110"	11190	11/91	11 9"	1119"	spec.	Heigh
8											11 01	18181	11911	10 9"	16/10"	11'10"	11 10	1 1 1	11 24	11 8 11	11 10"	119"	111 16"	Actual	Height in ft
											<	•	<	<	<	<			5	7	5	5	<	No of rods	Steel
												<	<	<	<	-				\	5	1	<	Size of rods	Steel (or x)
											< "	`	1	\		\	<				<	1	7	1 de	Honeycombs
										,	< '			1	1	<	1	<		(5	1	(Side 1	Plumb
										<			<	<	7	(<	, ,	, ,	,	(7	5	Side 2	Plumb (or x)
Tes No			7	7	☐Yes ☐No	☐ Yes ☐ No	16	٦١٢	٦١٢	\neg	Yes No	Yes No	ŲYes □No	Yes No	ı	7/		\neg	Yes No	Yes No	marked on column?	Reference level			