Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by $\mathcal{D}.\mathcal{J}$	Company	Block No 12
on QC report to (work after subm fter making corre		27986	x-Purdiotham	P. for know	SON (LLU)	,
OC team. Proditting ATR of	MD Sign		Sign	Sign	Project	1
eed only after recheck by C QC report to QC team. d out in the QC report. ATF		Report filed and signed by PM?	A	2014	Sort	
QC.	For filling	PM?	Date	Date	Phase	Sl. No.
	☐Yes ☐No	¶Yes □No	4111131	16/11/11	K	28439

Plinth Beam Check. Notes:

- Inspection should be done before casting of plinth beam.
 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.
 Prepare plinth beam Dimensions Check Plan as follows:

 Show outer dimensions. (Tolerance 2")
 Show length and width of plinth beams (Tolerance 1")
 Print an A3 size plan.

 Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Plinth Beam Dimensions Check Plan enclosed?	Ýes □No

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Plinth Ream Steel At at.					Remarks:	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	1	Brackets for elevation features provided?	Alignment of beams on outer side?			Quality of centering, rod bending and concreting. Quality of centering, rod bending and concreting?
--------------------------	--	--	--	--	----------	--	---	---	-----------------------------------	--	--	--

Notes:

- Mark o for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark X for major mistake that requires correction by replacement or re-fixing.
 Mark X X for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

	T -				, 	<u> </u>		
Remarks:	7.	6.	5.	4.	3.	2.	1.	S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
		\					(v or X)	Quantitative Check
Avg. Bad	God May Avg. Bad	Avg. Bad	Myood Avg. Bad	Muood Avg. Bad	Y GOOD Avg. Bad	□ Good □ Avg. □ Bad	(Good / Avg. / Bad)	Oualitative Check