Recommendation: Checked By MD on Apartment No Project Manager Prepared by Previous stage report no. Flat No. Company Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team Proceed with further work. ATR not required. Proceed with further work only after making corrections pointed out in the QC report. ATR not required M. Tegasidhar MA シエババイ Quality Control Check Repot. 9 MD Sign Sign Other Sign Project Others 29300 Stage: After Brickwork (Apartments) Report filed and signed by PM? ぞろへ 12 NS Date Phase Other Sl. No For filling Date 7944 23/02 Yes Yes 2000 No

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC
- Chicken mesh should be used in each and every joint between RCC & Brickwork
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Balcony sill level should be 3'3"from SFL. (Tolerance: 1") Diagonals of each room shall be equal. (Tolerance: 2")
- Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Ren	15	4	2	13 i			_		8	7	6	5	4	3	2	1	S No
Remarks	Other	Other	Other	Kitchen	LJulity / balcony 3	Hilliw/balcony 2	thility / balcony	I vappy I	Dining	Drawing	Toilet 3	Bedroom 3	Totlet 2	Bedroom 2	Toilet 1 (CT)	Bedroom 1 (M\$)	Room
				<	! ;	<u>۔</u> د	. :	a	く	<	(1	1	ſ	<	<	Wall thickness
				<	!	₹.		1	<_	<	1	\	1	1	<	<	Beds in walls
				<	1	<		1	۷,	<		١	j	J	<	<	Chicken mesh
				<	1	<	4	1	<	<	1	1	1	1	<	<	External brickwork & beam joint (or x)
				<	1	<	i	1	<	<	1	1)]	~	<	Room Dimensions (• or ×)
			•	1		[ţ	t		1	1	1	1	3	4	4	Room Dimensions Difference in inches
				<	1	<	1	1	<	3	1	1)		K	1	Diagonal (v or x)
				1	-	,	١	-	1	J	١	1			1	4	Diagonal Difference in inches
				1		1	1	}	\	1	1		1]	1	1	Balcony sill level
		1		<		<]	<	\	1	1	1	1	<	<	Room Height
				, c	ر	two	1)	7	500	,)	1	J	-	200	Plumb of walls (Good/Avg./Bad)
				<	1	<))		7	٠				1		Alignment of beams and walls - Nos.

Ouality Control Check Repot.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	☐ Good ☐ Avg. ☐ Bad
Specify rooms that need correction:	
Misc. Checks.	
Was 3.75 CFT proportion box provided?	'NYes □ No
Condition of proportion box?	☐ Good ☐ Avg. ☐ Bad
Was the Apartment cleaned before starting brick work?	☐ Yes ☐ No ☐ Cant' say
s the Apartment cleaned for plastering?	☐Yes ☐No
Wastage?	☐ High ☐ Medium ☐ Low
Storage of building material like bricks sand and cement.	☐ Good MAvg. ☐ Bad
Orum (200 Its) provided for curing in each flat?	□Yes □No
Remarks:	

Door Frames & Windows check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing. Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

	Quality Co
	ntrol Check
es	Repot.
<i>-</i>	Sta
an/ ar	ge: Aftı
level	er Brick
X)	work (A
epth	partme
x)	nts)
m)	
rm NA)	

_i,

Ren	15	1, 14	13	12		Ξ	Ç	8	7	6	Ŋ	4	ω	2		S No
Remarks:	Uther	Other	Kitchen	Utility/balcony3	Litility / balcony 2	Litity / balcony 1	-Lobby (Dining	Drawing	Totlet 3	Bedroom 3	Toilet-2	Bedroom-2	Toilet 1 (ET)	Bedroom 1(MB)	Room
			1	1	Ī		ŗ	\	<		-	1	1	<		Door size, face and position (vor X)
			1	l	t	•	r	1	1	•	1	1	1	\		Brick at bottom of door frame (✓ or 🗙)
			1	1	·	*!	!	\	<		1	٩.		〈	<	Door lentil level (v or X)
			1	{	1	•	1	١	٢	١	١	١	•	\	\	Door diagonal check (✓ or 🗙)
					ſ	•	ı	1	<	1	•		*****	V		Door Plumb - two sides (vor X)
			1	ı	-		1	1	<	1	1			<		Door frame black Japan/ wood primer/Peelambar check (v or X)
			<)	f	1	\	5	•	-		1	<u> </u>		Windows lentil & sill level (✓ or 🗙)
			<	Į	1	T	1	1	<	1	-	7	•	V	<	Windows size (✓ or 🗙)
			<]	!	1	ļ	5		1		_	〈	<	Windows - template depth & diagonal (✓ or 🗙)
			〈	1]	4	1	Ì	<	1	1		-	<		Windows - template powder coated (✓ or X)
			170				Ţ	1	1	1	1)	j	١		Loft & Kitchen platform required? (Yes or No)
			1	١	1	<u> </u>	1		J	1	1	1)	١	•	Loft & Kitchen platform provided (• or × or NA)
			1		J	1	1	1	7	1))	1		1	Loft & Kitchen platform slope (✓ or 🗙)