ect Sign To QC to correction	Ouglity Control Check Repot.		Stage: After Plumbing & Electrical	trical (Apartments)	
BNC Sign Project WFG Phase Project Project Project Project Phase		Other	1	Sl. No.	25978
ge report no. ge report no. gel report no.		Project	MFG	Phase	=1
ge report no. ge rep		Sign	Q-4	Date	+1100 HO
port no. \$\frac{2}{2} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	 	S.		Date	4-1-20-40
sheet date A S S All pages signed by engineer & customer? MD Sign		Sign	D. Brandburter	1 1 DN (19	NVPS NO
All pages signed by engineer & customer? MD Sign R on QC report to QC team. Proceed only after recheck by QC. ith work after submitting ATR on QC report to QC team. y after making corrections pointed out in the QC report. ATR not required.	Previous stage report no.	SISER	Report filed and signe	d 0) 1 M.	
MD Sign For filling For QC report to QC report to QC. For filling For making corrections pointed out in the QC report. ATR not required.	Additions & alterations sheet date	4-18-18	All pages signed by er	ngmeer & customer:	I S L
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	MD Sign		For filling	Yes No
A FLOCEGO WITH THE HIGH WOLKS TATES THOSE TO A PROPERTY OF THE	Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after su Proceed with further work only after making of Proceed with further work. ATR not required.	Oreport to QC team. Proceeding ATR rk after submitting ATR making corrections point required.	roceed only after recheck lon QC report to QC team ated out in the QC report.	by QC. ATR not required.	

Inspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring,
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

- Mark \checkmark for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1". Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

	1 1	2	Annioved revised drawing affact	A paragraph	리 [Revised drawing required from HO	Rev
	√Yes □No		Signed by customer,	Signed	√Yes □No	2 7	Signed by engineer,	Sign
						lteration sheet:	Remarks on additions & alteration sheet:	Ren
							Remarks	Rer
							Other	15
	8			٥		l.	Other	14
1				<	<		Kitchen	13
1		1	1			1	Utility/balcony-3	12
1	١	1	1	~	<	~	Utility / balcony-2	=
J	1	J	1	<	<	<	Utility / balcony 1	10
1	1	and the second	1				Lobby-1	9
1		-	1	<	1	١	Dining	00
<	<	1	٠	<	J	J	Drawing	7
	***	-	1	I	-	١	Teilet3	6
١	1	1	(~	(-	Bedroom 3 (416)	Ŋ
١	1	1	J	<	<	J	Toilet 2 (CT)	4
	1	1		<	-		Bedroom 2 (KB)	ယ
1	1	1	1	<	<	ſ	Toilet 1 (MT)	2
ſ	J		}	<	: [J	Bedroom 1(MB)	-
(* or *)		×	×			utility (vor	Roor	S No
Cienerator	DB (v or x)	check (> or	proofing or	points check	PVC Check	halcony &		
Placement of	L Iacement of	Linber ase or	Watel	Electrical	Cryca	CIVII WORK	-	191 ₀ - 1