	Quality
	Control
	Quality Control Check Repot.
	Stage: After
- CONTRACTOR - CON	Brickworl
	Stage: After Brickwork (Apartments)

Flat No.	E-402	Others	1	Sl. No.	29006
Company	BNC	Project	MFG	Phase	H.
Prepared by	M. Iga Sindhu	Sign	4	Date	13/01/18
Project Manager	Subba Reddy	Sign	1 Carolinary	Date	81:061
Previous stage report no.	no.	488B	Report filed and signed by PM?	d by PM?	Nes No
Apartment No		Other		Other	
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Sub Stop further work. Pro Proceed with further w	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck b Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Proceeds submitting ATR on ing corrections pointed ired.	eed only after recheck l QC report to QC team. I out in the QC report.	by QC. n. ATR not required.	

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check,

Notes:

- Mark v for correct or minor mistake which does not require correction
- ... Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- l. Mark XXX for major mistake that cannot be corrected.
- 5. Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC
- 7. Chicken mesh should be used in each and every joint between RCC & Brickwork.
- 8. Joint between brickwork & beam on external side must be filled.
- 9. Check room dimensions with working plan. (Tolerance: I")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 2. Check room height with specified height. (Tolerance: 1")
- 13. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 4. Specify the No. of beams which are not aligned by more than 1"in a room.
- 5. Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Kem	15	14	13	12	=	10	9	∞	7	6	١ ر	ν 1	Z (س	2	-	S No
Remarks	Other	Other	Kitchen	Utility/balcony 3	Dulity / balcony 2	1 Hility / halcony 1	Lebby 1	Dining	Drawing	Tellets	Demoon 3 (46)	ا د	7 7	3	Toilet 1 (MT)	Bedroom 1 (MB)	
			<	1	ζ :	·	!	<	<	1	1	X	<	,	<	<	Wall thickness (✓ or ×)
				· .	< .	:	1	<	<	\	2	\	K	<	`	<	Beds in walls (or x) Chicken mesh (or x) External brickwork & beam joint (or
			1	1	<u> </u>			< <	<	{	۷	<	<	\		<	Chicken mesh
		-	1	ĺ	₹ ,	-	·		3	1	~	<	<	. <	,		External brickwork & beam joint (• or X)
		 -			< .	12		< <		\	<	<	<	<	, ,	1	Room Dimensions
			(1	((()		Room Dimensions Difference in inches Diagonal (v or x)
		K	\	;	e ^r	Î	\ 				<	<	<	5	<	`	Diagonal (v or x)
		1	!					1				1	(ſ	5		Diagonal Difference in inches Balcony sill level
			:	***		· .		1		١	(((1	1		Balcony sill level
		K	1	· (8		\ 	<	\$	1		<	<	<	<		Room Height
		2	\ \ \ \	1.	1 (1 M)	> ·	5	tra	>		۶ ۶		٤	s)	44	, (Plumb of walls (Good/Avg./Bad)
		<		<	ζ.		<	<	, 1	<			<	<	5	2	Alignment of beams and walls - Nos.

Quality Control Check Repot.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	Good Navg. Bad
Specify rooms that need correction:	
Misc. Checks.	
Was 3.75 CFT proportion box provided?	\ \forall Y \text{es} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Condition of proportion box?	Good Avg. Bad
Was the Apartment cleaned before starting brick work?	☐ Yes ☐ No ☐ Cant' say
Is the Apartment cleaned for plastering?	\ \text{\text{Yes}} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Wastage?	☐ High ☐ Medium ☐ Low
Storage of building material like bricks sand and cement.	☐ Good ☐ Avg. ☐ Bad
Drum (200 lts) provided for curing in each flat?	Yes No
Remarks:	
77 77 77 77 77 77 77 77 77 77 77 77 77	

Door Frames & Windows check

- 1. Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark X X for major mistake that requires correction by replacement or re-fixing. Mark X X X for major mistake that cannot be corrected.

- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL.
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

Page 4 of