	Quality Control Check Repot.
	Control
	Check b
	₹epot.
	Stage
	After E
	<b>Srickwor</b>
	k (Apa
	Repot. Stage: After Brickwork (Apartments)
	$\overline{}$

Flat No. F-107	Others		S1. No.	32709
Company Vista tones	Project	Vista Homes	Phase	ł
Prepared by	Sign ·	V. S. K.	Date	22/01/19
Project Manager Shopen Rahi	Sign	M X	Date	2,20119
Previous stage report no.	32588	Report filed and signed by PM?	ed by PM?	☑Yes □ No
Apartment No	Other		Other	
Checked By MD on	MD Sign		For filling	□Yes □No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	n QC report to QC team. Provork after submitting ATR of ter making corrections point of required.	oceed only after recheck lon QC report to QC team ted out in the QC report.	by QC. ATR not required.	

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

## rickwork Check.

## Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- . Mark XXX for major mistake that cannot be corrected.
- 5. Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- . Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 1. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 12. Check room height with specified height. (Tolerance: 1")
- 13. Check plumb of walls where ever it appears to be out of plumb. (Tolcrance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than 1"in a room.
- 5. Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Ren	15	14	13	12	11	10	9	∞	7	6	Ş	4	3	2	1	S No
Remarks	Other	Other	Kitchen	Utility-/-balcony 3	Utility / baleony 2	Utility / balcony 1	Lebby 1	Dining	Drawing	Toilet 3	Bedroom 3	_	Bedroom 2 k.13	Toilet 1 30-701	Bedroom 1 M.B	Room
	ā		<	į	<	1	į	۷.	4		1	V	<	<	۷.	Wall thickness (~ or ×)
		,	Avg	i	<	<b>V</b>	f	*	君	•	ţ	<b>ゼ</b> .	5	ζ.	7	Beds in walls ( v or x)
			Z	i	~	~	1	۷,	<	1	ſ	<	<	<u> </u>	À	Wall thickness  (
			Z.		~	<u> </u>	1	<	<	1	Ì	ζ	<	ζ	<	External brickwork & beam joint ( v or ×)
			<	5	<	J	1	<	<	1	ſ	<	<	ć	~	Room Dimensions ( or x)
	-		Ł	1	۷	<b>V</b>	1	<	₹.		7	<	<	*	<	Room Dimensions Difference in inches
			×.	ī	<	<b>~</b>	1	<	ζ.	ļ	ı	<	۲.	<	<	Room Dimensions Difference in inches  Diagonal ( v or x)  Diagonal Difference in inches  Balcony sill level ( v or x)
			<	î	4	V	1	<	<	1	1	۷	۷	<	<	Diagonal Difference in inches
			Ţ	į	J	4	1	à	-	1	1	79	\$7.00 E	ì	<b>N</b>	Balcony sill level
			5	1	<	<	7	٤	<	Ì	ř	<	<	<	~	Room Height ( v or x)
			4	Ì	Ave	Avg	٦	Great	Greed	1	ì	Checol	ക്ര	Crock	Arg	Plumb of walls (Good/Avg./Bad)
			<	i	<	4	•	<	۷.		)	۷.	۷.	<	<	Alignment of beams and walls - Nos.

Quality Control Check Repot.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	☐ Good ☑ Avg. ☐ Bad
Specify rooms that need correction:	
Misc. Checks	
Was 3.75 CFT proportion box provided?	✓ Yes ☐ No
Condition of proportion box?	☐ Good ☑ Avg. ☐ Bad
Was the Apartment cleaned before starting brick work?	☐ Yes ☐ No ☑ Cant' say
Is the Apartment cleaned for plastering?	✓Yes □No
Wastage?	☐ High ¶Medium ☐ Low
Storage of building material like bricks sand and cement.	Good Avg. Bad
Drum (200 lts) provided for curing in each flat?	✓ Yes
Remarks:	

## Door Frames & Windows check

## Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark **XX** for major mistake that requires correction by replacement or re-fixing. Mark **XXX** for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 1/2" after plastering.
- Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 35" or 36" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

יאל	_	<u> </u>	_		T_	Γ	9	∞	7	6	ري ا	4	. w	T	_	
ema	15	14	13		11	10					-31			10000		S No
Remarks:	Other	Other	Kitchen	Mility/balcony3	Utility / balcony-2-	Utility / balcony 1	Lobb <del>y 1</del>	Dining	Drawing	Toilet 3	Bedroom 3	Toilet 2 (-Tai		Toilet 1 M. Tol	Bedroom 1 M.B	Room
			İ	Ţ	4	1	1	1	<	١	ţ	4	Í	ڒ	۷,	Door size, face and position ( ✓ or X)
			i	ı	`	1	ſ	1	Ų.	<b>\$</b> 7711	1	<	<	<		Brick at bottom of door frame (✓ or 🗙)
			!	1	<	N.	١	1	ζ	gue	ī	<	<	<b>\</b>	<	Door lentil level (✓ or 🗙)
			Ļ	ı	<	**	ŗ	1	<	i	î	ς_	<	ζ	\ \	Door diagonal check (✓ or X)
			·	1	<	١	1	1	ς	7	1	(	ζ	ς.	<	Door Plumb - two sides (✓ or 🗙)
-			1	}	۲	t,	1	1	,	1	ì	ſ	7	(	1	Door frame black Japan/ wood primer/Peelambar check ( or X)
			۷.	ţ	ì	1	١	1	۲	١	1	1	~	`	T	Windows lentil & sill level (✓ or 🗙)
		,		1		1	1	1	<	7	etern.	۲,	7	(		Windows size (✓ or 🗙)
		•	ζ,	ì		7	1	7	(	1		۲	٢ ,	;		Windows - template depth & diagonal (✓ or 🗙)
		•		1	t comment		1	9	<	1	1	<	۲ ,		F	Windows - template
		705	4	1	P	1	ĵ	1			1	١	1	١	Į Į r	oft & Kitchen platform equired ? (Yes or No)
		4	\		Day.	1		١	1	1	Ī	1	1	1	İ	Loft & Kitchen platform provided ( • or × or NA)
		<	`	1	1	1	}	١	1	١	1	]	1		I s	oft & Kitchen platform lope ( v or X)

Quality Control Check Repot.

Stage: After Brickwork (Apartments)