- (-))					
BIOCK NO	82	Slab No.	03	SI. No.	44408
Company	VOC (ILP)	Project	20C	Phase	
Prepared by	いったれたらの	Sign	FG	Date	9102/2018
Project Manager	A.Swawh	Sign	F	Date	8:02 (50 / 60
Previous stage report no.		30699	Report filed and signed by PM?		Yes No
Checked By MD on		MD Sign	Fo	For filling	□Yes □No
Recommendation: Stop further work. Stop further work. Proceed with furthe	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck! Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	OC team. Pr mitting ATR rrections poin	ATR	C.	

STAD CHECK.

Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
 Prepare Slab Dimensions Check Plan as follows:

 Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1") Show inner dimensions of ducts. (Tolerance 1") Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Slab Dimensions Check Plan enclosed?	ed?		☑Yes □No		11 ON 1VOTE HOLIGINATION MAKEN HOUSENESS	0.11.
Staircase - mid landing1	Specified ht:	f	Actual ht:	!	Within tolerance of 1/2"?	Yes No
Staircase - mid landing 2	Caractaryly					
Stantease - tilld läilding Z	Specified ht:	ı	Actual ht:	ţ	Within tolerance of 1/2"?	☐ Yes ☐ No—
Staircase width	Specified wd:)	Actual wd:	,	Within tolerance of 1/2"?	☐ Yes ☐ No_
Staircase slab thickness	Specified:	1	Actual:	1	Within tolerance of 1/4"?	☐Yes ☐No
		į				1,144

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☑ Good ☐ Avg. ☐ Bad
18"extension to beam bottom runners on outer side provided?	✓ Yes □No
Quality of Bracing Provided?	☐ Good ☑ Avg. ☐ Bad
Alignment of beams on outer side?	☐ Good ☑ Avg. ☐ Bad
Shuttering leveling?	☐ Good ☑ Avg. ☐ Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Remarks:	
	00000000000000000000000000000000000000
	•

Slab Steel check. Notes:

- Mark r for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XXX for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

	Remarks:	-		_	13. Sto		ļ	-	_					ļ				S No
		Steel check – slab extensions/ joints	Steel check – floating columns	Electrical Conducting	Steel Cleck - Column steel overlapping length and cranking	Covering blocks for slab	Steel Check - Slab Extra Bars	Steel Check – Slab cranking & chairs	Steel Check - Slab spacing of bars	Steel Check - Slab size of bars	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
			,		(×						×	<	(<		<	Quantitative Check
		☐ Good ☑ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	□Good □ Avg. □ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐Good ☐ Avg. ☐ Bad	☑Good ☐ Avg. ☐ Bad	Good Avg. Bad	☐Good ☐ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	☐Good ☐ Avg. ☐ Bad	Good Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad		Qualitative Check (Good / Avo / Rad)