Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Q Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
commendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after support Proceed with further work only after making or Proceed with further work. ATR not required.),	63 3		(4T) 12	90
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	MD Sign	32122	Sign	Sign	Project	Stage
eed only after recheck QC report to QC team d out in the QC report.		Report filed and signed by	AF	V-S-V	Sov &	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	∐Yes ∐No	XYes \(\text{No}\)	24/12/18	24/12/18	XI	32450

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark \vee for correct or minor mistake which does not require correction Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing. Mark \times \times for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	Ren	19	18	17	16	15	14	13	12	11	10	9	8	7	6	Ŋ	4	Ųλ	2	-	S No
	Remarks (1) Do	Other	Utility	Kitchen	Portico	Head room	Terrace/balcony 2	Terrace / baleony 1	Lobby 2	Lobby-t	Dining	Drawing	Foilet-4	Bedroom 4	Toilet-3	Bedroom-3		Bedroom 2 K.B		Bedroom 1 N.S	Room
	abo I			بر	1	4	ı	1		1	4	۷.	1	1	,	1	ζ.	2	ď	۷,	Skirting Provision (v or x)
	201			۷	!	4	1	1	1	1	1	۷	ı	1	1	i	ر ر	۷.	<u> </u>	į,	Finishing around door frame (v or x)
	Conidina			z	1	۷	1	1	١		4	۷.	1	1	ļ	1	٨	ζ.	Ł	۷.	Beams & columns finishing (v or x)
				۷	1	١	1	ſ	١	1	ı)	1	1	ī	1	Ì	1)	<u> </u>	Finishing of lofts (• or ×)
	Tore			4	1	۷	,	1	,	ļ	<	۷,	ļ	ļ	1	1	4		۷	く	Electrical junctions finishing (v or x)
	1. C.			<	1	۷,	1	١	1	1	4	4	1	1	1		۷.		4	۷.	Window check (✓ or X)
	en charle			×		1	ſ	1]	1	1	1	1	,	1	١	4		<	1	Tiles provision (• or ×)
	<u>_</u>			4	1	1	1	1	!	ı	1	١	}	1	,	,	1	3	1	1	Sink provision & size
	-			۷.	1	<	1	1	1	1	١	4	1	1	1	1	<	<	<	K	Grooves for door frames (v or X)
	Sitchen			1	1	1		<		1	1	,	1	1	ì	1	1	1	1	١	Balcony & terrace sill top finishing 10 (~ or ×)
	B			1	,	1	1		1	1	1		1	-	,	1	1	1)	1	Screeding in bathroom & utility (v or x)
)		١	1		1	1	1	1))	1)	1	1	1	,	Screeding in 6" above FFL? (✓ or ×)

Quality Control Check Repot. Stage: After Plastering (Villas)

	Remarks:	Plastering and finishing of chajjas (v or X)	Plastering quality of parapet walls (v or X)	Is plastering of compound wall and villa external walls 6" below FFL of schocks:	Plastering of compound wall & gate pillars (v or X)	Miscellaneous check Overall quality of plastering?
		<	Z		Vest No	☐ Good ☑ Avg. ☐ Bad