Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Stop further work Proceed with furtl Proceed with furtl	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Villa No.
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.		no.	moditive sudar	5. Sun Xolma	Milaigh Talate Project	0
eport to QC team. Proceer submitting ATR on cing corrections pointed tired.	MD Sign	84939	Sign			Stage
eed only after recheck l QC report to QC team I out in the QC report.		Report filed and signed by PM?	Mr wholl Date	1	Nilgisi Estate Phase	
by QC. ATR not required.	For filling				Phase	Sl. No.
	∐Yes ∐No	Yes No	03/11/17	03/11/17	1	<u> 28350</u>

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.
- 9"unplastered area from SFL should be left including in common areas and terraces. Mark XXX for major mistake that cannot be corrected.
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- Windows must be checked with templates. Tolerance 1/4".

- All doors frames should have 1/2 grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	19			90	1	14	13	12	11	10	9	000	7	0	S	4	. w	2	Ī	S No
Remarks KA P	Other	Utility	Kitchen	-Portico-	Head-room	Terrace/balcony2	Ferrace / balcony 1	Lobby 2	Lebby-b	Dining	Drawing	Toilet 4	Bedroom-4	Foilet-37	Bedroom 3	Toilet 2 C. TOI	Bedroom 2 G. Bec	Toilet 1 M. Toi	Bedroom 1 M.Bed	
Pladform			<	1	1	1	1	1	1	1	<	1	١	1	1	5	(	ς	5	Skirting Provision ( v or x)
5			ζ	1	1	1	1	1	١	1	ζ.	1	3	1	;	ζ	5	<	11	Finishing around door frame ( v or x)
and			<	1	١	1	١	1	١	١	5	-	,	•	1	<	(	~	<	Beams & columns finishing ( v or x)
Widt			1	١	1	1	1	1	1	1	1	1	}	1	)	-	\$6*******	)	1	Finishing of lofts ( v or x)
7			Ж	١	1	1	١	١	1	1	×	1	1	1	1	(	(	/	X	Electrical junctions finishing ( v or x)
2			ς	1	1	l	1	ī	1	)	<	١	1	1	}	<	5	\	5	Window check (✓ or X)
9			X	1	•	١	١	)	١	}	{	١	1	1	l	(	•	(	١	Tiles provision ( • or ×)
Pen			<	]	1	1	)	1	}	1	1	1	}	-	}	}	1	١	1	Sink provision & size ( v or x)
Spec			1	١	١	١	١	)	)	1	ζ	1	1	,	ı	ς	ζ	5	(	Grooves for door frames ( v or x)
specifications.				l	1	1	3	١	3	3	١	)	)	)	3	١	1	•	1	Balcony & terrace sill top finishing 10 ( v or x)
HONS.			١	}	1	)	١	١	١			1	1	1	1	1	1			Screeding in bathroom & utility ( v or x)
			1	)	1	]	1	)	)	)	)	)	)	}	3	)	)	)	1	Screeding in 6" above FFL? (v or x)

## Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check  Overall quality of plastering?  Plastering of compound wall & gate pillars ( v or x)	☐Good ☐Avg. ☐Bad —
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	☐Yes ☐No
Plastering quality of parapet walls ( vor x)	1
Plastering and finishing of chajjas ( • or ×)	)
Remarks: (1) Compound wall work not done as pen	Rigifian Affair, isis , am,