## Quality Control Check Repot. Stage: After Column Casting (villas)

Recommendation:  Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making Proceed with further work. ATR not required	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No.
ubmit ATR on QC re roceed with work af work only after mak work. ATR not requ		-	Radherlyon	iso kun	Milson estate	lol :
port to QC team. Proofer submitting ATR or ing corrections pointe ired.	MD Sign	27402	Sign	Sign	Project	Column No.
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	The state of the s	Report filed and signed	Chacl	Ridy	Aldoni ellate	73
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	√Yes □No	41/4/8	8/11/18	FI	15547

### Columns Position Check.

Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab.
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks,
- Show size and orientation of columns, (Tolerance 0.5")
- Show inner inner space between columns, (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

|--|

#### Stab Dimensions Check.

Notes:

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.

7 2	Actual thickness of slab?	4 11/2	Specified thickness of slab?
			A CONTRACTOR OF THE PROPERTY O
	Yes No		Slab Dimensions Check Plan enclosed?
dimension next to it.	usion with red colour and mention actual	olour. Circle each incorrect d	2. Chele each correct dimension w
			C. Find all AD SIZE plant.

# Quality Control Check Repot. Stage: After Column Casting (villas)

### Quality Control Check Repot. Stage: After Column Casting (villas)

# Columns height, plumb, steel & level marking check.

Notes:

- Mark v for correct or minor mistake which does not require correction Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing. Mark XXX for major mistake that cannot be corrected.
- Tolerance: Plumb 0.25".

Circle actual height of columns if level differs from specified height by more than 1".

20.	19.	18.	17.	16.	15.	14.	13.	12.	11.	10.	9.	×	7.	6.	5.	4.	3.	2.	<u>-</u>			S No
		-							'noue de							S	60	Ş	88			Col No.
									a consu							C)	5	CP	01			Col type
				592												パイン8	17:14:00	パナイプ	2,71.		Spec.	Heig
																8.3.	8,8,1	8.73	1.6.8		Actual	Height in ft
											*					<	1	<	5	rods	No of	Steel (
											U.					<	<u> </u>		<	rods	Size of	Steel ( v or x)
												,				<		<	5			Honeycombs
	i													100		~	<	<	<		Side 1	Plumb
										83						<	<	<	7		Side 2	Plumb ( or x)
☐Yes ☐No	□Yes □No	□Yes □No	□Yes □No	☐Yes ☐No	☐Yes ☐No	☐Yes ☐No	□Yes □No	☐Yes ☐No	☐ Yes ☐ No	☐Yes ☐No	∐Yes ∐No	Yes     No	∏Yes □No	☐Yes ☐No	☐Yes ☐No	√Yes □ No	∏Ýes □No	√Yes □No	√Yes □No	column?	marked on	Reference level