Quality Control Check Repot.
trol Chec
k Repot.
Stage: Before Casting
e Castir
Plint
am (Villas)

Recommendation:  Stop further work. Submit ATR on QC report  Stop further work. Proceed with work after symptoceed with further work only after making of Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager		Company	Block No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	MI	23013	A. Sux Car Sign	S. Suna delay Sign	The oscho (1) P) Project	104
eam. Proc g ATR on ms pointe	MD Sign		gn	gn	oject	
ced only after recheck by Q QC report to QC team. I out in the QC report. ATR	1944	Report filed and signed by PM?	( W	) <= )(C	700	100
C.	For filling	PM?	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	Yes No				28218

## Plinth Beam Check. Notes:

- Inspection should be done before casting of plinth beam.
  Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.
  Prepare plinth beam Dimensions Check Plan as follows:

  a. Show outer dimensions. (Tolerance 2")

  b. Show length and width of plinth beams (Tolerance 1")

  c. Print an A3 size plan.
  Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.
- 4.

ם	
Plinth Beam Dimensions Check Plan enclosed?	
Yes No	

## Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

	Service	Good Avg. Bad Yes No Good Avg. Bad Good Avg. Bad Yes No Ava Yes No Yes No Correct Needs corr
Jeve	vided?	☐ Yes ☐ No ☐ NA
		Yes No
Remarks: 1) Rod Bending work nat Sodisty. (2) Mud should be properly laveled at Beam bothom level.		Correct Needs
	narks: 1) Rod Bending work nat Sodisty.	

## Plinth Beam Steel check.

## Notes:

- Mark 

  for correct or minor mistake which does not require correction
   Mark 

  for minor mistake that requires minor correction.
   Mark 

  K for major mistake that requires correction by replacement or re-fixing.
   Mark 

  K for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

Page 3 of 3

ım (Villas)	Qualitative Check	Good Avg. Bad	A Good Ava Bad	COOM TAYS: Land	Good Avg. Laad	Good Avg. Dad	Good Avg. Dau	Good Avg. Bad	Good Avg. L Dau			
Stage: Before Casting Plinth Beam (Villas)	Quantitative Check	( or X)	>	>	\	gu	>	>	>			
Quality Control Check Repot.	Item		Steel Check - Beam no of rods	Steel Check - Beam size of bars	Steel Check - Beams Extra Bars	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Bearing	Covering blocks for beams	Depth and width of beams			
	SIA S	o No	1	2.	3.	4	5.	;   e	7.	Remarks:		

Stage: Before Casting Plinth Beam (Villas)