### Recommendation: Checked By MD on Project Manager Prepared by Company Block No Previous stage report no. Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Proceed with further work. ATR not required. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Quality Control Check Repot. Madthy Suday N.C. BUSIN SUNI 40 TUS DA 28396 MD Sign Project Sign Sign ì Stage: Before Casting Plinth Beam (Villas) Report filed and signed by PM? ろうころ gion Toloton Phase For filling Date Sl. No. Date Yes = 4 Yes 29991 No

### Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam
- Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark
- Prepare plinth beam Dimensions Check Plan as follows:
- Show outer dimensions. (Tolerance 2")
- Show length and width of plinth beams (Tolerance 1")
- Print an A3 size plan.

4 2

- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

  Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Dimensions Check Plan enclosed?	
---------------------------------	--

# Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	pping length should be 45 to 50 D)		Hrackets for elevation features provided?		Have rods for staircase slab been provided?	Quality of centering, rod bending and concreting?	Quality of centering, rod bending and concreting.
----------	------------------------------------	--	---	--	---	---	---

## Plinth Beam Steel check,

Notes:

- Mark v for correct or minor mistake which does not require correction
   Mark X for minor mistake that requires minor correction.
   Mark X X for major mistake that requires correction by replacement or re-fixing.
   Mark X X X for major mistake that cannot be corrected.
   Columns overlapping length should be 45 to 50 D.

# Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7. Depth and width of beams	6. Covering blocks for beams	5. Steel Check - Beams Bearing	4. Steel Check - I	3. Steel Check - I	2. Steel Check - I	1. Steel Check - I	S No	
	h of beams	s for beams	seums Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item	
	5	5	5	5	ς.	ς.	\	Quantitative Check ( • or ×)	
	Good Avg. Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Good Avg. ☐ Bad	Good Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)	