Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Recommendation:    Stop further work. Submit ATR on QC report   Stop further work. Proceed with work after su   Proceed with further work only after making of the Proceed with further work. ATR not required.	Thecked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
Recommendation:    Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.     Stop further work. Proceed with work after submitting ATR on QC report to QC team.     Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	MD Sign	30375	ASWER Sign	S. Sund Kungs Sign	νος ( μρ) Project	114
seed only after recheck long of the QC report to QC team.		Report filed and signed by PM?		20/0	200	
oy QC. ATR not required.	For filling	d by PM?	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	√Yes □No	04/04/18	81 40 40	)	30720

### Plinth Beam Check,

- Inspection should be done before casting of plinth beam
  Yellow conniel paint to be used for making LEL of flooring. Mark 2' alsove ELL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.
  Prepare plinth beam. Dimensions Check Plan as follows.
- Show outer dimensions (Taletaince 2")
  Show length and width of plinth beams (Taletaince 1")
- Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it. Project managers must make pedestal/column 0 self check report similar to report for column check. (X' must collect report and attach the

inth Beam Dimensions Check Plan enclosed?	Yes No
---	--------

## Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good ☐ Avg. ☐ Bad
Have rods for staircase slab been provided?	☐ Yes ☐ No
Quality of Bracing Provided?	☐ Good ☐Avg. ☐ Bad
Alignment of beams on outer side?	☐ Good [☐ Avg. ☐ Bad
Brackets for elevation features provided?	☐Yes ☐No ☑NA
Level marking at 2' above FFL is made?	☐Yes ☐No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Pedestal/column0 – self check report attached?	Yes No
Remarks: Mud should be proposly levelled inside of outsi	outside of vula.

## Plinth Beam Steel check.

### Notes:

- Mark v for correct or minor mistake which does not require correction
   Mark X for minor mistake that requires minor correction.
   Mark XX for major mistake that requires correction by replacement or re-fixing.
   Mark XXX for major mistake that cannot be corrected.
   Columns overlapping length should be 45 to 50 D.

# Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	3.	2.	1.	S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	<	<	ζ.	(		<	ζ.	Quantitative Check
	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Good Avg. Bad	☐ Good ☑ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐Good ☐ Avg. ☐ Bad	Good  Avg.  Bad	Qualitative Check (Good / Avg. / Bad)