Quality	
Control	
Control Check Repot.	
Stage: After Column Casting	
Column	
Casting	
(villas)	

Phone in the recent work. Proceed with further work. ATR not required.	Block No.		Column No		CI NI	
Phase CC LP Project CC Phase		12/	Column Ivo.	0/	SI. No.	31912
Sign Ort no. Ort no. Sign Ort no. Sign Ort no. Sign Ort no. Sign Ort no. Ort no. Sign Ort no. Ort no. Sign Ort no. Sign Ort no. Ort no. Ort no. Sign Ort no. Ort	Company	10001P	Project	<u>ح</u> مر -	Phase	
ort no. Sign Report filed and signed by PM? MD Sign MD Sign MD Sign For filling For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Prepared by	くなってのよ	Sign	くらんだけ	Date	31/10/18
ort no. 3 1346 Report filed and signed by PM? MD Sign MD Sign For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Project Manager		Sign		Date	3/10/18
MD Sign For filling rk. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required. urther work. ATR not required.	Previous stage report		31346	Report filed and signe	d by PM?	√Yes □No
ork. Submit ATR on QC report to QC team. Proceed only after recheck by Qork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR utther work. ATR not required.	Checked By MD on		MD Sign		For filling	☐Yes ☐No
	Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Submit ATR on QC rep Proceed with work after her work only after making the control of the contr	port to QC team. Proce or submitting ATR on an corrections pointed red.	ed only after recheck b QC report to QC team. out in the QC report. A	y QC. ATR not required.	

- 1. Inspection should be done after easting of columns at each stage and before starting centering works for each slab.
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolcrance 1") Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.
- Ω ^ω Circle cach correct dimension with olour-Circle each in

ah Dimensions Check	olumns Position Check Plan enclosed?	The contract dimension with green colour. Circle each incorrect dimension with red colour and mention actual
	√Yes □No	nension with red colour and mention actual dimension next to it.

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
 Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Sla Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimen

Specified thickness of slab? Actual thickness of slab?	Siad Dimensions Check Plan enclosed?	CIT TO INVALID CONTRACT TO CON
Mary Live		ICHOICH INCAL IO II.

Quality Control Check Repot. Stage: After Column Casting (villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good ✓ Avg. ☐ Bad
Quality of starters?	☐ Good ✓ Avg. ☐ Bad
Number and size of honey combs?	☐ High ☑ Medium. ☐ Low
Are the honey combs is slab and columns packed?	☐ Good ☑ Avg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	o o o o o o o o o o o o o o o o o o o
Have 6 cubes each for columns and slab casted and numbered for testing?	✓Yes ☐ No
Remarks:	
Curing.	
Bunds for curing made on slab?	
Bund size is less than 100 sft?	V
Drum (200 lts) provided for curing?	
Gunny bags used for column curing?	
Distance of tap from furthest distance that requires curing. (max permitted 100')	
Frequency of curing in number of times a day (enquire from labourers)	
Is the pressure in the curing pipe more than 15' head?	
Quality of infrastructure for curing.	Bad
Remarks: (Gurary bogs not provided for columns.	

Columns height, plumb, steel & level marking check. Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark X for major mistake that requires correction by replacement or re-fixing.
 Mark X X for major mistake that cannot be corrected.
 Tolerance: Plumb 0.25".

 Circle actual height of columns if level differs from specified height by more than

,	ĺ	•	
1	-	1	_
	ĺ		=
	١	1	?
	Į	•	יי
	ı		3
	ı		ŭ
•	Į	t	,
t	l.		1
		ļ	9
	l	-	7
	ļ	ř	-
	ŀ	č	height of column
		Ę	Ξ
	l	5	3
	l	č	ñ
_	l	;	
	l	Ċ	Ď
	l	Ì	Ď
	l	¢	ve differe tran
	l		
G	l		-
	l	-	,
	l	ζ	3
	l	1	3
	Ļ	0	3
	l	Š	į
	ı	ì	
		۶	P
	l	֡	1
		٤	Þ
	١	Ë	}
		c	1
	•		1
		ξ	3
I			•
I		֡	+
		-	
I		The second more of continuous is second discounted the second of the second sec	3 _
			,,,

20.	19.	18.	17.	16.	15.	14.	13.	12.	11.	10.	9.	.8	7.	6.	5.	4.		2.	1.			S No
									D	Ō	4	C	CI	134-	32	15,	AL	fiz	Aı		200	Col No.
									<u>C</u> 5	S	R	C5	C2	Cz	Ch	C	C	C	S			Col type
									ρ. =	1.4.78	8-11	5-1"	5.7	8-13	46.78	5.7	11.6-78	8-71	S- 21"		Spec.	Heigh
									8,21	8-5"	8-c"	8-21/2	5.7	8-2"	8-5"	5.7	8-76	8-64	14.5		Actual	Height in ft
	2							di.	۷.	۷,	٤	۷.	ζ.	۷.	4	C	۷	۷.	۷.		No of	Steel (
									j	٧	J	4	K.	۷.	۷.	۷.	ć	.	۷.,	rods	Size of	Steel (v or x)
									7	V	ζ.	r	<u>٧</u>	۷.	۷.,	۷.	V	۷.,	4			Honeycombs
									۷	٧	v		V	۷.	ć.	٧,	<i>,</i>	J.	<	,	Side 1	Plumb
					â				ζ.	<	۷,	ν.	V	< .	٧	ζ.	√ <u>`</u>	٠,	〈		Side 2	Plumb (or x)
☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	∐Yes ∐No	☐ Yes ☐ No	√Yes □No	✓ Yes ☐ No	☑ Yes □ No	√Yes □No	✓ Yes ☐ No	✓Yes □No	✓ Yes □ No	✓ Yes ☐ No	☐ Yes ☐ No	✓ Yes ☐ No	✓ Yes □ No	column?	marked on	Reference level				
							Ш		١,													