Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager Madhusudhaa	Prepared by	Company Cipost Fatales	Villa No. 138
QC report to QC team. Pork after submitting ATR armaking corrections point required.	MD Sign	33234	Sign	Sign	Project	Stage
roceed only after recheck on QC report to QC team ated out in the QC report.		Report filed and signed by PM?	No Man Date	Server 1	Nilgien Estates	
by QC. ATR not required.	For filling	d by PM?	Date	Date	Phase	Sl. No.
	Yes LNo	Z es L No	02/05/19	02/05/19		33503

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark v for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Rer	19	18	17	16	15	14	13	12	11	10	9	8	7	6	S	4	w	2	1	S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/ balcony 2	Terrace / balcony l	Lobby 2	Lobby 1	Dining	Drawing	Toilet 4	Bedroom 4	Toilet 3	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom 1	Room
						cony 2	lcony l									CT	KIS!	4	MK	
			*	Ĭ	<	1	-	\		× .	4	è]	Î	1	\$	4	ı	<	Skirting Provision (• or ×)
			4	Ś	۷,	Ĭ	-	1	ne dent	١	<		J	1	1	<	<	۷,	\ \	Finishing around door frame (• or ×)
			~	4	4	(Í	}		2	<	1	1	1	١	۷	<	۷	<	Beams & columns finishing (• or ×)
			~)	1	-	١	ì	1	٩	1	1	١	J	,	١	2	ì	1	Finishing of lofts (✓ or ×)
			٤.,	<	<		ı	ļ	-	<	<	1	١	1	١	4	_	1	<	Electrical junctions finishing (v or x)
			1	ľ	4)		I	1	1	\ \	į		ì	,	4	<	×	<	Window check (✓ or X)
			×	۱	1		}	ı	}	4	\$	1	1	-	1	4	1	÷.	, 1	Tiles provision
			<	, P	3	1	1	1)	1	٦	1	,	1	1	١)	1	Ì	Sink provision & size
			<	1	4	, 1	}	١	1	257	4]			Ł	١, ر	\<	<	Grooves for door frames (v or X)
			Ī	1	١))	1	,	1	*	1	١	1	1	1	9)	1	Balcony & terrace sill top finishing 10(v or x)
				ļ	1	1]	-	17	1	1	1	j	}	ŀ	F	j	}	,	Screeding in bathroom & utility (• or ×)
			1	1	150		J	77		Į		1	١	.	1	1	١	}	}	Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	☐ Good ☐ Avg. ☐ Bad
Plastering of compound wall & gate pillars (v or x)	\ \ \
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	⊠Yes □No
Plastering quality of parapet walls (vor X)	
Plastering and finishing of chajjas (vor X)	Avg
Remarks:	