Sl. No. So 8744 Company Company Company Company Project Company Comp	Ω	Quality Control Check Repot.		Stage: Before Casting Plinth Beam (Villas)	th Beam (Villas)	
Project Sign Nilcign: E9ta b Date Sign M. M.M. Date Corrections pointed out in the QC report. ATR not required.	Block No	141	ł		SI. No.	44802
Sign Sign Now Date Date Converged only after recheck by QC. Descriptions pointed out in the QC report. ATR not required.	Company	2000	Project	prilose sot to	Phase	700
Sign M. M.M. Date Convections pointed out in the QC report. ATR not required.	Prepared by		Sign	1. X = 1. X	Date	0 -57-0
Report filed and signed by PM? Sign For filling For filling I to QC team. Proceed only after recheck by QC. bmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR not required.	Project Manager		Sign	- CANA	Date	
Sign For filling to QC team. Proceed only after recheck by QC. bmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR not required.	Previous stage report no.	1 4 K W W W W W W W W W W W W W W W W W W	20408	Report filed and signed	by PM?	Yes No
to QC team. Proceed only after recheck by QC. Ibmitting ATR on QC report to QC team. Corrections pointed out in the QC report. ATR not required.	Checked By MD on	MD Si	gn l		For filling	
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required	Recommendation:		0		a or rimmg	
	Stop further work. Subm Stop further work. Proceed with further work Proceed with further work.	it ATR on QC report to sed with work after subnck only after making conck. ATR not required.	QC team. Proculting ATR on ections pointed	eed only after recheck b QC report to QC team. I out in the QC report. A	y QC. TR not required.	

Notes: Plinth Beam Check.

Inspection should be done before casting of plinth beam.
Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam Dimensions Check Plan as follows:

Print an A3 size plan.

Show outer dimensions. (Tolerance 2")
Show length and width of plinth beams (Tolerance 1")

Plinth Beam Dimensions Check Plan enclosed? Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Yes

Zo

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Plinth Beam Steel check.

Notes:

- Mark V for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	3.	2.		S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
		4	<	4	_	~	~J.	Quantitative Check (• or ×)
	☐ Good Navg. ☐ Bad	Good ∐ Avg. ∐ Bad	☐ Good NAvg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	✓ Good ☐ Avg. ☐ Bad	☑ Good ☐ Avg. ☐ Bad	□ Good □ Avg. □ Bad	Qualitative Check (Good / Avg. / Bad)