Quality Control Check Repot. Stage: After Plastering (Villas)

Villa No.	162	Stage		Sl. No.	33044
Company	Nilconi F States	Project	Nilaini Estates	Phase	Ħ
Prepared by		Sign	*SKAN	Date	.01/03/19
Project Manager	rung.	Sign	Com	Date	01/03/19
Previous stage report no	no.	32435	Report filed and signed by PM?	ed by PM?	Yes No
Checked By MD on	,	MD Sign		For filling	Yes No
Recommendation: Stop further work. Stop further work. Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointedired.	ced only after recheck! QC report to QC team! I out in the QC report.	by QC. ATR not required.	 .s

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2 "grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	S No
Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/ balcony 2	Terrace / balcony 1	Lobby 2	Lobby 1	Dining	Drawing	Foilet 4	Bedroom 4	Toilet3	Bedroom-3		Bedroom 2 以·药		Bedroom 1 M.R	Room
			×	1	4	1	}		1	<	4	7		1				*	۷.	Skirting Provision (v or x)
			1	1	4	1	1	١	١		4	•	ı	١	1	4	<	<	۷,	Finishing around door frame (v or x)
			۷,	<	4	1	1	1	1	4	۷	1	1	1	Ş	۷,	4	<	۲	Beams & columns finishing (v or x)
			4	١	١	1	Ī	}	1	7		i	١	1	,	1		*	1	Finishing of lofts (• or ×)
			2	<	4	1	1	١	1	4	<	1	١	١	١	<	<	<	۷	Electrical junctions finishing (v or x)
			<		*	1)	1	٩	٦	4	١	1	١	1	۷.	<	4	~	Window check (v or x)
			×	١	١	1	ì	1	١	١	1	١	3	1	1	1	650	4	4	Tiles provision (v or x)
			4	١	1	1	1	,	1	ì	1	1	1	١		1	٦	7	1	Sink provision & size
			١	٩	×	1	1	1	.1	1	٠,	١	1	1	1	C	Ç.	۷,	د	Grooves for door frames (v or x)
			1	1	١	Î	İ	,	9	1	1	١	1	١	١	1	١		}	Balcony & terrace sill top finishing 10 (or x)
_			}	٦	١	1	ı	1	1	١	1	}		1	1	9	١	1	1	Screeding in bathroom & utility (v or ×)
			1	-)	-	1	,	1	1	1	1	1	1	1		1	١	1	Screeding in 6" above FFL? (or x)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	☐ Good ✓ Avg. ☐ Bad
Plastering of compound wall & gate pillars (v or x).	
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Plastering quality of parapet walls (\checkmark or \times)	*
Plastering and finishing of chajjas (v or x)	
Remarks: per leveling not done in laws area.	